

**Capital Efficiency Plan™
Aquarion Water Company
Hingham/Hull Water System**

Prepared by:



March 2011



March 31, 2011

Mr. Robert Roland
Director of Operations
Aquarion Water Company
900 Main Street
Hingham, MA 02043

Subject: Capital Efficiency Plan™
T&H Project No. 2061

Dear Mr. Roland:

In accordance with our agreement, Tata & Howard is pleased to present you with the Capital Efficiency Plan™ for the Hingham/Hull Water System. The analysis and improvements in this report are based on the Three Circle Approach for capital efficiency, which combines hydraulic and critical component considerations with an asset management rating system to evaluate the condition of the water mains in the distribution system.

In the 2007 Water Supply and Distribution System Study, Tata & Howard used a hydraulic model to evaluate the Hingham/Hull water distribution system. Hydraulic recommendations were developed as part of this study and included in the Capital Efficiency Plan™. Additionally, the model was updated to include improvements to the system since 2007. The system was surveyed for critical areas and tested on the hydraulic model for redundancy. Finally, each water main was evaluated based on age, material, diameter, break history, water quality and soil conditions to determine its asset management score. The results were combined to determine the water mains most in need of replacement and establish a prioritized set of improvements in the system. A detailed description of the improvements and their estimated costs is presented in Section 7.

During the course of this project, Ms. Karen Gracey, P.E. served as Project Manager, Ms. Justine Evans, P.E. served as Project Engineer, Ms. Victoria Zabierek served as Engineer, and the undersigned provided technical reviews and served as Project Officer.

Mr. Robert Roland
Aquarion Water Company

March 31, 2011
Page 2

At this time, we wish to express our appreciation to the Aquarion Water Company for their participation in this study and for their help in collecting information and data. We also appreciate the opportunity to assist the Aquarion Water Company on this important project.

Sincerely,

TATA & HOWARD, INC.



Donald J. Tata, P.E.
President

Enclosures

TABLE OF CONTENTS

Letter of Transmittal

Section	Description	Page
1	Executive Summary	1
	1.1 General	1
	1.2 The Three Circle Approach	
2	Existing Water Distribution System	
	2.1 Distribution System	3
	2.2 Water Supply Sources	3
	2.3 Hull Booster Pump Station	7
	2.4 Water Storage Facilities	7
	2.5 Hingham/Hull District Water Treatment Facility	7
2.6 Previous System Studies	7	
3	Water Supply and Storage Evaluation	
	3.1 General	9
	3.2 Adequacy of Existing Water Supply Sources	9
	3.3 Adequacy of Existing Water Storage Facilities	13
4	Hydraulics	
	4.1 General	15
	4.2 Evaluation Criteria	15
	4.3 Hydraulically Deficient Areas	16
5	Critical Components Assessment	
	5.1 General	20
	5.2 Evaluation Criteria	20
	5.3 Critical Components	20
6	Asset Management	
	6.1 General	22
	6.2 Data Collection	22
	6.3 Evaluation Criteria	22
	6.4 Asset Management Areas of Concern	33
7	Capital Efficiency Recommendations	
	7.1 General	37
	7.2 General Recommendations	37
	7.3 Prioritization of Improvements	38

TABLE OF CONTENTS (continued)

LIST OF TABLES

Table	Description	Page
3-1	Estimated Yield of Existing Sources	10
5-1	Critical Service Areas	21
6-1	Asset Management Grading System	24
6-2	Pipe Material by Installation Year	25
6-3	Bleeder Inventory	35
6-4	Known Broken Valve Inventory	36
7-1	Prioritization of Improvements – Phase I	50
7-2	Estimated Improvement Costs – Phase I	51
7-3	Prioritization of Improvements – Phase II	52
7-4	Estimated Improvement Costs – Phase II	54
7-5	Prioritization of Improvements – Phase III	56
7-6	Estimated Improvement Costs – Phase III	58
7-7	Prioritization of Improvements and Estimated Improvement Costs – Phase III – Priority 3	60

TABLE OF CONTENTS (continued)

LIST OF FIGURES

Figure	Description	Page
2-1	Water Main Size Distribution	4
2-2	Water Main Material Distribution	5
6-1	Water Main Installation Years	27
6-2	Water Main Materials	28
6-3	Water Main Diameters	30
6-4	Areas with History of Breaks	31
6-5	Areas with Water Quality Concerns	32
6-6	Potentially Corrosive Soils	34

LIST OF APPENDICES

Appendix	Description
A	Water Distribution System Map
B	Input Data and Link Map
C	Hydraulically Deficient Areas Map
D	Critical Components Map
E	Asset Management Rating Map
F	Three Circle Integration Map
G	Phase I & II Improvements Map
	Phase III Improvements Map

SECTION 1 – Executive Summary

1.1 General

Tata & Howard, Inc. was retained by the Aquarion Water Company (Aquarion) to complete a Capital Efficiency Plan™ for the Hingham/Hull water system. The purpose of the plan is to identify areas of the water distribution system in need of rehabilitation, repair or replacement and prioritize improvements to make the most efficient use of the System's capital budget. In addition, water supply and storage needs are evaluated and prioritized. The conditions of the systems above ground facilities, including water supply and chemical feed facilities and water storage tanks, were not evaluated as part of this study.

1.2 The Three Circle Approach

The Capital Efficiency Plan™ evaluated the water distribution system using the Three Circle Approach. The Three Circle Approach includes the following evaluation criteria:

- System hydraulic evaluation,
- Critical component assessment,
- Asset management considerations.

Each circle represents a unique set of evaluation criteria for each water system component. From each set of criteria, system deficiencies are identified. System deficiencies from each circle are then compared. Any deficiency that falls into more than one circle is given higher priority than one that does not. Using the Three Circle Approach, recommended improvements are identified that will result in the most benefit to the system. In addition, the Three Circle Approach allows us to identify any situations where an improvement of a deficiency in one circle will eliminate a deficiency in another circle. By integrating all three sets of criteria, the infrastructure improvement decision making process and overall capital efficiency is optimized.

Tasks in this study included the following:

- Using data presented in the Water Supply and Distribution System Study, include an evaluation of water supply and storage needs based upon existing and future demands and fire flow requirements.
- Conduct a one day workshop with the operations and management staff to review operations and maintenance practices, break history and other pertinent information.
- Review previously completed reports and available data pertaining to the condition of the existing system.
- Incorporate applicable pipe information into the hydraulic model.
- Review recommended hydraulic improvements from the Water Supply and Distribution System Study, as well as potential improvements resulting from asset management and critical component considerations.

- Create a pipe rating system to identify areas needing rehabilitation or replacement. Use the rating system to create a prioritized plan of recommended improvements. The study will consider buried infrastructure only.

Based on the Three Circle Approach, a prioritized list of improvements was compiled. Improvements were separated into three phases. Phase I represents the most needed improvements based on hydraulic needs, location in the distribution system and the condition of the water main. In general, these include water mains that fall into two or three of the three circles strengthening the transmission grid, eliminating potential asset management concerns, and/or providing redundancy.

Phase I improvements include replacement of water mains on Pleasant Street and Liberty Pole Road in Hingham, and Atlantic Avenue, Summit Avenue, Edgewater Road, and the north end of Beach Avenue in Hull.

Phase II improvements generally include areas that fall into two circles, but are located on side streets or dead ends, as well as areas that are hydraulically deficient or have high asset management ratings. These improvements generally will benefit a localized area, while Phase I improvements benefit the transmission grid. Phase III improvements include water mains that are a concern due to either hydraulic deficiencies or asset management concerns only.

SECTION 2 – Existing Water System

2.1 Distribution System

Aquarion Water Company's Hingham/Hull distribution system consists of approximately 186 miles of water mains ranging in diameter from two to twenty inches. Figure No. 2-1 shows a breakdown of the water main size distribution of the existing water system. Approximately six percent of the system is 14-inch diameter or larger pipe, approximately 15 percent is 10 or 12-inch diameter pipe, approximately 38 percent of the system is 8-inch diameter pipe, approximately 31 percent is 6-inch diameter pipe, and approximately 10 percent is 4-inch diameter or smaller pipe. These mains are constructed of various materials including cement lined ductile iron (CLDI), cast iron (CI), galvanized steel, precast concrete, and asbestos cement (AC). Figure No. 2-2 shows the breakdown of material distribution of the existing water system. The existing system has seven active supply sources, one emergency supply source (Free Street Well No. 2), two water storage facilities and a water treatment facility. A map of the existing water distribution system is included in Appendix A.

The water distribution system is divided into two service areas. The main service area consists of the Town of Hingham, north of the water treatment facility, the Town of Hull and a portion of North Cohasset. The high service area includes the southern portion of Hingham. The distribution system services elevations range from approximately 0 to 131 feet above mean sea level (MSL) in the main service area and approximately 49 to 180 feet above MSL in the high service area. The Hingham/Hull District Water Treatment Facility provides water to both service areas.

2.2 Water Supply Sources

The Hingham/Hull water system includes seven water supply sources and one emergency source. The supply system is comprised of six groundwater sources and one surface water source. The Accord Pond is the sole surface water source within the system and Free Street Well Nos. 2A, 4, 3/5, Downing Street Well, Prospect Street Well, Scotland Street Well and Fulling Mill Station are groundwater supply sources. Free Street Well No. 2 is currently listed as an emergency supply source.

Downing Street Well

Downing Street Well is a gravel packed well located off Downing Street (Lat 42° 13' 25", Long 70° 52' 50"). It was constructed in 1965 to a depth of approximately 66.5 feet. The well was cleaned and rehabilitated in March 2002. The Massachusetts Department of Environmental Protection (MassDEP) approved pumping rate for this well is 284 gallons per minute (gpm) or 0.41 million gallons per day (mgd). The Downing Street

Figure No. 2-1
Water Main Diameter Distribution





Figure No. 2-2
Water Main Material Distribution



Well is the only supply source that pumps directly into the finished water system. All other sources are treated at the Hingham/Hull District Water Treatment Facility.

Free Street Well Nos. 2, 2A and 4

Free Street Well No. 2 is a gravel packed well located off Free Street (Lat 42° 13' 05", Long 70° 52' 40"). It was constructed in 1952 to a depth of approximately 73 feet. The well was cleaned and rehabilitated in March 2002. Free Street Well No. 2A is a replacement well that was installed in 2007 to a depth of approximately 79.5 feet. Free Street Well No. 4 is a gravel packed well located off Free Street (Lat 42° 13' 10", Long 70° 52' 45"). It was constructed in 1983 to a depth of approximately 86 feet. In November 2008, the MassDEP approved a status change of Free Street Well No. 2 and 4. Free Street Well No. 2 was changed from an active source to an emergency source while Free Street Well No. 4 was changed to an active source. MassDEP has limited the total maximum daily withdrawal from Free Street Well No. 4 to 0.81 mgd. The total combined volume to be withdrawn from Free Street Well No. 2 and 4 cannot exceed 1.80 mgd.

Free Street Well No. 3/5

Free Street Well No. 3/5 are gravel packed wells located off Free Street (Lat 42° 13' 05", Long 70° 52' 52"). Free Street Well No. 3 was constructed in 1967 to a depth of approximately 88.5 feet. Free Street Well No. 5 was constructed as a satellite well to supplement lost capacity of Free Street Well No. 3. The satellite well pumps to Well No. 3 and is then pumped to the system. The wells were cleaned and rehabilitated in 1998. The MassDEP approved pumping rate for these wells is 351 gpm or 0.51 mgd.

Prospect Street Well

The Prospect Street Well is a gravel packed well located off Elaine Road (Lat 42° 11' 30", Long 70° 52' 30"). It was constructed in 1971 to a depth of approximately 58 feet. The MassDEP approved pumping rate for this well is 269 gpm or 0.39 mgd.

Scotland Street Wells

The Scotland Street Well is a gravel packed well located off Scotland Street (Lat 42° 11' 25", Long 70° 52' 20"). It was constructed in 1956 to a depth of approximately 45 feet. A replacement well was installed in 2008 to a depth of 57 feet. The original well was cleaned and rehabilitated in March 2002. The MassDEP approved pumping rate for this well site is 1,078 gpm or 1.55 mgd.

Fulling Mill Station

The original Fulling Mill Station is a dug well fed by infiltration basins located at 93 South Pleasant Street (Lat 42° 12' 10", Long 70° 52' 30"). It was constructed in 1903 to a depth of approximately 21.5 feet. Two replacement wells were installed at the Fulling Mill Well site in 2008. The Fulling Mill Replacement Wells No. 1 and 2 have a capacity

of 430 gpm and 265 gpm, respectively. The MassDEP approved pumping rate for this well site is 941 gpm or 1.36 mgd.

Accord Pond

Accord Pond is 100 acre pond located off Whiting Street (Lat 42° 10' 30", Long 70° 53' 30"). The total storage capacity of the pond is approximately 523 million gallons with a drainage basin area of 1.01 square miles. The intake pipe is a gravity feed line to the treatment plant. The estimated safe yield of the pond is approximately 0.69 mgd.

2.3 Hull Booster Pump Station

The Hull Booster Pump Station services the northern portion of Hull. The booster pump station provides domestic pressure only when high demands in Hull reduce pressures in the area.

2.4 Water Storage Facilities

There are two water storage facilities located within the Hingham/Hull system. The Turkey Hill Tank is located on Turkey Hill Lane in Hingham. The welded steel standpipe is 70 feet in diameter, 70 feet tall and has a reported capacity of 2.01 million gallons (mg). It has an overflow elevation of 240 feet and is connected to the system with a 20-inch diameter water main. The Accord Tank is located on Whiting Street in Hingham. The elevated welded steel tank is 58 feet in diameter, 112 feet tall and has a reported capacity of 0.75 mg. Accord Tank has an overflow elevation of 282 feet and is connected to the system through a 16-inch diameter water main.

2.5 Hingham/Hull District Water Treatment Facility

Aquarion operates a 7.7 mgd water treatment facility located in Hingham. The treatment facility, in operation since April 1996, receives water from all water supply sources except the Downing Street Well and satisfies the treatment requirements set forth by the United States Environmental Protection Agency (US EPA). The Hingham/Hull District Water Treatment Facility treats raw water via rapid mix, Superpulsator clarifiers, deep-bed GAC filters and post-filtration disinfection, pH adjustment and fluoridation. The facility also has a large holding tank for treated water to improve water pressure in the system during high demand periods.

2.6 Previous System Studies

A Water Supply and Distribution System Study was completed by Tata & Howard in 2007. The System Study provided recommended storage, supply and distribution system improvements to meet the existing and future needs of the system. Using the hydraulic model, capital improvements were evaluated and prioritized. Distribution system

improvements were primarily recommended based on the hydraulic characteristics of the system to eliminate hydraulic restrictions and fire flow deficiencies.

SECTION 3 – Water Supply and Storage Evaluation

3.1 General

In accordance with MassDEP, the supply sources of a water system must be capable of meeting existing and projected maximum day demand (MDD) conditions and existing and projected summer average day demand (SADD) conditions with the largest source out of service. In this section, safe yields of the supplies and permitted withdrawals of the existing supply sources were compared to current and future demand conditions.

3.2 Adequacy of Existing Water Supply Sources

In 1987, the Water Management Act (WMA) program was implemented by MassDEP to regulate withdrawal of water from the state's watershed basins. Under this program, all new and existing sources withdrawing more than 100,000 gallons per day (gpd) are required to obtain a withdrawal permit under the WMA. When first implemented, the registered withdrawal volume for a public water system was based on that system's historical pumping rate of the water supply source(s) between 1981 and 1985. However, permits can be renewed and amended as system demands increase and additional supply sources are utilized. The WMA program considers the need for the withdrawal, the impact of the withdrawal on other hydraulically connected water suppliers, the environmental impacts of the withdrawal and the water available in the river basin or subbasin (the basin safe yield) prior to issuing a permit. It is important to note that the basin safe yield is different from the safe yield of a supply. In accordance with the WMA permit application instructions, the basin safe yield is the total water available to be withdrawn from a river basin or subbasin, whereas the safe yield of a well is the volume of water the well is capable of pumping under the most severe pumping and recharge conditions that can be realistically anticipated.

The current Hingham/Hull system is comprised of seven supply sources and one emergency source. Table No. 3-1 provides the current withdrawal rates from each well and a summary of the MassDEP approved withdrawal rates for each of Aquarion's supply sources presented in Section 2. The total allowable withdrawal rate from existing sources is approximately 6.71 mgd without the emergency source Free Street Well No. 2. The ADD and MDD in 2009 were 3.13 mgd and 4.95 mgd, respectively. The projected ADD and MDD for the year 2025 are 4.12 mgd and 7.25 mgd, respectively.

MassDEP guidelines recommend that a system have adequate supply to meet (1) the projected MDD and (2) the projected SADD with the largest source offline. The current SADD is estimated by averaging the three maximum demand months for the past five years. The SADD peaking factor is determined by dividing the SADD by the average ADD for each of the past five years. These peaking factors are averaged to estimate the future summer peaking factor. Based on 2005 through 2009 monthly demand data, the summer peaking factor is 1.30. Based on a projected ADD of 4.12 mgd, the estimated future SADD is 5.36 mgd.

Table No. 3-1 Estimated Yield of Existing Sources		
Source Name	Current Estimated Yield (mgd)	MassDEP Approved Withdrawal Rate (mgd)
Downing Street	0.32	0.41
Free Street No. 2A and 4*	1.80	1.80
Free Street No. 3/5	0.37	0.51
Fulling Mill Station	1.36	1.36
Prospect Street Well	0.24	0.39
Scotland Street Well	1.55	1.55
Accord Pond	0.69	0.69
Total	6.33	6.71

*Free Street No. 4 has a maximum withdrawal rate of 0.81 mgd. The total combined withdrawal rate from Free Street No. 2A and 4 is 1.80 mgd.

The system's total combined yield of the active supply sources is approximately 6.33 mgd. Compared to the projected MDD in 2025, a deficit of 0.92 mgd is estimated. The total combined allowable withdrawal volume from Free Street Wells No 2A and 4 is 1.80 mgd. However, MassDEP has limited the maximum withdrawal volume from Free Street Well No. 4 to 0.81 mgd, while Free Street No. 2A is allowed to pump up to 1.80 mgd. Therefore, Free Street Well No. 2A is the largest source based on sustainable yield; therefore the available pumping rate while the largest source is off-line is 5.34 mgd including 0.81 mgd from Free Street No. 4. Compared to the projected SADD, a deficit of 0.02 mgd is estimated.

In order to eliminate this predicted deficit, the 2007 Water Supply and Distribution System Study recommended a phased approach to maximize production of existing supply sources and augment the current supply with new sources or water purchase. The first and second phases, to maximize production at several wells to satisfy current demands and improve source management, have been completed. The third phase will augment the current supply through potential new source development and water purchase.

Phase I

Several higher capacity supply wells within the system had experienced a gradual reduction in pumping capacity over the years. In an effort to restore capacity to these wells, Aquarion recently installed replacement wells at the Scotland Street Well, Free Street Well No. 2, and the Fulling Mill Well Site. As a result, each well site capacity was restored to the MassDEP approved withdrawal rate. Therefore, the current total available yield was increased to 6.33 mgd.

Phase II

Following the maximization of existing sources, additional supply must be obtained to satisfy the projected demands in 2025. Phase II consisted of exchanging production between Free Street No. 2 and Free Street No. 4.

Free Street No. 4 had an approved safe yield of 0.81 mgd for emergency production only. Historical records indicate better water quality at Free Street No. 4 than Free Street No. 2. This may be due to Free Street No. 4 being constructed to a greater depth than Free Street No. 2. Aquarion has invested considerable time and money into permitting Free Street No. 4 as a permanent source and increasing the available yield to 1.3 mgd. However, increases in yield are uncertain primarily due to environmental concerns for the Weir River and the limitations of the Interbasin Transfer Act. Based on this information, Aquarion was approved to utilize Free Street No. 4 and the new Free Street No. 2A as the permanent sources and make the existing Free Street No. 2 an emergency source. This approach did not increase the withdrawal rate from the sub-basin, only changes the point of withdrawal to Free Street No. 4 and 2A, rather than Free Street No. 2 and 2A.

Phase III

Phase III incorporates longer term alternatives to supplement current system capacity. The following alternatives include the development of a new source and water purchase from adjacent and nearby water wholesale sellers. Each water purchase alternative would require an agreement between the Aquarion Water Company and another utility or private entity to meet the projected system demands. Further, new infrastructure and potentially water treatment would be required to transport and treat purchased water to the Hingham-Hull system.

New Source Development

In accordance with MassDEP guidelines, the development of a new source consists of four stages. The exploratory stage is for review of existing available information, evaluation of potential sites and installation of test wells. The second stage includes preparation and submittal of the request for site exam, alternatives analysis, land use survey and pumping test proposal. After approval by the MassDEP, the third stage is to complete a minimum five-day pump test and accompanying pump test report to be submitted to the MassDEP for review. The final stage consists of the design of the pump station and associated water main from the source well to the system. A Water Management Act permit is required when the total withdrawal volume is greater than 100,000 gpd. In addition, all new sources will require the completion of an Environmental Notification Form (ENF) to be submitted to the Massachusetts Environmental Policy Act Office for review and public comment.

Permitting for new source development is a time consuming and costly process depending on the location and potential impact on the environment. In addition, the process does not guarantee that sufficient yield and quality will be found or that Aquarion can obtain ownership of the Zone I radius. In general, the permitting and development

process could take up to five years to complete. In addition, water treatment may be required, which will increase the time and cost of the project.

The United States Geological Survey (USGS) potential aquifer yield potential maps were reviewed to identify potential well site locations within town boundaries. The areas of reasonable yield currently host one or more active supply wells. Additional gravel packed wells in these subbasins could strain these areas. Therefore, a fracture trace analysis was conducted to identify potential bedrock well locations. This type of well would withdraw water from a deeper aquifer, not immediately connected to the shallower aquifer supplying current gravel packed wells. A new bedrock supply well is permitted in the same manner as sand and gravel sources, and is constrained by the results of pump testing and MassDEP approval.

Several sites were identified during the fracture trace analysis as potential supply well locations, however, a pumping test would be required to determine the yield. The sites are located within the South Coastal Basin and the property is owned by the Massachusetts Department of Conservation and Recreation (DCR). Obtaining access to these areas may prove extremely difficult as DCR does not favor development on agency owned land. Additional evaluation will be conducted on potential sand and gravel sources and bedrock wells at existing well sites as well as appropriate locations within the service area.

Interconnection to Cohasset

All current supply sources should be maximized and potential sites investigated prior to seeking water sources across town boundaries. The Town of Cohasset currently operates and maintains the Aaron Reservoir as a water supply source. Currently, system demands only require the Town to utilize a portion of the permitted withdrawal rate. In addition, preliminary estimates indicate that a surplus of approximately 1.0 mgd may exist through 2025 based on projected demands in Cohasset. The current cost for purchasing water is approximately \$4.50 per 1,000 gallons for finished water. The Aquarion Water Company currently wheels up to 0.3 mgd of finished water from Cohasset to the Linden Pond development. Additional finished water may be available through this connection with the completion of a Water Management Act Permit and infrastructure upgrades. Additional analysis on the estimated cost for purchasing finished water from Cohasset is needed.

Although it may be cost effective at current prices, from an operation and maintenance standpoint for Aquarion to purchase raw water and treat it at the existing Hingham/Hull District Water Treatment Facility, the capital costs associated with constructing approximately four miles of raw water main from Aaron Reservoir to the treatment facility would be considerable.

MWRA Connection

The MWRA currently provides wholesale water to approximately 50 communities throughout Massachusetts. The closest area for Aquarion to connect to the MWRA

system is the City of Quincy, Massachusetts. This would require the construction of approximately two miles of water main along Route 3A and a new pump station. Reportedly, the current cost for MWRA is approximately \$3,400 per 1.0 million gallons with a \$5,500,000 participation fee.

Desalination Facility

Currently, the Town of Hull is conducting a feasibility study regarding the construction and operation of a desalination plant. This improvement would reduce the demands on Aquarion system and offer a potential long-term option for supplement supply. However, this option is still in the planning and discussion phase. The estimated cost for this improvement is on the order of \$20,000,000 for a plant with a capacity of approximately 2.5 mgd.

A desalination plant has been constructed by Aquaria Corporation and Bluestone Energy Services in the Town of Dighton, Massachusetts, to satisfy water demands in Brockton, Massachusetts. In order for Aquarion to obtain water from this plant, approximately one mile of new 20-inch diameter water main would need to be constructed from Dighton to Brockton. Brockton would then transmit the water through existing infrastructure to Hingham and charge a wheeling fee to Aquarion. Based on information presented in previous reports, the minimum contract amount for purchasing water from Dighton would be \$176,000 per year per 100,000 gallons and the current water charge of approximately \$1.23 per 1,000 gallons will be assessed in addition to the annual fee.

3.3 Adequacy of Existing Water Storage Facilities

Distribution storage is provided to meet peak consumer demands such as peak hour demands and additionally, to provide a reserve for fire fighting. Storage may also serve to provide an emergency supply in case of temporary breakdown of pumping facilities, or for pressure regulating during periods of fluctuating demand.

There are three components that must be considered when evaluating storage requirements. These components include equalization, fire flow requirements, and emergency storage.

Equalization storage provides water from the tanks during peak hourly demands in the system. Typically, this quantity is a percentage of the maximum day demands. The percentages can range from fifteen to twenty-five percent, with fifteen percent used for a large system, twenty percent for a medium sized system and twenty five percent used for a small system. A system is considered small if it has less than 3,300 customers, while a system is considered large if it has more than 50,000 customers. The Hingham/Hull system would be considered a medium system. As a result, twenty percent of maximum day demand was used for the equalization storage calculations.

1. Equalization
 - Medium sized system = 20 percent of the Maximum Day Demand
 - Maximum Day Demand in year 2008 = 5.98 mgd

- Estimated Maximum Day Demand in year 2025 = 7.25 mgd
- Equalization (2009) = $0.20 \times 4.95 = 0.99$ mg
- Equalization (2025) = $0.20 \times 7.25 = 1.45$ mg

The fire flow storage component is based on the basic fire flow requirement multiplied by the required duration of the flow. This basic fire flow is defined as a fire flow indicative of the quantities needed for handling fires in important districts, and usually serves to mitigate some of the higher specific fire flows. Within the Hingham/Hull system, a basic fire flow of 2,000 gpm for a duration of two hours was used for the storage evaluation.

2. Basic Fire Flow Requirement
 - Representative fire flow = 2,000 gpm
 - Duration of 2 hours or 120 minutes
- Basic Fire Flow Requirement = $2,000 \times 120 = 0.24$ mg

The emergency storage component is typically equivalent to one ADD. However, if there is emergency power available at the source(s) and the supply is sufficient to meet the ADD or there are emergency connections with surrounding communities, the emergency storage component can be waived. Therefore, the emergency storage component was not included in the storage capacity calculations.

3. Emergency - Waived

The total required storage for any given year is the equalization component plus the basic fire flow requirement. Therefore, the current (year 2004) and projected (year 2025) total required storage is as follows:

- Total Required Storage (2009) = $0.99 + 0.24 = 1.23$ mg.
- Total Required Storage (2025) = $1.45 + 0.24 = 1.69$ mg.

Under existing and projected ADD, MDD and peak hour demands, a minimum pressure of 20 psi should be maintained throughout the distribution system. In the Hingham/Hull system, the highest customer is at an elevation of approximately 131 feet in the main service area and 180 feet in the high service area, and in order to maintain a pressure of 20 pounds per square inch (psi) at these elevations, the tank levels can drop to approximately 177 feet and 226 feet, respectively. Based on this scenario, the entire Accord Tank (0.75 mg), at a base elevation of 244 feet, is usable. However, the Turkey Hill (2.0 mg) has a base elevation of 170 feet. Therefore, in order to maintain 20 psi throughout the system the Turkey Hill Tank level cannot drop below 63 feet. This reduces the usable storage in the Turkey Hill Tank to 1.81 mg.

The total usable storage in the Hingham/Hull water distribution system is approximately 2.56 mg. The projected required storage for the design year is approximately 1.69 mg. Therefore, the system has approximately 0.87 mg of surplus storage.

SECTION 4 – Hydraulic Evaluation

4.1 General

In the 2007 Water Supply and Distribution System Study, Tata & Howard, Inc. used a hydraulic model to evaluate the Hingham/Hull water distribution system and as a basis for recommending water distribution system improvements. At the time of the study, a hydraulic computer model was created using WaterGEMS modeling software, allowing the user to conduct hydraulic simulations. The computer model is represented by the node, pipe and tank information provided in Appendix B. A color-coded junction map of the water distribution system model can be found in Appendix B. The node map provides information on storage facilities, water supply sources, sizes of water mains, and a general layout of the distribution system. The hydraulic input data in Appendix B provides data on system demands, length and diameter of water mains, roughness coefficient or “c-value” of water mains, elevations, pumping rates of water supply sources, and overflow elevations at storage facilities

As part of the system study, the hydraulic model was verified based on fire flow testing and information pertaining to the sources and storage facilities. Verification of the computer model was completed under steady state conditions. It should be noted that verification of the model for extended period simulations was outside the scope of this study. Once the model was verified, recommendations set forth by the Insurance Services Office (ISO) for water storage necessary for fire protection, fire flows, and peak demands were utilized in the analysis of the distribution system under steady state conditions. As part of this Capital Efficiency Plan™, the model was updated to include improvements to the system since 2007.

4.2 Evaluation Criteria

The Hydraulic Evaluation facet of the Three Circle Approach evaluates the system’s ability to meet varying demand conditions. In general, a minimum pressure of 35 pounds per square inch (psi) at ground level is required during average day, maximum day, and peak hour demand conditions. During MDD with a coincident fire flow, a minimum pressure of 20 psi is required at ground level throughout the system. In order to evaluate the system’s ability to meet these criteria, the following hydraulic simulations were run in the model:

Insurance Services Office (ISO) Fire Flow Recommendations

The recommended fire flow in any community is established by the ISO. The ISO determines a theoretical flow rate recommended to combat a major fire at a specific location; taking into account the building structure, floor area, the building contents, and the availability of fire suppression systems. In general, the flows recommended for proper fire protection are based on maintaining a residual pressure of 20 psi. This residual pressure is considered necessary to maintain a positive pressure in the system to allow continued service to the customers and avoid negative pressures that could introduce groundwater into the system.

The estimated recommended fire flows, as determined by the ISO, were simulated on the computer model. Areas where the available fire flow did not meet the ISO recommended fire flow were considered hydraulically deficient. As part of the Water Distribution System Study, recommended improvements were developed to alleviate these deficiencies.

Additional Fire Flows Requirements

According to American Water Works Association (AWWA), the minimum recommended fire flow in residential areas where homes are between 31 feet and 100 feet apart is approximately 750 gpm. Based on the 2007 study, certain areas of the system could not meet the minimum recommended fire flow. The recommended improvements to achieve 750 gpm in these areas are also included as hydraulic improvements in the Capital Efficiency Plan™.

4.3 Hydraulically Deficient Areas

In general, the recommendations presented in the 2007 study were broken down into three components. The first presented general recommendations that could be completed on an as-needed basis. The second and third components were the Priority I and II recommendations for system improvements relative to the water supply and distribution system. Priority I Hydraulic Improvements were intended to meet water supply needs and mitigate ISO fire flow deficiencies. Priority II Hydraulic Improvements identified improvements required at or near system extremities for fire flow deficiencies, as well as system looping in certain areas. A map of the recommended hydraulic improvements is included in Appendix C.

The following list provides a summary of the Priority I and II Hydraulic Improvements that will need to be completed. It should be noted that this Capital Efficiency Plan™ focused only on buried infrastructure. Therefore, previous recommendations for storage, supply and pump stations were not included. General recommendations are discussed in Section 7 of this study.

Priority I Hydraulic Improvements

1. In order to provide a nominal capacity of 2,000 gpm at the end of Nantasket Avenue in Hull, it is recommended that the existing Hull Booster Pump Station be upgraded to include fire pumps. The fire pumps would provide additional fire flow to all services north of the pump station.
2. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Beach Avenue in Hull be replaced with 12-inch diameter cement lined ductile iron water main. The proposed water main will be installed along an existing utility easement adjacent to Beach Avenue.
3. In order to provide the ISO recommended fire flow of 3,500 gpm on Beal Street in Hingham, it is recommended that the existing 8-inch diameter water main that runs

along Beal Street be replaced with 12-inch diameter cement lined ductile iron water main.

4. In order to provide the ISO recommended fire flow of 3,000 gpm on Atlantic Avenue in Hull, it is recommended that the existing 6-inch diameter water main that runs along Atlantic Avenue from Gunrock Avenue to Jerusalem Road should be replaced with 12-inch diameter cement lined ductile iron water main. This improvement accounts for the approximately 1,200 linear feet of 12-inch water main being installed on Atlantic Avenue between Stony Beach Road and Gunrock Avenue in the spring 2011. Additionally, the existing 6-inch diameter water main that runs along Summit Avenue should be replaced with 8-inch diameter cement lined ductile iron water main.
5. In order to provide the ISO recommended fire flow of 3,000 gpm on Keith Way in Hingham, it is recommended that the existing 8-inch diameter water main that runs along Recreation Park Drive from Derby Street to Keith Way and along Keith Way be replaced with 16-inch diameter cement lined ductile iron water main.
6. In order to provide the ISO recommended fire flow of 3,500 gpm on George Washington Boulevard in Hingham, it is recommended that the existing 8-inch diameter water main that runs along George Washington Boulevard be replaced with 12-inch diameter cement lined ductile iron water main.
7. In order to provide the ISO recommended fire flow of 3,000 gpm on East Gate Lane in Hingham, it is recommended that the existing 8-inch diameter water main that runs along East Gate Lane be replaced with 12-inch diameter cement lined ductile iron water main.
8. In order to provide the ISO recommended fire flow of 3,000 gpm on Pleasant Street in Hingham, it is recommended that the existing 6-inch diameter water main that runs along Pleasant Street from Main Street to Middle Street be replaced with 8-inch diameter cement lined ductile iron water main.
9. In order to provide the ISO recommended fire flow of 3,000 gpm on Rockway Avenue in Hull, it is recommended that the existing 6-inch diameter water main that runs along Rockway Avenue from Wyola Road to Rock View Road be replaced with 8-inch diameter cement lined ductile iron water main. Additionally, the existing 6-inch diameter water mains that run along Wyola Road from Rock View Road to Logan Avenue and Delawanda Road from Rock View Road to Logan Avenue should be replaced with 8-inch diameter cement lined ductile iron water main.
10. In order to provide the ISO recommended fire flow of 3,000 gpm on Downer Avenue in Hingham, it is recommended that the existing 8-inch diameter water main that runs along Downer Avenue from Otis Street to Planters Field Lane be replaced with 12-inch diameter cement lined ductile iron water main.

11. In order to provide the ISO recommended fire flow of 3,000 gpm on Pinegrove Road in Hingham, it is recommended that the existing 8-inch diameter water main that runs along Main Street from Pinegrove Road to Gardner Road and along Pinegrove Road be replaced with 12-inch diameter cement lined ductile iron water main.
12. In order to provide the ISO recommended fire flow of 1,000 gpm on Mayflower Avenue in Hull, it is recommended that the existing 4-inch diameter water main that runs along Mayflower Avenue be replaced with 8-inch diameter cement lined ductile iron water main. Additionally, the existing 6-inch diameter water main that runs along Hampton Circle from Moreland Avenue to Mayflower Avenue should be replaced with 8-inch diameter cement lined ductile iron water main.

Priority II Hydraulic Improvements

13. In order to provide the inherent capacity for fire flow, an 8-inch diameter cement lined ductile iron water main is recommended on Rockwood Road from East Street to Ledgewood Circle and on Ledgewood Circle in Hingham.
14. In order to provide the inherent capacity for fire flow, it is recommended that the existing water mains on Grist Mill Lane, Howland Lane from Grist Mill Lane to Whitcomb Avenue and Whitcomb Avenue from High Street to Howland Lane in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main.
15. In order to provide the inherent capacity for fire flow, it is recommended that the existing water mains on Nutty Hill Road and Whitehorse Road from High Street to Nutty Hill Road in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main.
16. In order to provide the inherent capacity for fire flow, it is recommended that the existing 4-inch diameter water main on Electric Avenue (also known as Edgewater Road) in Hull be replaced with an 8-inch diameter cement lined ductile iron water main.
17. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Simmons Road in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main.
18. In order to provide the inherent capacity for fire flow, it is recommended that the existing water mains on Smith Road and Hobart Street from New Bridge Road to Smith Road in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main.
19. In order to provide the inherent capacity for fire flow, it is recommended that the existing water mains on Summit Drive and Harbor View Drive from Thaxter Street to Summit Drive in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main.

20. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Dighton Street in Hull be replaced with an 8-inch diameter cement lined ductile iron water main.
21. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Howe Street from Marsh Street to Jarvis Avenue be replaced with an 8-inch diameter cement lined ductile iron water main.
22. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Spruce Street and Hull Street from Canterbury Street to Spruce Street in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main.
23. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Carleton Road in Hingham be extended to High Street with 8-inch diameter water main.

SECTION 5 – Critical Component Assessment

5.1 General

A critical component assessment was performed for the water distribution system in order to evaluate the impact of potential water main failures on the water distribution system. The critical component assessment includes identification of critical areas served, critical water mains and the need for redundant mains.

5.2 Evaluation Criteria

Critical areas served are locations in the distribution system that require continual water supply for public health, welfare or financial reasons. Examples of critical service areas include hospitals, nursing homes, schools, and business districts. All water mains within 1,000 feet of a critical area are considered a critical component. Because water storage tanks and sources provide water and maintain pressure to critical service areas, tanks and primary sources are also considered critical areas. Therefore, any water main within 1,000 feet of a water storage tank or primary source is considered a critical component.

Critical water mains are those mains that are the sole transmission main from a source or tank are considered critical components. In addition, main transmission lines that do not have a redundant main are considered critical. The evaluation included a visual review of the water mains leading into and out of the critical areas and the transmission grid.

5.3 Critical Components

Critical areas served, critical supply mains and redundant mains were evaluated in the Hingham/Hull Water System based on the criteria described above. The following provides a listing of the areas that are considered critical components.

Critical Areas Served

A system-wide review of critical areas served such as hospitals, health care facilities, and schools was completed. Other critical services such as the Coast Guard Station located in Hull and Russelectric, Inc, a 24-hour facility, were identified during the workshop with Aquarion staff. Twenty nine critical services were identified. Table No. 5-1 presents all critical areas served including critical services and critical components of the distribution system.

Critical Water Mains

Critical water mains include primary transmission lines as well as mains connecting water storage tanks and sources to the system. Critical mains are highlighted on Critical Components Map found in Appendix D.

**Table No. 5-1
Critical Service Areas**

Critical Area	Location
1. Coast Guard Station at Allerton Point	93 Main Street, Hull
2. Lillian Jacobs School	180 Harborview Road, Hull
3. Memorial Middle School	81 Central Avenue, Hull
4. Hull High School	180 Main Street, Hull
5. Hingham High School	17 Union Street, Hingham
6. Hingham Middle School	1103 Main Street, Hingham
7. Foster Elementary School	55 Downer Avenue, Hingham
8. Plymouth River Elementary School	200 High Street, Hingham
9. South Elementary School	831 Main Street, Hingham
10. Derby Academy	56 Burditt Avenue, Hingham
11. Notre Dame Academy	1073 Main Street, Hingham
12. St. Paul's School	18 Fearing Road, Hingham
13. South Shore Medical Center	35 Pond Park Road, Hingham
14. Harbor House Nursing & Rehabilitation	11 Condito Road, Hingham
15. Queen Anne's Nursing Home	50 Recreation Park Drive, Hingham
16. Welch Healthcare	15 Condito Road, Hingham
17. Cohasset Knoll Nursing & Rehabilitation Facility	1 Chief Justice Cushing Highway, Cohasset
18. Deerfield Senior Services	20 Pond Park Road, Hingham
19. Russ Electric, Inc.	99 Industrial Park Road, Hingham
20. Turkey Hill Tank	Turkey Hill Lane, Hingham
21. Accord Tank	Whiting Street, Hingham
22. Hingham/Hull District Water Treatment Facility	900 Main Street, Hingham
23. Downing Street Well	Downing Street, Hingham
24. Central Fire – Hingham	339 Main Street, Hingham
25. Town Hall – Hingham	210 Central Street, Hingham
26. Town Hall – Hull	253 Atlantic Avenue, Hull
27. East Elementary School	2 Collins Street, Hingham
28. Linden Ponds	203 Linden Ponds Way, Hingham
29. Peddocks Island	Peddocks Island, Hull

The system was also evaluated for areas where additional mains could be added to create redundancy and strengthen the transmission grid. One area where redundant mains could be installed is from the existing 20-inch diameter water main on South Pleasant Street east along South Pleasant Street and on Lazell Street to the 20-inch main on Union Street. This route will provide redundancy to the existing 24-inch diameter main on Main Street, and strengthen the transmission grid from the Treatment Facility to North Hingham and Hull.

SECTION 6 – Asset Management Considerations

6.1 General

The Hingham/Hull water distribution system has been in operation since 1882. The existing system includes approximately 186 miles of water main varying in size and material. A number of factors including age, material, break history, soil conditions, pressure, and water quality affect the decision to replace or rehabilitate a water main. Using an Asset Management approach, each water main in the system was assigned a grade based on these factors. The grades were then used to establish a prioritized schedule for water main replacement or rehabilitation.

6.2 Data Collection

Information regarding the water main diameters was obtained from existing water distribution system maps. Information regarding pipe age, material and break history was obtained from workshops with system managers and operators and Aquarion records. Because record drawings do not exist for much of the system, water main age, material and break history are based on the operators' field experience and best estimates.

6.3 Evaluation Criteria

In order to prioritize water main replacement or rehabilitation, a water main grading system has been established. The grading system uses the water main characteristics such as age, material, break history, water quality, diameter size and soil characteristics to assign point values to each pipe in the system. Each category is assigned a rating between zero and 100 with zero being the most favorable and 100 being the worst case within the category. Each category is then given a weighted percentage, which represents priorities within the system. It is at the Owner's discretion to adjust the weight based on system performance and condition. Our recommendation is to assign a maximum of 30 percent to any one category. The rating is then multiplied by the weight. The weighted rating for each performance criteria will be utilized to determine the overall rating per pipe. Those pipes with the highest grade are most in need of replacement or rehabilitation.

In order to establish a rating system specific to the Hingham/Hull water system, a workshop was held with the system management and operators. During the discussion, it was determined that water main diameter is a priority for the Hingham/Hull system. Aquarion has experienced a substantial number of breaks in 2¼-inch mains that service multiple homes. Therefore, small diameter mains were given more points within the category and the diameter category was given a larger percentage of the total weighted rating. Aquarion is also concerned with external corrosion of water mains due to bog areas as well as tidal influenced areas. Therefore, the corrosive soil category was given additional weight in the overall rating scale. In addition, material of water main was noted as a priority for Aquarion. Therefore, material was given a higher percent of the overall weighted rating. Table No. 6-1 presents the Asset Management grading system including the ratings and category weights that resulted from discussions with Aquarion.

Age/Material

The water industry in the United States followed certain trends over the last century. The installation date of a water main correlates with a specific pipe material that was used during that time as shown on Table No. 6-2. For example, up until about the year 1958, unlined cast iron water mains were the predominant pipe material installed in water systems. Factory cement lined cast iron mains were manufactured from the late 1950's to about the mid 1970's, when pipe manufactures switched primarily to factory cement lined ductile iron pipe.

Cast iron water mains consist of two types; pit cast and sand spun. Pit cast mains were generally manufactured up to the year 1930 while sand spun mains were generally manufactured between 1930 and 1970. Pit cast mains with diameters between 4-inch and 12-inch do not have a uniform wall thickness and may have "air inclusions" as a result of the manufacturing process. This reduces the overall strength of the main, which makes it more prone to leaks and breaks. Although sand spun mains have a uniform wall thickness, the overall wall thickness was thinner than the pit cast mains. The uniformity provided added strength, however, the thin wall thickness made it more susceptible to corrosion breaks. Pit cast mains 16-inch diameter and larger have very thick pipe walls and are generally stronger than the thinner walled sand spun cast mains.

While the transition to factory cement lined cast iron mains had begun in the early 1950's, prior to the year 1958, most cast iron water mains that were manufactured were still unlined. Unlined cast iron mains increased the potential for internal corrosion. By 1958 the majority of cast iron mains manufactured had a factory cement lining. The year 1958 is also when rubber gasket joints were introduced. Prior to this date, joint material was jute (rope type material) packed in place with lead or a lead-sulfur compound, also known as "leadite" or "hydrotite". Leadite type joint materials expand at a different rate than iron due to temperature changes. This can result in longitudinal split main breaks at the pipe bell. Sulfur in the leadite can promote bacteriological corrosion that can lead to circumferential breaks of the spigot end of the pipe.

The rating score is higher for water mains manufactured before 1958 as opposed to water mains manufactured after this time. After 1958, factory lined cast iron was manufactured and installed up until 1970. This material provided increased protection against internal corrosion. Unlined cast iron water mains make up approximately 60 percent of the Hingham/Hull water system. It was assumed that cast iron water main installed after 1960 was factory lined. Factory lined cast iron makes up approximately 20 percent of the system.

Prestressed concrete cylinder pipe (PCCP) was first produced in 1942 and most widely used in the early 1970s. There are two types of PCCP, embedded-cylinder pipe (ECP) and lined-cylinder pipe (LCP). LCP typically ranges from 16-inch to 48-inche in diameter and ECP is 48-inch and larger diameter pipe. Both types are a thin cement lined

Capital Efficiency Plan™ - Hingham/Hull Water System

Table No. 6-1 Asset Management Grading System			
Weight	Performance Criteria	Rating	Weighted Rating
20%	<u>Breaks per 1,000 Feet</u>		
	Greater than 10.0	100	25
	5.0 to 10.0	75	18.75
	2.0 to 5.0	50	12.5
	Less than 2.0	25	6.25
	No History of Breaks	0	0
25%	<u>Material</u>		
	Asbestos Cement	100	25
	Galvanized Steel	80	20
	Unlined Cast Iron	70	17.5
	Prestressed Concrete	10	2.5
	Factory Lined Cast Iron	10	2.5
	PVC	0	0
	Ductile Iron	0	0
20%	<u>Installation Date</u>		
	Pre 1930	100	20
	1930-1957	80	16
	1958-1969	20	4
	1970-1979	10	2
	1980-1989	5	1
	1990-1999	2	0.4
	2000-2007	0	0
25%	<u>Diameter</u>		
	4-inch water main or smaller	100	20
	6-inch water main	80	16
	8-inch water main	40	8
	10-inch water main	20	4
	12-inch water main	10	2
	14-inch water main or larger	0	0
5%	<u>Soil</u>		
	Clay, Tidal Influence	100	5
	Gravel, Sand	0	0
5%	<u>Water Quality</u>		
	History of water quality problems	100	5
	No history of water quality problems	0	0

**Table No. 6-2
Pipe Material by Installation Year**

Installation Year	Asbestos Cement	Ductile Iron	Galvanized Steel	PVC	Prestressed Concrete	Factory Lined Cast Iron	Unlined Cast Iron	Total
1880-1889							3,876	3,876
1890-1899			227				51,678	51,905
1900-1909			1,365				53,539	54,904
1910-1919			2,486				120,201	122,687
1920-1929			8,632				62,684	71,316
1930-1939			1,984				25,940	27,924
1940-1949	22,238		486				34,780	57,504
1950-1959	118,973		1,814		9,660		47,031	177,478
1960-1969	5,983	1,048			3,642	149,879		160,552
1970-1979		29,892	1,415	942		29,832		62,081
1980-1989		72,096				4,407		76,503
1990-1999		79,431		1,069				80,500
2000-2008		34,937		232				35,169
Grand Total	147,194	217,404	18,409	2,243	13,302	184,118	399,729	982,399

steel cylinder wrapped with prestressed wire. The ECP also has a second layer of concrete between the steel cylinder and the wire. The steel cylinder and wires are susceptible to corrosion. Approximately one percent of the system consists of PCCP water mains. These water mains are all 20-inch diameter water mains and make up a portion of the transmission grid of the system.

Between 1958 and 1970, the water industry also utilized asbestos cement (AC) pipe for their expanding water systems. An advantage of AC pipe is that it resists tuberculation build up, resulting in less system head loss. However, based on external influences such as soil type and high groundwater, the structural integrity of AC mains can deteriorate over time, thereby becoming sensitive to pressure fluctuations and/or nearby construction activities. Approximately 15 percent of the system consists of AC water mains.

Polyvinyl Chloride (PVC) pipe was first used in the United States in the early 1960s. Due to its resistance to both chemical and electrochemical corrosion, PVC pipe is not damaged by aggressive water or corrosive soils. In addition, the smooth interior of PVC pipe is resistant to tuberculation. The 1994 "Evaluation of Polyvinyl Chloride (PVC) Pipe Performance" by the AWWA Research Foundation, found that utilities have experienced minimal long term problems with PVC pipe. Generally, problems with PVC occurred when the area surrounding the pipe was disturbed after installation of the pipe, indicating that PVC pipe is not as strong as ductile iron when hit by excavation equipment after installation. It should be noted that PVC is a permeable material. Low molecular weight petroleum products and organic solvents can permeate PVC pipe if the contaminants are found in high concentrations in the soil surrounding the pipe. Less than one percent of the system is PVC pipe.

Approximately 23 percent of the system is cement lined ductile iron water main. This material was introduced in the United States in 1950's, however, was not widely used until the 1970's. According to the Ductile Iron Pipe Research Association (DIPRA), ductile iron pipe retains all of cast iron's qualities such as machinability and corrosion resistance, but also provides additional strength, toughness, and ductility.

In general, the oldest water mains in the system received a high rating of 100, while the newest received a rating of zero. A significant rating decrease occurs around 1958, which represents the timeframe when factory lining was introduced. Figures No. 6-1 and 6-2 present the installation year of the water mains and the materials, respectively.


Diameter

The Hingham/Hull water distribution system consists of water main ranging in diameter from two to twenty-four inches. Approximately 38 percent of the system is comprised of 8-inch diameter pipes and approximately 31 percent is 6-inch diameter pipes.

In general, as the diameter of a pipe increases, the strength increases. In most cases, failure occurs in the form of ring cracks. This is primarily the result of bending forces on the pipe. Pipes that are 6-inch in diameter are more likely to deflect or bend than a larger diameter main. Pipes that are 8-inch in diameter are less likely to break from bending

Installation Year

- Pre-1900
- 1901 - 1930
- 1931 - 1960
- 1961 - 1990
- 1991 - 2009




Water Main Installation Years

Capital Efficiency Plan™
Hingham/Hull Distribution System
Aquarion Water Company

Figure No.

6-1



Date: March 2011

Scale: 1:72,000 Prepared by or under the supervision of: Robert L. Roland

Water Main Materials
Capital Efficiency Plan™
Hingham/Hull Distribution System
Aquarion Water Company

Figure No.

6-2

forces due to their increased diameter and resulting increased moment of inertia. In addition, the pipe wall thickness typically increases as the pipe diameter increases. Pipes that are 16-inches in diameter and larger have significantly thicker walls than 12-inch diameter pipe and smaller diameter mains, such that in addition to superior bending resistance, they also are much more resistant to failure from pipe wall corrosion.

The rating system for the diameter of the water mains follows the concept that 4-inch diameter water mains are not as strong as 20-inch diameter water mains. Therefore, a rating of 100 was given to 4-inch diameter and smaller water mains and a rating of zero was given to the 14-inch diameter and larger water mains. Table No. 6-1 shows a significant drop in the rating score between a 6-inch diameter water main (80) and 8-inch diameter water main (40). This is due to wall thickness and field experience. An 8-inch diameter water main has proven to have nearly twice the bending strength of a 6-inch diameter water main. In general, 8-inch diameter water mains are stronger and less likely to break than 6-inch diameter pipes. Figure No. 6-3 presents the various diameter sizes throughout the distribution system.

Break History


Based on conversations with company personnel, the Hingham/Hull water system experiences approximately 20 breaks per year on average. In relation to the total miles of water main in the system, this equates to approximately 11 breaks per 100 miles per year. In comparison to the national average of 25 breaks per 100 miles per year, the Hingham/Hull water system is in good condition. However, each water main break costs the system time and labor. They also cause disruption to the public and water consumers. At some point, it becomes more efficient to replace the main than to continue repairing it. Based on Aquarion water main break records, there are several areas in the system that have experienced frequent breaks. These areas are given a rating of 100 while areas with no known breaks received a rating of zero. Areas that have a history of breaks are highlighted on Figure No. 6-4.

Water Quality

In general, the water quality in the Hingham/Hull water system meets or exceeds state and federal water quality standards. However, the water quality in a few areas, including Main Street between South Pleasant Street and Pleasant Street, Fottler Road, and High Street, is a concern. In addition, the neighborhood extending from Volunteer Road to Old Colony Road, Clark Road, and the area near the intersection of High Street, Ward Street and French Street have experienced high color and turbidity during peak demand periods in the spring and summer. Reportedly, customers in these areas have complained of black water, due to high manganese concentrations. This is believed to be due to their proximity to the ground water sources. Prior to construction of the Hingham/Hull District Water Treatment Facility, well water was distributed to the distribution system with minimal treatment. The areas surrounding the wells received the bulk of deposits from the water causing tuberculation of the water main. As demands increase in the summer months, the water main experiences scouring of the pipes, causing the manganese deposits in the pipes to release into the water. Areas where water quality is of concern are highlighted on Figure No. 6-5.

Water Main Diameter

-  4-Inch or Smaller
-  6-Inch
-  8-Inch
-  10-Inch
-  12-Inch or Larger



Date: March 2011


Scale: 1:72,000 Prepared by or under the supervision of: Robert L. Roland

Water Main Diameter
Capital Efficiency Plan™
Hingham/Hull Distribution System
Aquarion Water Company

Figure No.

6-3


-  0.1 to 1.0
-  1.1 to 5.0
-  5.1 to 10.0
-  Greater than 10.0



Areas with History of Breaks
Capital Efficiency Plan™
Hingham/Hull Distribution System
Aquarion Water Company

Figure No.

6-4



Areas with Water Quality Concerns
Capital Efficiency Plan™
Hingham/Hull Distribution System
Aquarion Water Company

Figure No.

6-5

Soils

Water main degradation can occur both internally and externally. Factors that increase the rate of external corrosion include high groundwater, soils with low calcium carbonate, or soils with high acidity or sulfate. Wetlands areas have greater potential to cause external corrosion of water mains than other soil conditions. Areas that are under the influence of ocean water also have increased corrosion potential due to the high salt content. Aquarion has experienced external corrosion in areas near the ocean as well as areas where the pipes are in clay which is a low permeable soil. As a result, groundwater will not drain away from the pipe as quickly. The additional contact with water can accelerate the rate of external corrosion of a pipe. Aquarion has identified several clay areas including Crow Point in Hingham, several hills in Hull and portions of Jerusalem Road in Cohasset.


As shown on Figure No. 6-6, much of the Hingham/Hull area is made up of potentially corrosive soils. Areas where the water system and the potentially corrosive soils coincide are considered areas of potential exterior corrosion. Water mains located in potentially corrosive soil were assigned a rating of 100, while all other pipe was assigned a rating of zero.

6.4 Asset Management Areas of Concern

Based on the Asset Management ratings, there are several areas of concern in the system. Water mains with a total rating between zero and 30 are considered to be in good to excellent condition. Areas with a total rating between 31 and 60 are considered to be in fair to good condition, and areas with a total rating greater than 60 are considered to be in poor to fair condition. Asset Management ratings are presented graphically in Appendix E.

In addition, Aquarion has identified two operational concerns in the system: bleeders and broken valves. As indicated in Table No. 6-3, Aquarion operates 13 bleeders each winter due to shallow water mains. According to the 2008 Annual Statistical Report, an estimated 9.6 million gallons of water was lost to bleeders in 2008. Because bleeders waste water and increase operation and maintenance time for Aquarion staff, Aquarion has indicated that replacing shallow water mains that requires bleeders is a priority.

Table No. 6-4 includes the locations of the 21 known broken valves in the water distribution system. Broken valves increase the number of customers affected during shutdowns due to main breaks. In addition, one broken valve on a water line, may indicate that other valves on that main are in poor condition. Therefore, water mains with broken valves were given higher priority for replacement.



Date: March 2011

Scale: 1:72,000 Prepared by or under the supervision of: Robert L. Roland

Potentially Corrosive Soils

Capital Efficiency Plan™
Hingham/Hull Distribution System
Aquarion Water Company

Figure No.

6-6

Capital Efficiency Plan™ - Hingham/Hull Water System

Table No. 6-3 Bleeder Inventory	
Location of Bleeder	Location of Shallow Main
<u>Hingham</u>	
Pioneer Road	Liberty Pole Road
Brewster Road	Brewster Road and Liberty Pole Road
High Street	Intersection of High Street and Ward Street
Grove Avenue at Hayes Road	Hayes Road
Elmore Road	Elmore Road
East Street at Skating Club	East Street (2¼-inch main)
<u>Hull</u>	
Maple Way	Maple Way
Sunset Avenue	Sunset Avenue
S Street	Cadish Avenue – K Street to U Street
T Street at Beach Avenue	T Street
Beach Avenue	Beach Street – L Street to X Street
X Street at Beach Avenue	X Street at Beach Avenue
North Truro Street	Alsada Road and Logan Avenue

Capital Efficiency Plan™ - Hingham/Hull Water System

Table No. 6-4 Known Broken Valve Inventory	
Location of Valve	Size
<u>Hingham</u>	
High Street	8-Inch
Winthrop Road	8-Inch
Brewster Road	8-Inch
Bradford Road	2-Inch
Green Street at Water Street	4-Inch
Elm Street at Lafayette Avenue	6-Inch
Bel Air Road at Westview Circle	8-Inch
Rockland Street (Valve No. 458)	8-Inch
Nantasket Avenue (Vale No. 460)	8-Inch
<u>Hull</u>	
Point Allerton Avenue	12-Inch
Nantasket Avenue at Carousel	12-Inch
C Street at Cadish Avenue	6-Inch
Crest Road	1-Inch
Gunrock Avenue at Atlantic Avenue	4-Inch
Manomet Avenue at Kenberma Street	6-Inch
Beach Avenue at Coburn Street	6-Inch
Beacon Road at Bluff Road	6-Inch
Standish Avenue at Beacon Road	6-Inch
Whitehead Avenue at Fifth Street	8-Inch
Nantasket Road at Third Street	4-Inch
Bay Street at Roosevelt Avenue	6-Inch
Bay Street at Island View Road	6-Inch
Edgewater Road at Tenth Street	2-Inch

SECTION 7 – Capital Efficiency Recommendations

7.1 General

The following summarizes the findings of the study and presents a prioritized plan for recommended improvements and associated costs. The prioritization of improvements allows for constructing the necessary improvements over an extended period of time as funds allow.

Costs are based on the February 2011 Engineering News Record (ENR) construction cost index for Boston, MA of 11433.13 and include a 25 percent allowance for engineering and contingencies and costs associated with water services, hydrants and permanent and temporary trench pavement. Estimates do not include costs for land acquisition, easement, or legal fees.

The capital improvement projects considered by this study will provide a direct benefit to the overall level of service to the Hingham/Hull customers, reduce operation and maintenance cost by reducing the frequency of water main failures and the damage they cause, as well as improve fire protection to the homeowners and businesses.

The Water Research Association's (formerly the American Water Works Research Foundation) study on "Cost of Infrastructure Failure," which was completed in 2002, found that in addition to direct costs paid by water utility ratepayers for water main failures, there are also societal costs, which are paid by the public. Examples of the direct costs include outside contractor costs, engineering costs, police assistance, fire department assistance, electrical, telephone and gas utility damage costs, landscaping restoration costs and laboratory costs. Examples of societal costs included the cost of traffic impacts, business customer outage impacts, public health impacts (including loss of life), property damage not covered by direct costs, and the cost of reduced fire fighting capability during the failure event.

Replacement of one percent of a system each year (a 100 year replacement cycle) is a reasonable guideline based on industry experience and analysis. For the Hingham/Hull distribution system, this would equate to approximately 9,800 linear feet of water main replacement each year as a guideline. Regular rehabilitation of water mains reduces main failures, leakage and water quality issues. Water main rehabilitation can also provide socio-economic benefits by reducing operational costs associated with chemical and energy usage. Also, rehabilitation or replacement of water mains that are inadequately sized to provide needed fire protection will improve public safety.

7.2 General Recommendations

In order to establish a comprehensive database of the condition of the system, it is recommended that Aquarion create a water main failure database. The database should include the location of each break and the properties of the failed main such as diameter, material, joint type, and type of lining. In addition, Aquarion should record the type of

failure such as ring crack, lateral split, hole in the pipe, “punk” AC pipe failure, or joint leak. If possible, Aquarion should include the apparent cause of the failure such as frost load, traffic load, direct contractor damage, settlement, water hammer, external soil corrosion or stray current. This data should then be inputted into the hydraulic model to create a Water Main Failure Map for identifying problem areas in the future. The water main failure database will aid Aquarion in making water main replacement decisions in the future.

In addition, it is recommended that Aquarion create a database of new or replacement water mains. The database should include water main diameter, material, lining, joint type, soil conditions, date of installation, and as-built drawings. This data can be added to the existing database, created for this study, to maintain a comprehensive water main database.

It is recommended that prior to installation of all new ductile iron water mains, Aquarion test the soils in the area of the new main to determine if the soil has high corrosion potential. If the soil is found to be potentially corrosive soil, Aquarion should consider wrapping the main to protect against external corrosion. Wrapping is a relatively inexpensive practice that may extend the life of new ductile iron pipe. In addition, wrapping helps to protect the pipe from stray currents that may develop near the main.

Based on proposed development within the High Service Area, a high service area build-out analysis is recommended. The analysis should consider existing and proposed storage and supply requirements and existing high service area infrastructure. Recommendations should be developed to alleviate and storage, supply or distribution system deficiencies.

7.3 Prioritization of Improvements

Based on the Three Circles Approach, a prioritized list of improvements was created. Improvements were separated into three phases. The Phase I Improvements are priority improvements based on hydraulic needs, location in the distribution system and the condition of the water main. In general, these include water mains that fall into two or more of the three circles strengthen the transmission grid, eliminate potential asset management concerns, as well as provide redundancy. The hydraulically deficient areas, critical component considerations and asset management ratings are combined on the Three Circle Integration map included in Appendix F.

It should be noted that due to the nature of this Capital Efficiency Plan™, the list of improvements is extensive. This results in a high associated cost if all of the suggested improvements were constructed. The intent of the prioritization, therefore, is to serve as a guide for implementation from the most needed to the least needed improvements based on the weighted criteria established jointly by Aquarion and Tata & Howard. These improvements would most logically be constructed over an extended period of time.

Table No. 7-1, at the end of this section, includes a prioritized list of Phase I Improvements and the hydraulic, critical component and asset management status of each

improvement. Table No. 7-2 includes the linear footage and estimated cost of each Phase I Improvement. A Phase I and Phase II Improvements map is included in Appendix G. It should be noted that paving schedules were not evaluated as part of this study. Aquarion may reprioritize the recommendations if paving is scheduled on any of the roads recommended for improvement.

Phase I Improvements

1. As a result of its age and material, the 6-inch diameter AC main on Pleasant Street from Main Street to Middle Street in Hingham has an asset management rating of 66. The main is located in a critical area near Hingham High School and the Downing Street Well. In addition, the main does not meet the ISO recommended fire flow of 3,000 gpm on Pleasant Street, making it a recommended hydraulic improvement. Due to these considerations, it is recommended that an 8-inch diameter water main replace the existing main from Main Street to Middle Street. This improvement will not only eliminate an asset management concern, but will also strengthen the hydraulics of the transmission grid. The estimated probable construction cost for approximately 1,500 feet of 8-inch diameter water main is \$281,000.
2. The existing 6-inch and 4-inch diameter water main on Beach Avenue in Hull has experienced frequent breaks and has required numerous repairs. The main was installed in corrosive soils, and also at a shallow depth, requiring the use of a bleeder. Several broken gate valves are located along the main, increasing the number of customers affected by a shutdown. In addition, its location within the sand dunes along the beach impedes repair costs and inhibits maintenance efforts. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Beach Avenue be replaced with 12-inch diameter cement lined ductile iron water main. The proposed water main will be installed along an existing utility easement adjacent to Beach Avenue. In addition, the existing 2-inch main on X Street has an asset management rating of 73. The main was installed at a shallow depth, requiring the use of a bleeder. The main is also a dead end, impacting water quality. It is recommended that the main be replaced and extended to Y Street with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 1,800 linear feet of 12-inch diameter water main and approximately 370 linear feet of 8-inch diameter water main, including design, coordination with gas and sewer utilities, construction and contingencies, is \$439,000.
3. The existing 6-inch unlined cast iron water main on Downer Avenue in Hingham from Otis Street to Planters Field Lane has an asset management rating of 63. In addition, the main is located in a critical area, adjacent to the Foster Elementary School. In order to provide ISO needed fire flow of 3,000 gpm on Downer Avenue, it is recommended that the existing 6-inch diameter water main on Downer Avenue from Otis Street to Planters Field Lane be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for

installation of approximately 1,450 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$271,000.

4. The existing 6-inch diameter cast iron main on Hull Street and Spruce Street in Hingham is considered a critical main due to its use as a transmission main for both the Hingham and Cohasset service areas. In addition, the existing main does not provide the inherent fire flow capacity for the area serviced by the main. The water main on Hull Street has an asset management rating of 63. It is recommended that the existing water main be replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 1,740 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$304,000.
5. The existing 6-inch diameter unlined cast iron main on Atlantic Avenue in Hull does not meet the ISO needed fire flow of 3,000 gpm. In addition, the main has an asset management rating of 68, due to its material, age, and location in corrosive soils. It is recommended that the existing main that runs along Atlantic Avenue from Gunrock Avenue to Jerusalem Road be replaced with a 12-inch diameter cement lined ductile iron water main. Additionally, the existing 4-inch diameter water main that runs along Summit Avenue should be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for the installation of approximately 3,500 linear feet of 12-inch diameter water main and approximately 1,200 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$950,000. This improvement accounts for the approximately 1,200 linear feet of 12-inch water main being installed on Atlantic Avenue between Stony Beach Road and Gunrock Avenue in the spring 2011.
6. The existing 4-inch diameter main on Edgewater Road in Hull is in a hydraulically deficient area with an asset management rating of 63. In addition, a broken valve exists at the connection with Nantasket Avenue. It is recommended that the 4-inch cast iron main be replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 480 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$138,000.
7. In order to provide the inherent capacity for fire flow, it was recommended in Section 4 that the existing 6-inch unlined cast iron water mains on Nutty Hill Road and Whitehorse Road from High Street to Nutty Hill Road in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main. The mains are also located in a critical area, due to the proximity of the Plymouth River School. However, while reviewing the asset management ratings of the water mains, the water main on Hemlock Road has an asset management rating of 64 and is considered fair to poor, and the water main on Whitehorse Road has an asset management rating of 59, which is considered good to fair. Replacing the water main on Hemlock Road from High Street to Nutty Hill Road will also provide the inherent capacity for fire flow. The estimated probable construction cost for

installation of approximately 1,500 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$245,000.

8. Due to its age and material, the 6-inch and 8-inch diameter AC main on Liberty Pole Road in Hingham has an asset management rating of 66. The main is located in a critical area, near the South Elementary School. In addition, the main was installed at a shallow depth, requiring the use of a bleeder to prevent freezing. It is recommended that the existing main be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 2,100 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$434,000.

Phase II Improvements

Phase II Improvements generally include areas that fall into two circles, but are located on side streets or dead ends, as well as areas that are hydraulically deficient or have high asset management ratings. These improvements generally will benefit a localized area, while Phase I Improvements benefit the transmission grid. Phase II Improvements should be completed as funds become available and considered as when reviewing road paving schedules. Table No. 7-3 includes a prioritized list of Phase II Improvements and the hydraulic, critical component and asset management status of each improvement. Table No. 7-4 includes the linear footage and estimated cost of each Phase II Improvement.

9. In order to provide ISO recommended fire flow of 3,000 gpm on Rockaway Avenue in Hull and eliminate a hydraulically deficient area, it is recommended that the existing 6-inch diameter water main that runs along Rockaway Avenue from Wyola Road to Alsada Road be replaced with 8-inch diameter cement lined ductile iron water main. Additionally, it is recommend that the existing 6-inch diameter water mains that run along Wyola Road from Rock View Road to Logan Avenue and Park Avenue from Wyola Road to Shore Garden Road be replaced with 8-inch diameter cement lined ductile iron water main. The water main on Park Avenue has an asset management rating of 68. The estimated probable construction cost for installation of approximately 1,350 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$277,000.
10. In order to provide ISO recommended fire flow of 1,000 gpm on Mayflower Avenue in Hull, it is recommended that the existing 4-inch diameter water main that runs along Mayflower Avenue be replaced with 8-inch diameter cement lined ductile iron water main. The main on Mayflower Avenue has an asset management rating of 67, due to its diameter, age and material. Additionally, the existing 6-inch diameter water main that runs along Hampton Circle from Moreland Avenue to Mayflower Avenue should be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 750 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$162,000.

11. In order to provide the inherent capacity for fire flow, it is recommended that the existing water mains on Grist Mill Lane, Howland Lane from Grist Mill Lane to Whitcomb Avenue and Whitcomb Avenue from High Street to Howland Lane in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main. The mains have an asset management rating of 61. The estimated probable construction cost for installation of approximately 3,600 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$586,000.
12. In order to provide the inherent capacity for fire flow, it is recommended that the existing 6-inch AC water main on Howe Street in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main. The existing main has a poor asset management rating of 61; replacement of the main will eliminate this concern. The estimated probable construction cost for installation of approximately 1,970 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$321,000.
13. To provide the ISO recommended fire flow of 3,000 gpm on Keith Way (at all locations), in Hingham, it is recommended that the existing 8-inch diameter water main that runs along Recreation Park Drive to Keith Way be replaced with a 16-inch diameter cement lined ductile iron water main. The 8-inch main on Recreation Park Drive should be extended to Derby Street with 16-inch diameter main to provide fire flow and to eliminate a dead end. It is also recommended that the existing 12-inch diameter main on Keith Way be replaced with 16-inch diameter cement lined ductile iron main. The water mains in this location are considered to be in a critical area due to the servicing of a medical facility. The estimated probable construction cost for installation of approximately 2,450 linear feet of 16-inch diameter water main, including design, construction and contingencies is \$460,000.
14. Channel Street is located in a critical area, near Hull High School. The existing 6-inch AC main has experienced frequent breaks, and due to its age and material has an asset management rating of 71. Therefore, an 8-inch diameter cement lined ductile iron water main is recommended to replace the existing main. The estimated probable construction cost for installation of approximately 710 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$116,000.
15. O Street in Hull is located in a critical area near a public school. The existing 2-inch galvanized steel main from Central Avenue to Nantasket Avenue has an asset management rating of 75 due to its age, material, and break history. The main has experienced five breaks in the past decade, creating the need for frequent costly repairs. It is recommended that the main be replaced with 8-inch cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 730 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$119,000.

16. The existing 6-inch water main on Beach Avenue from A Street to L in Hull has experienced frequent breaks and has required numerous repairs. The main was installed in corrosive soils, and also at a shallow depth, requiring the use of a bleeder. The main has an asset management rating of 68. The main is considered critical, due to its use as a primary transmission main to North Hull. In addition, its location within the sand dunes along the beach impedes repair cost and inhibits substantial maintenance efforts. In order to provide the inherent capacity for fire flow, it is recommended that the existing water main on Beach Avenue be replaced with 12-inch diameter cement lined ductile iron water main. The proposed water main will be installed along an existing utility easement adjacent to Beach Avenue. The estimated probable construction cost for installation of approximately 7,100 linear feet of 12-inch diameter water main, including design, coordination with gas and sewer utilities, construction and contingencies, is \$1,332,000.
17. In order to eliminate a dead end, and provide the inherent capacity for fire flow, it is recommended that the existing 6-inch diameter water main on Carleton Road in Hingham be extended to High Street with an 8-inch ductile iron water main. The estimated probable construction cost for installation of approximately 500 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$166,000.
18. In order to provide ISO recommended fire flow of 3,000 gpm on Pinegrove Road in Hingham, it is recommended that the existing 8-inch diameter water main that runs along Main Street from Pinegrove Road to Gardner Road and along Pinegrove Road be replaced with 12-inch diameter cement lined ductile iron water main. The water mains are located in a critical area, due to the proximity of two schools. The water main on Main Street has an asset management rating of 53; replacement of the main will eliminate this concern. The estimated probable construction cost for the installation of approximately 3,270 linear feet of 12-inch diameter water main, including design, construction and contingencies is \$614,000.
19. The water main on Simmons Road in Hingham is comprised of 2-inch galvanized steel and 4-inch unlined cast iron installed in 1924. Due to these factors, the main has an asset management rating of 63. In order to provide adequate fire flow, it is recommended that the existing main on Simmons Road be replaced with an 8-inch cement lined ductile iron main. The estimated probable construction cost for installation of approximately 1,060 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$173,000.
20. The unlined 4-inch cast iron main on N Street from Central Avenue to Nantasket Avenue was installed in 1922. Due to its age and material, the main has a poor asset management rating of 68. The main is also located in a critical area near the Hull Memorial School. In order to eliminate the asset management concern, and provide increased fire flow, it is recommended that the main be replaced with 8-inch diameter cement lined ductile iron water mains. The estimated probable

construction cost for installation of approximately 730 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$119,000.

21. The water mains on H Street, M Street and K Street from Central Avenue to Cadish Avenue in Hull are composed of 6-inch and 4-inch unlined cast iron water main, installed prior to 1922. These mains have high asset management ratings from 70 to 73 due to their high break rate and age. The K Street main is also located in corrosive soils. In addition, the mains are located in a critical area due to the proximity of a public school. It is recommended that all the mains are replaced with 8-inch cement lined ductile iron main. The estimated probable construction cost for installation of approximately 1,790 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$351,000.
22. The existing 6-inch diameter cast iron water main on Central Avenue in Hull has an asset management rating of 78. The aging main is located in corrosive soils, leading to frequent breaks. A portion of the main is also located in a critical area, near a school. It is recommended that the entire main from A Street to Q Street be replaced with 8-inch diameter cast iron water main to strengthen the transmission grid. The estimated probable construction cost for installation of approximately 3,340 linear feet of 8-inch diameter water main, including design, construction and contingencies is \$543,000.
23. In order to provide the inherent capacity for fire flow, it is recommended that the existing water mains on Summit Drive and Harbor View Drive from Thaxter Street to Summit Drive in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main. Due to their age and material, the existing 6-inch AC water mains have an asset management rating of 66 and 61, respectively. The estimated probable construction cost for installation of approximately 1,800 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$294,000.
24. The existing 4-inch and 2¼-inch diameter cast iron main on Otis Hill Road in Hingham has an asset management rating of 78. In addition, the main is located in a critical area adjacent to a school. The main has also experienced several breaks due to its poor condition. Future breaks could potentially cause disruptions at the nearby school. It is recommended that the existing main be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 1,330 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$217,000.
25. The existing 2¼-inch unlined cast iron main on Downing Street in Hingham was installed in 1937. Due to its age, material, and break history, the main has an asset management rating of 64. In addition, the main is located in a critical area due to its proximity to Hingham High School. In order to eliminate the asset management concern, and provide increased fire flow, it is recommended that the main be replaced with an 8-inch diameter cement lined ductile iron water main. The

estimated probable construction cost for installation of approximately 1,140 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$186,000.

26. The main on Independence Lane in Hingham is composed of 6-inch diameter AC pipe. The main has a high asset management rating of 66 due to its age and material. It is recommended that the existing main from be replaced with 8-inch cement lined ductile iron water main. The estimated probable construction cost for the installation of approximately 1,900 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$392,000.
27. The existing 6-inch and 2-inch diameter mains on Hull Street and Clark Drive in Hingham have asset management ratings of 64 and 65, respectively. The Hull Street main is considered critical because it is part of the transmission grid. In order to eliminate the asset management concern, and increase available fire flow on both streets, it is recommended that both mains are replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for the installation of approximately 1,060 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$187,000.
28. The existing main on High Street from Tower Road to Whitehorse Road in Hingham is a 6-inch diameter unlined cast iron water main. The water main has an asset management rating of 64. The main is considered critical as it services a public school. In addition, the main is choke point for the transmission grid as the majority of High Street is composed of 8-inch diameter main. In order to eliminate the hydraulic bottleneck, it is recommended the existing main be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for the installation of approximately 2,210 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$413,000.
29. In order to provide the inherent capacity for fire flow, it was recommended in Section 4 that the existing 2¼-inch and 6-inch diameter water mains on Smith Road and Hobart Street from New Bridge Road to Smith Road in Hingham be replaced with an 8-inch diameter cement lined ductile iron water main. The existing 6-inch diameter water main on Hobart Street from New Bridge Road to Smith Road has an asset management rating of 27 and is considered to be in good to excellent condition. The existing water main on Hobart Street from Smith Road to Main Street has an asset management rating of 63 and is considered to be in fair to poor condition. This water main should be replaced instead of the portion from New Bridge Road to Smith Road. This will also provide the inherit capacity for fire flow in the area and it will all Aquarion to leave in a good main and replace a poor main.

Also, a 14-inch gate valve was reportedly installed on the 20-inch diameter water main on Main Street at Hobart Street in Hingham. The smaller diameter valve creates additional headlosses in the 20-inch diameter main, which reduces the available fire flow and the efficiency of the distribution system. In addition,

Aquarion generally requires butterfly valves on mains 16-inches in diameter and larger. Therefore, while work is being completed on Hobart Street from Smith Road to Main Street, it is recommended that the 14-inch gate valve be replaced with a 20-inch butterfly valve. The estimated probable construction cost of approximately 3,460 linear feet of 8-inch diameter ductile iron main and a 20-inch butterfly valve, including engineering, construction, and contingencies, is \$571,000.

Phase III Improvements

Phase III Improvements generally include areas that fall into one circle. Phase III-Priority 1 Improvements include areas that are hydraulically deficient, and do not meet ISO recommended fire flow. Phase III-Priority 2 Improvements encompass mains that have high asset management ratings as well as broken valves or minimal ground cover. Phase III-Priority 3 Improvements only include mains with high asset management ratings. Phase III Improvements should be completed as funds become available and considered as when reviewing road paving schedules. Table No. 7-5 includes an unordered list of Phase III Improvements for Priority 1 and 2 Improvements, and the hydraulic, critical component and asset management status of each improvement. Table No. 7-6 includes the linear footage and estimated cost of each Phase II-Priority 1 and 2 Improvement. The Phase III-Priority 3 Improvements with the highest asset management ratings for Hingham and Hull are included in Table No. 7-7. The remaining Phase III-Priority 3 Improvements are displayed graphically on the Phase III Improvements Map, located in Appendix G.

Phase III-Priority 1

30. In order to provide ISO needed fire flow of 3,500 gpm on George Washington Boulevard in Hingham, it is recommended that the existing 8-inch diameter water main that runs along George Washington Boulevard be replaced with 12-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 2,360 linear feet of 12-inch diameter water main, including design, construction and contingencies is \$531,000.
31. In order to provide ISO needed fire flow of 3,000 gpm on East Gate Lane in Hingham, it is recommended that the existing 8-inch diameter water main that runs along East Gate Lane be replaced with 12-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 1,380 linear feet of 12-inch diameter water main, including design, construction and contingencies is \$259,000.
32. In order to provide ISO needed fire flow of 3,500 gpm on Beal Street in Hingham, it is recommended that the existing 8-inch diameter water main that runs along Beal Street be replaced with 12-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 2,500 linear feet of 12-inch diameter water main, including design, construction and contingencies is \$540,000.

33. In order to provide the inherent capacity for fire flow, an 8-inch diameter cement lined ductile iron water main is recommended on Rockwood Road from East Street to Ledgewood Circle and on Ledgewood Circle in Hingham. Replacement of the main will also eliminate an asset management concern, as the main has a rating of 56. The estimated probable construction cost for installation of approximately 3,380 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$601,000.
34. In order to provide the inherent capacity for fire flow, it is recommended that the existing 2-inch diameter PVC and 6-inch diameter cast iron mains on Dighton Street in Hull be replaced with an 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 700 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$114,000.

Phase III – Priority 2

35. The existing 2-inch galvanized steel main on Bradford Road in Hingham was installed in 1927. Due to its age the main has a poor asset management rating of 70. In addition, there is an inoperable gate valve at the connection with the water main on Central Street. Due to these factors, it is recommended that the main be replaced with new 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 540 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$88,000.
36. The existing 6-inch cast iron main on Eldridge Court in Hingham has an asset management rating of 78 due to age and frequent break history. In addition, there is a broken gate valve at the connection with the water main on Water Street. Due to these factors, it is recommended that the main be replaced with new 8-inch diameter cement lined ductile iron main. Replacement of the main will also eliminate a choke point in the system. The estimated probable construction cost for installation of approximately 300 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$87,000.
37. The existing 4-inch cast iron main on Elm Street in Hingham between Hershey Street and Emerald Street has asset management ratings of 68. In addition, there is an inoperable gate valve at the connection with the water main on Hersey Street. Due to these factors, it is recommended that the main be replaced with new 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 800 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$130,000.
38. A 6-inch and 8-inch diameter AC main currently runs along Brewster Road in Hingham. The main has experience frequent breaks, leading to its asset management rating of 61. In addition, the main was installed at a shallow depth, requiring the use of bleeder to prevent main freezing. It is recommended that the main be replaced with 8-inch cement lined ductile iron water main, to eliminate the bleeder and asset management issues. The estimated probable construction cost for

installation of approximately 2,500 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$516,000.

39. The existing 2¼-inch diameter unlined cast iron main on East Street in Hingham near the Cohasset Town Line has an asset management rating of 74 due its age. In addition, the main was installed to a shallow depth, requiring the use of a bleeder. In order to eliminate the bleeder to conserve water, as well as strengthen the interconnection to the Cohasset water system, it is recommended that the main be replaced with 8-inch diameter cement lined ductile iron water main. The estimated probable construction cost for installation of approximately 650 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$155,000.
40. The existing 1-inch and 2-inch diameter galvanized steel main on Elmore Road in Hingham was installed to a shallow depth, requiring the use of a bleeder. In addition, the 1-inch and 2-inch mains are dead ended, preventing proper turnover. The mains have an asset management rating of 65 due to their age and break history. It is recommended that the main is replaced with 8-inch diameter cement lined ductile iron water main along the entire length of Elmore Road to eliminate these concerns. The estimated probable construction cost for installation of approximately 730 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$151,000.
41. A 2¼-inch and 2-inch diameter cast iron and galvanized steel main currently runs along Hayes Road in Hingham. The main has an asset management rating of 69 due to its age. In addition, the main was installed at a shallow depth, requiring the use of bleeder to prevent main freezing. It is recommended that the main be replaced with 8-inch cement lined ductile iron water main, to eliminate the bleeder and asset management issues. The estimated probable construction cost for installation of approximately 420 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$121,000.
42. The existing 6-inch diameter main on the majority of Manomet Avenue in Hull has an asset management rating of 68 due to its age, material, break history, and that it is located in corrosive soil. In addition, the gate valve at Kenberma Street is inoperable. Due to these factors, it is recommended that the main be replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 5,400 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$878,000.
43. The existing 6-inch diameter main on Whitehead Avenue from Nantasket Avenue to Nantasket Road in Hull has an asset management rating of 68 due to its age, material, break history, and that it is located in corrosive soil. In addition, the gate valve at 5th Street is inoperable. Due to these factors, it is recommended that the main be replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 2,070 linear

feet of 8-inch diameter water main, including design, construction and contingencies, is \$337,000.

44. The existing 4-inch diameter main on Sunset Avenue in Hull has an asset management rating of 78. The main was installed in 1893 at a shallow depth, requiring the use of a bleeder. It is recommended that the main be replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 1,400 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$228,000.
45. The existing 4-inch diameter and 2-inch diameter water mains on T Street in Hull have an asset management rating of 75. The mains were installed circa 1900 at a shallow depth, requiring the use of a bleeder. It is recommended that the mains be replaced with 8-inch diameter cement lined ductile iron main. The estimated probable construction cost for installation of approximately 840 linear feet of 8-inch diameter water main, including design, construction and contingencies, is \$137,000.

Table No. 7-1 Prioritization of Improvements - Phase I							
Item No.	Location	From	To	Town	Hydraulically Deficient?	Critical Area?	Asset Management Rating
1	Pleasant Street	Main Street	Middle Street	Hingham	Yes	Yes	66
2	Beach Avenue	L Street	X Street	Hull	Yes	Yes	63
	X Street			Hull	No	No	73
3	Downer Avenue	Otis Street	Planters Field Lane	Hingham	Yes	Yes	63
4	Hull Street	Canterbury Street	Spruce Street	Hingham	Yes	Yes	63
	Spruce Street			Hingham	Yes	No	27
5	Atlantic Avenue	Gunrock Avenue	Jerusalem Road	Hull	Yes	No	73
	Summit Avenue			Hull	Yes	No	68
6	Edgewater Road	Nantasket Avenue	Existing 6-inch	Hull	Yes	No	63
7	Nutty Hill Road			Hingham	Yes	Yes	64
	Hemlock Road	High Street	Nutty Hill Road	Hingham	Yes	Yes	64
8	Liberty Pole Road	Main Street	Colonial Road	Hingham	No	Yes	66

Table No. 7-2 Estimated Improvement Costs - Phase I							
Item No.	Location	From	To	Town	Water Main Diameter (in.)	Length (LF)	Estimated Cost
1	Pleasant Street	Main Street	Middle Street	Hingham	8	1,500	\$281,000
2	Beach Avenue	L Street	X Street	Hull	12	1,770	\$332,000
	X Street			Hull	8	370	\$107,000
3	Downer Avenue	Otis Street	Planters Field Lane	Hingham	8	1,450	\$271,000
4	Hull Street	Canterbury Street	Spruce Street	Hingham	8	860	\$161,000
	Spruce Street			Hingham	8	880	\$143,000
5	Atlantic Ave	Gunrock Avenue	Jerusalem Road	Hull	12	3,500	\$755,000
	Summit Avenue			Hull	8	1,200	\$195,000
6	Edgewater Road	Nantasket Avenue	Existing 6-inch	Hull	8	480	\$138,000
7	Nutty Hill Road			Hingham	8	650	\$106,000
	Hemlock Road	High Street	Nutty Hill Road	Hingham	8	850	\$139,000
8	Liberty Pole Road	Main Street	Colonial Road	Hingham	8	2,100	\$434,000
Total Estimated Phase I Cost:							\$3,062,000

Table No. 7-3 Prioritization of Improvements - Phase II							
Item No.	Location	From	To	Town	Hydraulically Deficient?	Critical Area?	Asset Management
9	Park Avenue	Wyola Road	Shore Garden Road	Hull	Yes	No	68
	Wyola Road	Rock View Road	Logan Avenue	Hull	Yes	No	32
	Rockaway Avenue	Wyola Road	Alsada Road	Hull	Yes	No	-
10	Mayflower Avenue			Hull	Yes	No	68
	Hampton Circle	Moreland Avenue	Mayflower Avenue	Hull	Yes	No	58
11	Grist Mill Lane			Hingham	Yes	No	40
	Howland Lane	Whitcomb Avenue	Grist Mill Lane	Hingham	Yes	No	61
	Whitcomb Avenue	High Street	Howland Lane	Hingham	Yes	No	61
12	Howe Street			Hingham	Yes	No	61
13	Keith Way			Hingham	Yes	Yes	9
	Recreation Park Drive	Derby St.	Keith Way	Hingham	Yes	Yes	12
14	Channel Street	Helen Street	Town Way	Hull	No	Yes	71
15	O Street	Central Avenue	Nantasket Avenue	Hull	No	Yes	75
16	Beach Avenue	A Street	L Street	Hull	No	Yes	68
17	Carleton Road		High Street	Hingham	Yes	Yes	-
18	Pinegrove Road			Hingham	Yes	Yes	17
	Main Street	Pinegrove Road	Gardner Road	Hingham	Yes	Yes	53
19	Simmons Road			Hingham	No	No	63

Table No. 7-3 (Continued)
Prioritization of Improvements - Phase II

Item No.	Location	From	To	Town	Hydraulically Deficient?	Critical Area?	Asset Management
20	N Street	Central Avenue	Nantasket Avenue	Hull	No	Yes	68
21	M Street	Central Avenue	Cadish Avenue	Hull	No	Yes	73
	K Street	Central Avenue	Cadish Avenue	Hull	No	Yes	78
	H Street	Central Avenue	Cadish Avenue	Hull	No	Yes	73
22	Central Avenue	A Street	Q Street	Hull	No	Yes	78
23	Summit Drive			Hingham	Yes	No	66
	Harborview Drive	Thaxter Street	Summit Drive	Hingham	Yes	No	61
24	Otis Hill Road	Broad Cover Road	Gov. Long Road	Hingham	No	Yes	79
25	Downing Street			Hingham	No	Yes	64
26	Independence Lane	Liberty Pole Road	Colonial Road	Hingham	No	Yes	66
27	Hull Street	Clark Drive	Existing 8-inch	Hingham	No	Yes	64
	Clark Drive			Hingham	No	Yes	65
28	High Street	Tower Road	Whitehorse Rd	Hingham	No	Yes	64
29	Smith Road			Hingham	Yes	No	61
	Hobart Street	Main Street	Smith Road	Hingham	Yes	No	63

Table No. 7-4 Estimated Improvement Costs - Phase II							
Item No.	Location	From	To	Town	Water Main Diameter (in.)	Length (LF)	Estimated Cost
9	Park Avenue	Wyola Road	Shore Garden Road	Hull	8	200	\$58,000
	Wyola Road	Rock View Road	Logan Avenue	Hull	8	900	\$147,000
	Rockaway Avenue	Wyola Road	Alsada Road	Hull	8	250	\$72,000
10	Mayflower Avenue			Hull	8	550	\$104,000
	Hampton Circle	Moreland Avenue	Mayflower Avenue	Hull	8	200	\$58,000
11	Grist Mill Lane			Hingham	8	850	\$139,000
	Howland Lane	Whitcomb Avenue	Grist Mill Lane	Hingham	8	800	\$130,000
	Whitcomb Avenue	High Street	Howland Lane	Hingham	8	1,950	\$317,000
12	Howe Street			Hingham	8	1,970	\$321,000
13	Keith Way			Hingham	16	850	\$160,000
	Recreation Park Drive	Derby St.	Keith Way	Hingham	16	1,600	\$300,000
14	Channel Street	Helen Street	Town Way	Hull	8	710	\$116,000
15	O Street	Central Avenue	Nantasket Avenue	Hull	8	730	\$119,000
16	Beach Avenue	A Street	L Street	Hull	12	7,100	\$1,332,000
17	Carleton Road		High Street	Hingham	8	500	\$166,000
18	Pinegrove Road			Hingham	12	1,370	\$257,000
	Main Street	Pinegrove Road	Gardner Road	Hingham	12	1,900	\$357,000
19	Simmons Road			Hingham	8	1,060	\$173,000

Table No. 7-4 (Continued)							
Estimated Improvement Costs - Phase II							
Item No.	Location	From	To	Town	Water Main Diameter (in.)	Length (LF)	Estimated Cost
20	N Street	Central Avenue	Nantasket Avenue	Hull	8	730	\$119,000
21	M Street	Central Avenue	Cadish Avenue	Hull	8	470	\$136,000
	K Street	Central Avenue	Cadish Avenue	Hull	8	600	\$98,000
	H Street	Central Avenue	Cadish Avenue	Hull	8	720	\$117,000
22	Central Avenue	A Street	Q Street	Hull	8	3,340	\$543,000
23	Summit Drive			Hingham	8	1,190	\$194,000
	Harborview Drive	Thaxter Street	Summit Drive	Hingham	8	610	\$100,000
24	Otis Hill Road	Broad Cover Road	Gov. Long Road	Hingham	8	1,330	\$217,000
25	Downing Street			Hingham	8	1,140	\$186,000
26	Independence Lane	Liberty Pole Road	Colonial Road	Hingham	8	1,900	\$392,000
27	Hull Street	Clark Drive	Existing 8-inch	Hingham	8	530	\$100,000
		Clark Drive		Hingham	8	530	\$87,000
28	High Street	Tower Road	Whitehorse Rd	Hingham	8	2,210	\$413,000
29	Smith Road			Hingham	8	1,960	\$319,000
	Hobart Street	Main Street	Smith Road	Hingham	8	1,500	\$252,000
Total Estimated Phase II Cost:							\$7,599,000

Table No. 7-5 Prioritization of Improvements - Phase III							
Priority 1							
Item No.	Location	From	To	Town	Hydraulically Deficient?	Critical Area?	Asset Management
30	George Washington Boulevard			Hingham	Yes	No	25
31	East Gate Lane			Hingham	Yes	No	37
32	Beal Street	Lincoln Street	Tuckers Lane	Hingham	Yes	No	25
33	Rockwood Road	East Street	Ledgewood Circle	Hingham	Yes	No	59
	Ledgewood Circle			Hingham	Yes	No	59
34	Dighton Street			Hull	Yes	No	20

Table No. 7-5 (Continued)
Prioritization of Improvements - Phase III

Priority 2							
Item No.	Location	From	To	Town	Hydraulically Deficient?	Critical Area?	Asset Management
35	Bradford Road			Hingham	No	No	70
36	Eldridge Court	Green Street	Water Street	Hingham	No	No	78
37	Elm Street	Hershey Street	Emerald Street	Hingham	No	No	68
38	Brewster Road			Hingham	No	No	61
39	East Street	Near Cohasset Town Line		Hingham	No	No	74
40	Elmore Road			Hingham	No	No	65
41	Hayes Road			Hingham	No	No	69
42	Manomet Avenue			Hull	No	No	68
43	Whitehead Avenue	Nantasket Road	Nantasket Avenue	Hull	No	No	68
44	Sunset Avenue			Hull	No	No	78
45	T Street			Hull	No	No	75

**Table No. 7-6
 Estimated Improvement Costs - Phase III**

Priority 1							
Item No.	Location	From	To	Town	Water Main Diameter (in.)	Length (LF)	Estimated Cost
30	George Washington Boulevard			Hingham	12	2,360	\$531,000
31	East Gate Lane			Hingham	12	1,380	\$259,000
32	Beal Street	Lincoln Street	Tuckers Lane	Hingham	12	2,500	\$540,000
33	Rockwood Road	East Street	Ledgewood Circle	Hingham	8	2,970	\$483,000
	Ledgewood Circle			Hingham	8	410	\$118,000
34	Dighton Street			Hull	8	700	\$114,000

Table No. 7-6 (Continued)
Estimated Improvement Costs - Phase III

Priority 2							
Item No.	Location	From	To	Town	Water Main Diameter (in.)	Length (LF)	Estimated Cost
35	Bradford Road			Hingham	8	540	\$88,000
36	Eldridge Court	Green Street	Water Street	Hingham	8	300	\$87,000
37	Elm Street	Hershey Street	Emerald Street	Hingham	8	800	\$130,000
38	Brewster Road			Hingham	8	2,500	\$516,000
39	East Street	Cohasset Town Line		Hingham	8	650	\$155,000
40	Elmore Road			Hingham	8	730	\$151,000
41	Hayes Road			Hingham	8	420	\$121,000
42	Manomet Avenue			Hull	8	5,400	\$878,000
43	Whitehead Avenue	Nantasket Road	Nantasket Avenue	Hull	8	2,070	\$337,000
44	Sunset Avenue			Hull	8	1,400	\$228,000
45	T Street			Hull	8	840	\$137,000
Total Estimated Phase III – Priority 1 and 2 Cost:							\$4,873,000

Table No. 7-7 Prioritization of Improvements and Estimated Improvement Costs-Phase III – Priority 3							
Hingham							
Item No.	Location	From	To	Asset Management Rating	Water Main Diameter (in)	Length (LF)	Estimated Cost
1	Off South Street	Opposite Cresswell Lane		80	8	200	\$ 58,000
2	Crow Point Lane	Lincoln Street	End	80	8	425	\$123,000
3	Downer Avenue	Lincoln Street	Crow Point Lane	78	8	1,000	\$163,000
4	Bayberry Road	Bradley Woods Drive	Sycamore Lane	76	8	500	\$144,000
5	Meadow Road	Rockland Street	Cliff Road	76	8	500	\$144,000
	Cliff Road	Meadow Road	End	74	8	700	\$114,000
6	Causeway Road	Downer Avenue	End	75	8	650	\$106,000
7	Crowes Lane	Hershey Street	End	75	8	700	\$114,000
8	Beach Road	Wompatuck Road	End	74	8	700	\$114,000
	Beach Lane	Wompatuck Road	End	74	8	250	\$ 72,000
9	Rhodes Place			74	8	550	\$159,000
10	Forget Me Not Lane			74	8	300	\$ 87,000
11	Alden Road			74	8	330	\$ 95,000
12	Bradley Hill Road			61-74	8	1050	\$171,000

Table No. 7-7 (Continued)							
Prioritization of Improvements and Estimated Improvement Costs-Phase III – Priority 3							
Hull							
Item No.	Location	From	To	Asset Management Rating	Water Main Diameter (in)	Length (LF)	Estimated Cost
1	Wharf Avenue	8-inch DI main	End	83	8	125	\$ 36,000
2	Newport Road	Nantasket Road	Warfield Avenue	83	8	2,350	\$382,000
3	C Street	Central Avenue	End of 4-inch	83	8	1,150	\$187,000
4	B Street			83	8	1,800	\$293,000
5	D Street			81	8	2,050	\$334,000
6	G Street	Central Avenue	Unlined Cast Iron	81	8	350	\$101,000
	G Street	Cadish Avenue	Ductile Iron	76	8	350	\$101,000
	G Street	Nantasket Avenue	Beach Avenue	70	8	650	\$106,000
7	Harold Place			80	8	215	\$ 62,000
8	Alden Street			80	8	400	\$115,000
9	Nantasket Road	8-inch	Clifton Avenue	78	8	550	\$ 90,000
10	Warren Street	Nantasket Avenue	Manomet Avenue	78	8	800	\$130,000
11	Lewis Street	Nantasket Avenue	Beach Avenue	63-78	8	900	\$147,000



**Water Distribution System
Hingham/Hull, Massachusetts
Aquarion Water Company**



TATA & HOWARD
Water and Wastewater Consultants

MARCH 2011

Approximate Scale: 1" = 1,500'

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1390	P-207	8	Ductile Iron	1990	0	0	FALSE
1392	P-238	24	Ductile Iron	1995	0	0	FALSE
1393	P-239	12	Factory Lined Cast Iron	1973	2.2	0	FALSE
1394	P-240	8	Factory Lined Cast Iron	1973	0	0	FALSE
1395	P-242	8	Ductile Iron	1984	0	0	FALSE
1396	P-249	12	Unlined Cast Iron	1910	0	0	FALSE
1397	P-251	8	Factory Lined Cast Iron	1965	0	0	TRUE
1398	P-252	8	Ductile Iron	1987	0	1	FALSE
1399	Charles St	8	Factory Lined Cast Iron	1973	0.7	0	FALSE
1400	P-254	8	Factory Lined Cast Iron	1973	0.7	0	FALSE
1401	P-255	8	Factory Lined Cast Iron	1981	0	0	FALSE
1402	South Pleasant St	24	Ductile Iron	1995	0	1	FALSE
1403	P-259	8	Factory Lined Cast Iron	1962	0	0	FALSE
1405	P-262	8	Asbestos Cement	1951	0	0	TRUE
1406	P-263	8	Asbestos Cement	1951	0	0	TRUE
1407	P-264	8	Asbestos Cement	1951	0	0	TRUE
1408	P-265	8	Factory Lined Cast Iron	1961	0	0	FALSE
1409	P-266	8	Ductile Iron	1978	0	0	FALSE
1411	P-268	8	Ductile Iron	1973	0	0	TRUE
1412	P-269	6	Unlined Cast Iron	1951	0.9	0	TRUE
1413	P-270	6	Unlined Cast Iron	1939	0	0	TRUE
1414	P-271	6	Unlined Cast Iron	1939	0	0	TRUE
1415	P-273	6	Asbestos Cement	1950	0	0	FALSE
1416	P-274	6	Asbestos Cement	1950	0	0	FALSE
1418	P-277	24	Ductile Iron	1995	0	0	TRUE
1419	P-278	8	Asbestos Cement	1951	0	0	TRUE
1420	P-279	24	Ductile Iron	1995	0	0	TRUE
1421	P-281	20	Unlined Cast Iron	1910	0.6	0	TRUE
1423	P-283	8	Asbestos Cement	1956	0	0	FALSE
1424	P-284	8	Unlined Cast Iron	1957	0	0	FALSE
1425	P-285	8	Factory Lined Cast Iron	1962	0	0	FALSE
1426	P-288	6	Factory Lined Cast Iron	1963	0	0	FALSE
1427	P-289	8	Ductile Iron	1987	0	0	FALSE
1428	P-290	8	Factory Lined Cast Iron	1962	0	0	FALSE
1429	P-291	8	Factory Lined Cast Iron	1976	0	0	FALSE
1430	P-292	6	Unlined Cast Iron	1951	0.9	0	TRUE
1431	P-293	6	Unlined Cast Iron	1951	0.9	0	TRUE
1432	P-294	6	Unlined Cast Iron	1951	0.9	0	TRUE
1433	P-295	8	Asbestos Cement	1951	0	0	FALSE
1434	P-296	8	Asbestos Cement	1951	0	0	TRUE
1435	P-297	8	Asbestos Cement	1951	0	0	TRUE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1436	P-299	8	Ductile Iron	1987	1.5	0	TRUE
1437	P-300	8	Ductile Iron	1987	0	1	TRUE
1438	P-301	6	Unlined Cast Iron	1955	0	0	TRUE
1439	P-302	6	Unlined Cast Iron	1955	0.9	0	TRUE
1440	P-303	6	Unlined Cast Iron	1955	0.9	0	TRUE
1441	P-304	6	Unlined Cast Iron	1955	0.9	0	TRUE
1442	P-305	6	Factory Lined Cast Iron	1962	1.7	0	TRUE
1443	P-306	6	Unlined Cast Iron	1955	1.55	0	TRUE
1444	Berkley Rd	8	Ductile Iron	1974	0	1	TRUE
1445	P-308	8	Factory Lined Cast Iron	1974	0	0	TRUE
1446	P-309	8	Ductile Iron	1974	0	1	FALSE
1447	P-310	8	Ductile Iron	1974	0	0	FALSE
1448	P-311	8	Ductile Iron	1974	0	0	FALSE
1449	P-313	8	Asbestos Cement	1951	0	0	TRUE
1450	P-314	8	Factory Lined Cast Iron	1960	0	0	TRUE
1451	P-316	8	Factory Lined Cast Iron	1960	0	0	TRUE
1452	P-318	6	Factory Lined Cast Iron	1963	0	0	TRUE
1453	P-319	8	Factory Lined Cast Iron	1963	0	0	TRUE
1454	High St	8	Asbestos Cement	1951	0	0	TRUE
1455	P-321	12	Ductile Iron	1987	0	0	TRUE
1456	P-322	8	Asbestos Cement	1952	0	0	TRUE
1457	P-323	8	Ductile Iron	1983	0	0	TRUE
1458	P-324	8	Asbestos Cement	1952	0	0	TRUE
1459	P-325	8	Asbestos Cement	1951	0	0	FALSE
1461	P-327	8	Factory Lined Cast Iron	1964	0	0	TRUE
1462	P-330	8	Factory Lined Cast Iron	1974	0	0	FALSE
1463	P-331	8	Ductile Iron	1975	0	0	FALSE
1464	P-332	12	Factory Lined Cast Iron	1970	0	0	FALSE
1466	P-334	8	Ductile Iron	1976	0	0	FALSE
1467	French St	12	Factory Lined Cast Iron	1970	0.4	0	FALSE
1468	P-337	8	Ductile Iron	1976	0	0	FALSE
1469	P-338	8	Ductile Iron	1976	0	0	FALSE
1470	P-339	8	Ductile Iron	1976	0	0	FALSE
1471	P-340	8	Ductile Iron	1976	0	0	FALSE
1472	P-341	8	Ductile Iron	1989	0	0	FALSE
1473	P-342	8	Ductile Iron	1989	0	0	FALSE
1474	P-343	8	Ductile Iron	1989	0	0	FALSE
1475	P-344	12	Ductile Iron	1981	0.4	0	FALSE
1476	P-345	8	Ductile Iron	1983	0	1	FALSE
1477	P-346	8	Ductile Iron	1985	0	0	FALSE
1478	P-347	8	Ductile Iron	1985	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1479	P-348	8	Ductile Iron	1976	0	0	FALSE
1480	Hobart St	8	Ductile Iron	1976	0	1	FALSE
1481	P-350	8	Factory Lined Cast Iron	1975	0	0	FALSE
1482	P-351	8	Factory Lined Cast Iron	1975	0	0	FALSE
1483	P-352	6	Factory Lined Cast Iron	1962	0	0	FALSE
1484	P-353	8	Factory Lined Cast Iron	1967	0	0	TRUE
1485	P-354	8	Factory Lined Cast Iron	1967	0	1	FALSE
1486	P-355	8	Factory Lined Cast Iron	1967	0	0	FALSE
1487	P-356	8	Ductile Iron	1977	0	1	FALSE
1489	P-358	8	Factory Lined Cast Iron	1969	0	1	TRUE
1490	P-359	6	Factory Lined Cast Iron	1970	0	1	FALSE
1491	P-360	8	Ductile Iron	1977	0	1	FALSE
1492	P-361	8	Ductile Iron	1977	0	1	FALSE
1493	P-362	8	Ductile Iron	1977	0	1	FALSE
1494	P-363	20	Ductile Iron	1995	0	0	FALSE
1496	Free St	8	Asbestos Cement	1960	3.7	0	FALSE
1498	Union St	8	Asbestos Cement	1965	2.8	0	FALSE
1499	P-368	8	Ductile Iron	1981	0	0	FALSE
1500	P-369	6	Ductile Iron	1981	0	0	FALSE
1501	P-370	8	Ductile Iron	1981	0	0	FALSE
1502	P-371	8	Ductile Iron	1981	0	0	FALSE
1503	P-372	8	Ductile Iron	1981	0	0	FALSE
1504	P-373	8	Ductile Iron	1981	0	1	FALSE
1505	P-374	8	Asbestos Cement	1965	2.8	0	FALSE
1506	P-375	8	Ductile Iron	1965	0	0	FALSE
1507	P-378	8	Factory Lined Cast Iron	1966	0	1	FALSE
1508	P-379	8	Factory Lined Cast Iron	1966	0	0	FALSE
1509	Union Street	20	Prestressed Concrete	1952	0	0	FALSE
1510	P-381	6	Unlined Cast Iron	1923	0	0	FALSE
1511	P-386	8	Factory Lined Cast Iron	1966	0	0	FALSE
1512	Middle St	20	Prestressed Concrete	1952	0	0	FALSE
1513	P-387	20	Prestressed Concrete	1952	0	0	FALSE
1514	P-390	6	Unlined Cast Iron	1916	0	0	FALSE
1515	P-391	6	Unlined Cast Iron	1923	0	0	FALSE
1517	P-393	8	Asbestos Cement	1956	0.9	0	FALSE
1518	P-395	6	Asbestos Cement	1953	2	0	FALSE
1519	P-397	6	Asbestos Cement	1953	0	0	FALSE
1520	P-399	8	Asbestos Cement	1956	0.9	0	FALSE
1522	Main Str	20	Unlined Cast Iron	1910	0.6	0	FALSE
1523	P-403	10	Unlined Cast Iron	1918	0	0	FALSE
1524	P-406	20	Unlined Cast Iron	1910	0.6	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1525	P-407	20	Unlined Cast Iron	1910	0	0	FALSE
1527	Short Street	20	Unlined Cast Iron	1910	0	0	FALSE
1528	P-410	12	Unlined Cast Iron	1948	0	0	FALSE
1529	P-412	8	Ductile Iron	1985	0	0	FALSE
1530	P-413	8	Ductile Iron	1985	0	0	FALSE
1531	P-414	6	Unlined Cast Iron	1913	0	0	FALSE
1532	P-415	6	Unlined Cast Iron	1913	0	0	FALSE
1533	P-417	8	Unlined Cast Iron	1927	0	0	FALSE
1534	P-418	6	Unlined Cast Iron	1937	0	0	FALSE
1535	P-419	8	Ductile Iron	1985	0	0	FALSE
1536	P-421	20	Unlined Cast Iron	1910	0.6	0	TRUE
1537	P-422	6	Unlined Cast Iron	1939	0	0	TRUE
1541	Hersey Street	6	Unlined Cast Iron	1899	0	0	TRUE
1542	P-427	6	Unlined Cast Iron	1899	0	0	TRUE
1543	P-428	20	Unlined Cast Iron	1910	0.6	0	TRUE
1544	P-429	6	Unlined Cast Iron	1927	0	0	TRUE
1545	P-430	6	Unlined Cast Iron	1931	0	0	TRUE
1547	P-432	8	Ductile Iron	1983	0	0	FALSE
1548	P-433	6	Unlined Cast Iron	1899	0	0	TRUE
1549	P-435	6	Unlined Cast Iron	1937	0	0	FALSE
1552	P-438	6	Asbestos Cement	1955	0	0	TRUE
1553	P-439	20	Unlined Cast Iron	1910	0.6	0	TRUE
1554	P-440	6	Unlined Cast Iron	1939	0	0	TRUE
1555	P-441	20	Unlined Cast Iron	1910	0.6	0	TRUE
1556	P-442	20	Unlined Cast Iron	1910	0	0	FALSE
1558	P-444	6	Unlined Cast Iron	1957	1.6	0	FALSE
1559	East St.	20	Unlined Cast Iron	1910	0	0	FALSE
1560	Leavitt St	8	Asbestos Cement	1956	0.4	0	FALSE
1561	P-447	8	Factory Lined Cast Iron	1968	0	0	FALSE
1562	P-448	8	Asbestos Cement	1956	0.4	0	FALSE
1563	P-449	8	Asbestos Cement	1956	0.4	0	FALSE
1564	P-450	8	Ductile Iron	1986	0	0	FALSE
1565	P-451	8	Factory Lined Cast Iron	1986	0	0	FALSE
1567	P-453	8	Ductile Iron	1986	0	0	FALSE
1568	P-454	8	Ductile Iron	1986	0	0	FALSE
1570	P-458	8	Ductile Iron	1980	0	0	FALSE
1571	P-459	8	Ductile Iron	1975	0.4	1	FALSE
1572	P-460	8	Ductile Iron	1996	0	0	FALSE
1573	P-461	8	Ductile Iron	1985	0.4	0	FALSE
1574	P-462	8	Ductile Iron	1975	0	0	FALSE
1575	P-463	8	Ductile Iron	1975	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1576	P-464	8	Ductile Iron	1975	0	0	FALSE
1577	P-465	8	Ductile Iron	1991	0	0	FALSE
1578	P-466	8	Ductile Iron	1991	0.4	0	FALSE
1579	P-467	8	Ductile Iron	1991	0	0	FALSE
1580	P-468	8	Ductile Iron	1985	0.4	0	FALSE
1581	New Bridge St	8	Ductile Iron	1991	0.4	1	FALSE
1582	P-470	8	Unlined Cast Iron	1899	0	0	FALSE
1583	Fort Hill St	8	Unlined Cast Iron	1899	0	0	FALSE
1584	Fresh River Ave	8	Unlined Cast Iron	1899	0.7	0	FALSE
1586	P-474	8	Unlined Cast Iron	1917	1.5	0	FALSE
1587	P-475	8	Ductile Iron	1995	0	0	FALSE
1588	P-476	8	Ductile Iron	1992	0	0	FALSE
1589	P-477	8	Ductile Iron	1992	0	0	FALSE
1590	P-478	8	Ductile Iron	1992	0	0	FALSE
1591	P-479	8	Ductile Iron	1992	0	0	FALSE
1592	P-480	8	Ductile Iron	1992	0	0	FALSE
1593	P-481	8	Ductile Iron	1992	0	0	FALSE
1594	P-483	8	Ductile Iron	1992	0	0	FALSE
1595	P-484	8	Ductile Iron	1992	0	0	FALSE
1596	P-485	8	Ductile Iron	1992	0	0	FALSE
1597	P-486	8	Ductile Iron	1992	0	1	FALSE
1598	P-487	8	Ductile Iron	1992	0	1	FALSE
1599	P-488	8	Ductile Iron	1992	0	0	FALSE
1600	P-489	8	Ductile Iron	1992	0	0	FALSE
1601	P-490	8	Ductile Iron	1992	0	0	FALSE
1602	P-491	8	Unlined Cast Iron	1899	0	0	FALSE
1604	P-494	8	Ductile Iron	1985	0	0	FALSE
1608	P-500	8	Ductile Iron	1985	0	1	FALSE
1609	P-501	8	Ductile Iron	1985	0	0	FALSE
1610	P-502	12	Factory Lined Cast Iron	1962	0.2	0	FALSE
1612	P-505	6	Ductile Iron	1983	0	0	FALSE
1613	P-506	8	Unlined Cast Iron	1917	2.1	0	FALSE
1614	P-507	8	Unlined Cast Iron	1917	2.1	0	FALSE
1615	P-509	8	Factory Lined Cast Iron	1965	0	0	FALSE
1616	P-510	8	Ductile Iron	1985	0	0	FALSE
1617	P-511	8	Ductile Iron	1985	0	0	FALSE
1618	P-512	6	Factory Lined Cast Iron	1962	0	1	FALSE
1619	P-513	8	Ductile Iron	1985	0	0	FALSE
1620	P-514	8	Unlined Cast Iron	1950	1.26	0	FALSE
1621	South Street	8	Asbestos Cement	1956	0	0	FALSE
1622	P-516	6	Unlined Cast Iron	1933	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1623	P-518	8	Unlined Cast Iron	1939	7.5	0	FALSE
1625	P-521	6	Unlined Cast Iron	1895	6.5	0	FALSE
1626	P-522	8	Unlined Cast Iron	1933	5	0	FALSE
1627	North Street	10	Unlined Cast Iron	1917	0.5	0	FALSE
1628	P-524	10	Unlined Cast Iron	1917	0.5	0	FALSE
1629	P-525	8	Unlined Cast Iron	1917	0	0	FALSE
1630	P-526	8	Ductile Iron	1985	0	0	FALSE
1631	P-527	8	Unlined Cast Iron	1933	5	0	FALSE
1632	P-528	12	Unlined Cast Iron	1923	9.2	0	FALSE
1633	P-529	6	Unlined Cast Iron	1901	0.9	0	FALSE
1634	P-530	8	Unlined Cast Iron	1921	0	0	FALSE
1635	P-531	8	Unlined Cast Iron	1921	0	0	FALSE
1638	P-535	12	Ductile Iron	1985	1.4	0	TRUE
1641	Beal St	6	Unlined Cast Iron	1916	0	0	TRUE
1642	P-540	6	Asbestos Cement	1953	0	0	TRUE
1643	P-542	12	Ductile Iron	1986	1.4	0	TRUE
1644	P-543	8	Asbestos Cement	1954	4.2	0	TRUE
1645	P-544	12	Ductile Iron	1986	0	0	TRUE
1646	P-546	8	Factory Lined Cast Iron	1971	0.8	0	TRUE
1647	P-547	8	Factory Lined Cast Iron	1971	0.8	0	TRUE
1648	P-548	6	Unlined Cast Iron	1916	0	0	TRUE
1649	P-549	6	Unlined Cast Iron	1916	0	0	TRUE
1650	P-550	8	Ductile Iron	1978	0	0	TRUE
1651	P-551	8	Ductile Iron	1978	0	0	TRUE
1652	P-552	8	Ductile Iron	1978	0	0	TRUE
1653	P-553	12	Factory Lined Cast Iron	1971	0	0	TRUE
1654	P-554	8	Ductile Iron	1991	0	0	TRUE
1655	P-556	8	Ductile Iron	1991	0	0	TRUE
1656	P-557	8	Ductile Iron	1991	0	0	TRUE
1657	P-558	8	Ductile Iron	1991	0	0	TRUE
1659	P-561	8	Ductile Iron	1991	0	0	TRUE
1660	P-562	8	Ductile Iron	1991	0	0	FALSE
1661	P-563	8	Ductile Iron	1991	0	0	TRUE
1662	P-564	8	Ductile Iron	1975	34.8	0	TRUE
1663	P-566	12	Ductile Iron	1986	0	0	TRUE
1664	P-569	8	Factory Lined Cast Iron	1975	0	0	TRUE
1667	P-573	8	Ductile Iron	1978	0	0	TRUE
1668	P-574	8	Ductile Iron	1978	0	0	TRUE
1670	P-576	8	Ductile Iron	1979	0	0	TRUE
1674	P-580	8	Ductile Iron	1985	0	0	TRUE
1676	P-582	8	Asbestos Cement	1952	9.4	0	TRUE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1678	P-586	6	Unlined Cast Iron	1939	0	0	FALSE
1679	P-587	6	Unlined Cast Iron	1939	1.6	0	FALSE
1680	P-589	8	Unlined Cast Iron	1917	1.8	0	FALSE
1681	P-590	6	Unlined Cast Iron	1939	0	0	FALSE
1682	P-591	6	Unlined Cast Iron	1939	0	0	FALSE
1683	P-592	8	Asbestos Cement	1956	0	0	FALSE
1684	P-593	6	Asbestos Cement	1950	0	0	FALSE
1685	P-594	6	Asbestos Cement	1949	1.7	0	FALSE
1686	P-595	6	Asbestos Cement	1949	1.7	0	FALSE
1687	P-596	6	Asbestos Cement	1956	0	0	FALSE
1688	P-597	6	Asbestos Cement	1956	0	0	FALSE
1689	P-598	6	Unlined Cast Iron	1940	0	0	FALSE
1690	P-599	6	Asbestos Cement	1950	2.2	0	FALSE
1691	P-602	8	Unlined Cast Iron	1917	0	0	FALSE
1692	P-604	8	Asbestos Cement	1956	0	0	FALSE
1693	Lincoln Street	6	Unlined Cast Iron	1910	0.4	0	FALSE
1694	P-607	6	Asbestos Cement	1948	0	0	FALSE
1695	P-608	6	Asbestos Cement	1948	0	0	FALSE
1696	P-609	6	Unlined Cast Iron	1910	0.4	0	FALSE
1697	P-610	8	Unlined Cast Iron	1921	0	0	FALSE
1698	P-611	12	Unlined Cast Iron	1922	0	0	FALSE
1700	P-613	8	Unlined Cast Iron	1921	0	0	FALSE
1702	P-615	6	Unlined Cast Iron	1917	0	0	FALSE
1704	P-617	6	Factory Lined Cast Iron	1961	1.7	0	FALSE
1705	P-618	6	Factory Lined Cast Iron	1961	1.7	0	FALSE
1707	P-620	12	Unlined Cast Iron	1948	1	0	FALSE
1708	P-621	6	Factory Lined Cast Iron	1961	1.7	0	FALSE
1709	P-623	6	Unlined Cast Iron	1909	0.9	0	FALSE
1710	P-624	8	Unlined Cast Iron	1928	0	0	FALSE
1711	P-625	12	Unlined Cast Iron	1948	1	0	FALSE
1712	P-626	6	Unlined Cast Iron	1941	6.1	0	FALSE
1713	P-627	12	Unlined Cast Iron	1948	1	0	FALSE
1714	P-628	8	Ductile Iron	1993	0	0	FALSE
1715	P-629	12	Unlined Cast Iron	1948	1	0	FALSE
1716	P-630	6	Asbestos Cement	1951	0	0	FALSE
1717	P-631	12	Unlined Cast Iron	1948	1	0	FALSE
1718	P-633	12	Unlined Cast Iron	1948	1	0	FALSE
1719	P-634	12	Unlined Cast Iron	1917	1.4	0	FALSE
1720	P-635	12	Unlined Cast Iron	1917	1.4	0	FALSE
1721	P-637	6	Unlined Cast Iron	1916	0	0	FALSE
1722	P-638	6	Unlined Cast Iron	1917	10	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1724	P-640	12	Unlined Cast Iron	1959	0	0	FALSE
1725	Summer Street	12	Unlined Cast Iron	1917	1.4	0	FALSE
1726	P-642	8	Ductile Iron	1980	0	0	FALSE
1728	P-644	12	Unlined Cast Iron	1917	1.4	0	FALSE
1729	P-645	6	Ductile Iron	1976	0	0	FALSE
1730	P-646	6	Asbestos Cement	1957	0	0	FALSE
1731	P-647	20	Unlined Cast Iron	1910	0	0	FALSE
1732	P-648	20	Unlined Cast Iron	1910	0	0	FALSE
1733	P-649	8	Factory Lined Cast Iron	1972	0	0	FALSE
1735	P-651	14	Unlined Cast Iron	1903	0	0	FALSE
1736	P-652	6	Unlined Cast Iron	1941	0.3	0	FALSE
1737	P-653	6	Factory Lined Cast Iron	1960	0	0	FALSE
1738	P-654	14	Unlined Cast Iron	1903	0	1	FALSE
1739	P-655	20	Unlined Cast Iron	1910	0	0	FALSE
1740	P-656	20	Unlined Cast Iron	1910	1.1	0	FALSE
1741	Kilby St	20	Prestressed Concrete	1954	0	0	FALSE
1742	P-659	6	Unlined Cast Iron	1941	0.3	0	FALSE
1743	Andrews Isle	6	Factory Lined Cast Iron	1969	0	0	FALSE
1748	P-667	12	Unlined Cast Iron	1917	1.4	0	FALSE
1749	P-669	6	Asbestos Cement	1949	0	0	FALSE
1750	P-670	6	Unlined Cast Iron	1957	0	0	FALSE
1751	P-671	8	Factory Lined Cast Iron	1963	1.5	0	FALSE
1752	P-672	8	Factory Lined Cast Iron	1963	1.5	0	FALSE
1753	P-673	6	Asbestos Cement	1950	2.2	0	FALSE
1754	P-674	6	Unlined Cast Iron	1957	0	0	FALSE
1755	P-675	8	Ductile Iron	1991	0	0	FALSE
1757	P-680	12	Asbestos Cement	1957	0	0	FALSE
1758	P-681	8	Asbestos Cement	1957	1	0	FALSE
1759	P-682	8	Unlined Cast Iron	1959	1	0	FALSE
1760	East Street	6	Unlined Cast Iron	1903	0	1	FALSE
1761	P-684	20	Prestressed Concrete	1963	0	1	FALSE
1762	P-685	8	Factory Lined Cast Iron	1963	0	1	FALSE
1763	Summer St	6	Unlined Cast Iron	1903	0	1	FALSE
1764	P-687	8	Ductile Iron	1991	0	1	FALSE
1765	P-689	20	Prestressed Concrete	1963	0	1	FALSE
1766	P-690	6	Asbestos Cement	1951	0	1	FALSE
1767	P-691	6	Asbestos Cement	1951	0	0	FALSE
1768	P-692	20	Prestressed Concrete	1963	0	1	FALSE
1769	Chief Justice Cushing Hwy	8	Factory Lined Cast Iron	1967	0	0	FALSE
1771	East Str	6	Unlined Cast Iron	1908	0	1	FALSE
1772	P-696	6	Unlined Cast Iron	1908	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1773	P-697	6	Unlined Cast Iron	1908	0.2	0	FALSE
1776	P-704	8	Factory Lined Cast Iron	1972	0	0	TRUE
1777	P-705	8	Factory Lined Cast Iron	1971	5.7	0	TRUE
1778	P-706	8	Factory Lined Cast Iron	1972	0	0	TRUE
1779	P-707	6	Asbestos Cement	1945	0	0	TRUE
1780	P-708	6	Asbestos Cement	1945	0	0	TRUE
1781	P-709	6	Asbestos Cement	1945	0	0	TRUE
1782	P-710	6	Asbestos Cement	1945	2.2	0	TRUE
1783	P-711	8	Asbestos Cement	1945	0	0	TRUE
1784	P-712	6	Asbestos Cement	1945	0	0	TRUE
1785	P-713	8	Asbestos Cement	1945	0	0	TRUE
1786	P-714	8	Asbestos Cement	1945	0	0	TRUE
1787	Lincoln Str	8	Unlined Cast Iron	1941	2.15	0	FALSE
1788	P-716	8	Ductile Iron	1994	0	0	FALSE
1789	P-717	8	Ductile Iron	1994	0	0	FALSE
1790	P-718	8	Ductile Iron	1994	0	0	FALSE
1791	P-719	8	Ductile Iron	1994	0	0	FALSE
1793	P-721	8	Ductile Iron	1994	0	0	FALSE
1794	P-722	12	Ductile Iron	1994	0	1	FALSE
1795	P-723	12	Ductile Iron	1994	0	0	FALSE
1796	P-724	12	Ductile Iron	1994	0	0	FALSE
1797	P-725	6	Unlined Cast Iron	1910	1.2	0	FALSE
1798	P-726	6	Unlined Cast Iron	1910	11.7	0	FALSE
1799	P-727	8	Unlined Cast Iron	1941	0	0	FALSE
1801	P-729	12	Unlined Cast Iron	1921	0.7	0	FALSE
1802	P-730	12	Unlined Cast Iron	1916	0.7	0	FALSE
1803	P-732	8	Unlined Cast Iron	1922	0	0	FALSE
1804	P-733	12	Ductile Iron	1985	0	0	FALSE
1805	P-736	8	Asbestos Cement	1952	0	0	FALSE
1806	P-738	8	Asbestos Cement	1952	0	0	FALSE
1807	P-739	12	Unlined Cast Iron	1921	0.7	0	FALSE
1809	Otis Str	12	Unlined Cast Iron	1921	0.7	0	FALSE
1810	P-742	6	Unlined Cast Iron	1935	0	0	FALSE
1811	P-743	6	Asbestos Cement	1947	1.6	0	FALSE
1812	P-744	6	Factory Lined Cast Iron	1960	0	0	FALSE
1813	Downer Ave	6	Unlined Cast Iron	1910	1.2	0	FALSE
1814	P-746	8	Asbestos Cement	1957	1.7	0	FALSE
1815	P-747	6	Unlined Cast Iron	1910	1.2	0	FALSE
1816	P-748	8	Unlined Cast Iron	1925	0.9	0	FALSE
1817	P-749	8	Unlined Cast Iron	1932	0	0	FALSE
1818	P-750	8	Unlined Cast Iron	1932	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1819	P-751	8	Unlined Cast Iron	1932	0	0	FALSE
1820	P-752	6	Asbestos Cement	1955	0	0	FALSE
1821	P-753	8	Unlined Cast Iron	1932	0	0	FALSE
1823	P-755	6	Unlined Cast Iron	1937	0	0	FALSE
1824	P-756	6	Unlined Cast Iron	1937	0	0	FALSE
1825	P-757	6	Unlined Cast Iron	1937	0	0	FALSE
1826	P-758	6	Unlined Cast Iron	1937	0	0	FALSE
1828	P-761	6	Asbestos Cement	1953	1.7	0	FALSE
1829	P-762	6	Asbestos Cement	1955	1.7	0	FALSE
1830	P-764	6	Asbestos Cement	1955	0.6	0	FALSE
1831	P-765	6	Asbestos Cement	1953	0	0	FALSE
1832	P-766	8	Factory Lined Cast Iron	1971	0	0	FALSE
1833	P-767	6	Asbestos Cement	1952	0	0	FALSE
1835	P-769	6	Asbestos Cement	1955	0	1	FALSE
1836	P-770	6	Asbestos Cement	1955	0	1	FALSE
1837	P-771	6	Asbestos Cement	1955	1.1	1	FALSE
1838	P-772	6	Asbestos Cement	1952	0	0	FALSE
1841	P-775	8	Unlined Cast Iron	1905	0	0	FALSE
1843	P-778	8	Factory Lined Cast Iron	1968	0	0	FALSE
1844	P-779	6	Asbestos Cement	1946	0	0	FALSE
1845	P-780	8	Unlined Cast Iron	1898	0	0	FALSE
1848	P-783	6	Unlined Cast Iron	1922	0	0	FALSE
1849	P-784	6	Unlined Cast Iron	1922	0.8	0	FALSE
1850	P-785	6	Unlined Cast Iron	1922	0.8	0	FALSE
1851	P-787	8	Ductile Iron	1989	0	0	FALSE
1852	P-789	8	Ductile Iron	1989	0	0	FALSE
1853	P-790	10	Unlined Cast Iron	1917	0.4	0	FALSE
1854	Downer Avenue	10	Unlined Cast Iron	1921	0.4	0	FALSE
1855	P-792	8	Ductile Iron	1985	0	0	FALSE
1856	P-793	6	Unlined Cast Iron	1917	2.3	0	FALSE
1858	P-795	8	Unlined Cast Iron	1916	0	0	FALSE
1861	P-799	6	Factory Lined Cast Iron	1960	0	0	FALSE
1862	George Washington Blvd	8	Factory Lined Cast Iron	1973	1.2	1	FALSE
1863	P-802	8	Asbestos Cement	1953	0	0	FALSE
1864	P-803	8	Unlined Cast Iron	1957	0.4	0	FALSE
1865	P-804	6	Unlined Cast Iron	1958	0.9	0	FALSE
1866	P-805	6	Asbestos Cement	1947	0	0	FALSE
1867	P-806	6	Asbestos Cement	1947	0	0	FALSE
1868	P-807	6	Asbestos Cement	1947	0	0	FALSE
1869	P-808	6	Asbestos Cement	1947	0	0	FALSE
1870	P-809	6	Asbestos Cement	1947	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1871	P-810	8	Unlined Cast Iron	1957	0.4	0	FALSE
1872	P-811	8	Unlined Cast Iron	1957	0.4	0	FALSE
1873	P-813	8	Asbestos Cement	1955	0	1	FALSE
1874	P-814	6	Asbestos Cement	1955	0.8	0	FALSE
1875	P-815	8	Unlined Cast Iron	1957	0.4	0	FALSE
1876	P-816	8	Unlined Cast Iron	1957	0.4	0	FALSE
1877	P-817	8	Unlined Cast Iron	1957	0	0	FALSE
1878	P-818	8	Unlined Cast Iron	1957	0	0	FALSE
1879	P-821	8	Unlined Cast Iron	1957	0.4	0	FALSE
1882	P-824	20	Unlined Cast Iron	1910	0	0	FALSE
1883	P-825	16	Unlined Cast Iron	1917	0.4	1	FALSE
1884	P-826	12	Unlined Cast Iron	1891	0.3	1	FALSE
1885	P-827	6	Unlined Cast Iron	1899	0	0	FALSE
1886	P-828	8	Ductile Iron	1985	0.7	0	FALSE
1887	P-829	12	Unlined Cast Iron	1891	0.3	0	FALSE
1888	P-830	8	Ductile Iron	1985	0	0	FALSE
1889	Rockland Street	12	Unlined Cast Iron	1891	0.3	1	FALSE
1890	P-833	6	Asbestos Cement	1947	8.6	0	FALSE
1891	P-834	6	Ductile Iron	1996	0	0	FALSE
1892	P-835	6	Ductile Iron	1996	0	0	FALSE
1893	P-836	6	Ductile Iron	1996	0	0	FALSE
1894	P-837	6	Asbestos Cement	1947	2	0	FALSE
1895	P-838	6	Ductile Iron	1992	0	0	FALSE
1896	P-839	12	Unlined Cast Iron	1891	0.3	0	FALSE
1898	P-841	6	Unlined Cast Iron	1908	0.2	0	FALSE
1900	P-844	8	Factory Lined Cast Iron	1965	1.3	0	FALSE
1903	P-851	6	Ductile Iron	1981	0	0	FALSE
1904	P-853	8	Ductile Iron	1981	0.3	1	FALSE
1905	Surry Dr	8	Ductile Iron	1981	0.3	1	FALSE
1907	P-858	6	Unlined Cast Iron	1958	3	0	FALSE
1908	P-860	6	Asbestos Cement	1956	4.4	0	FALSE
1909	P-861	6	Factory Lined Cast Iron	1960	0	0	FALSE
1910	P-863	8	Factory Lined Cast Iron	1962	0	0	FALSE
1911	P-865	8	Factory Lined Cast Iron	1960	0	1	FALSE
1912	P-866	6	Unlined Cast Iron	1882	2.5	1	FALSE
1918	P-874	12	Ductile Iron	2010	0	0	FALSE
1919	P-875	10	Unlined Cast Iron	1923	1.2	0	FALSE
1920	P-876	6	Unlined Cast Iron	1921	0	0	FALSE
1921	P-877	12	Unlined Cast Iron	1923	1	0	FALSE
1923	P-879	12	Unlined Cast Iron	1923	2.2	0	FALSE
1924	P-880	6	Unlined Cast Iron	1959	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1926	P-882	6	Ductile Iron	1986	0	0	FALSE
1927	P-883	12	Unlined Cast Iron	1923	2.2	0	FALSE
1928	P-884	12	Ductile Iron	1986	0	0	FALSE
1929	P-885	8	Ductile Iron	1994	0	0	FALSE
1930	P-886	8	Ductile Iron	1986	0	0	FALSE
1931	P-887	8	Ductile Iron	1986	0	0	FALSE
1932	P-888	8	Ductile Iron	1986	0	1	FALSE
1933	P-889	12	Unlined Cast Iron	1923	2.2	0	FALSE
1935	P-891	6	Factory Lined Cast Iron	1960	0	0	FALSE
1937	P-893	20	Unlined Cast Iron	1924	0	1	FALSE
1938	P-894	6	Factory Lined Cast Iron	1960	0	0	FALSE
1940	P-896	20	Unlined Cast Iron	1924	0	0	FALSE
1941	P-897	8	Ductile Iron	1987	0	0	FALSE
1942	P-899	8	Ductile Iron	1989	0	0	FALSE
1943	P-900	8	Ductile Iron	1989	0	0	FALSE
1944	P-901	8	Ductile Iron	1989	0	1	FALSE
1945	P-902	8	Ductile Iron	1989	0	0	FALSE
1946	P-903	8	Ductile Iron	1989	0	0	FALSE
1947	P-905	20	Unlined Cast Iron	1924	0	0	FALSE
1948	P-906	20	Unlined Cast Iron	1924	0	0	FALSE
1949	P-907	6	Unlined Cast Iron	1923	0	1	FALSE
1950	P-908	8	Unlined Cast Iron	1925	0	0	FALSE
1953	P-916	8	Ductile Iron	1985	0	0	FALSE
1956	P-920	6	Asbestos Cement	1958	0	0	FALSE
1957	P-921	6	Asbestos Cement	1958	1.8	0	FALSE
1958	P-922	6	Asbestos Cement	1955	3	0	FALSE
1959	P-923	6	Asbestos Cement	1955	3	0	FALSE
1960	P-924	6	Asbestos Cement	1954	2	0	FALSE
1962	P-926	6	Asbestos Cement	1954	2	0	FALSE
1963	P-927	6	Asbestos Cement	1954	5.9	0	FALSE
1966	P-932	12	Unlined Cast Iron	1894	1.3	1	FALSE
1967	P-933	8	Unlined Cast Iron	1906	0.9	1	FALSE
1969	P-935	8	Unlined Cast Iron	1906	0.9	0	FALSE
1971	P-937	8	Unlined Cast Iron	1906	0	0	FALSE
1972	P-938	8	Asbestos Cement	1963	0	0	FALSE
1973	P-940	6	Unlined Cast Iron	1907	0	0	FALSE
1974	P-941	6	Unlined Cast Iron	1915	0	0	FALSE
1975	P-942	6	Unlined Cast Iron	1907	0	0	FALSE
1976	P-943	6	Unlined Cast Iron	1918	0	0	FALSE
1977	P-944	6	Unlined Cast Iron	1907	0	0	FALSE
1978	P-945	6	Unlined Cast Iron	1922	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
1979	P-946	6	Unlined Cast Iron	1907	0	0	FALSE
1980	P-947	6	Unlined Cast Iron	1950	0	0	FALSE
1981	P-948	6	Unlined Cast Iron	1907	0	0	FALSE
1982	P-949	6	Unlined Cast Iron	1907	0	0	FALSE
1984	P-951	6	Unlined Cast Iron	1915	2.6	0	FALSE
1985	P-952	6	Unlined Cast Iron	1908	0.9	0	FALSE
1986	P-953	6	Unlined Cast Iron	1908	0.9	0	FALSE
1987	P-954	6	Unlined Cast Iron	1915	0	0	FALSE
1988	P-955	6	Unlined Cast Iron	1915	1.1	0	FALSE
1989	P-956	6	Unlined Cast Iron	1908	0.9	0	FALSE
1991	P-958	6	Unlined Cast Iron	1906	0	0	FALSE
1992	P-959	6	Unlined Cast Iron	1906	1.1	0	FALSE
1993	P-960	6	Unlined Cast Iron	1893	0.9	0	FALSE
1995	P-962	6	Unlined Cast Iron	1893	0.9	1	FALSE
1996	P-963	12	Unlined Cast Iron	1894	1.3	1	FALSE
1997	P-964	12	Ductile Iron	1975	0	1	FALSE
1998	Nantasket Avenue	12	Unlined Cast Iron	1894	1.3	1	FALSE
1999	P-966	8	Unlined Cast Iron	1924	0	0	FALSE
2000	Hull Shore Drive	12	Ductile Iron	1975	0	1	FALSE
2001	P-968	6	Unlined Cast Iron	1923	0	1	FALSE
2002	P-969	6	Unlined Cast Iron	1915	4.8	1	FALSE
2003	P-970	6	Unlined Cast Iron	1923	2.5	1	FALSE
2004	P-971	4	Unlined Cast Iron	1916	0	1	FALSE
2005	P-972	6	Unlined Cast Iron	1916	1.2	0	FALSE
2006	P-973	6	Unlined Cast Iron	1916	1.2	0	FALSE
2007	P-974	6	Unlined Cast Iron	1916	1.2	0	FALSE
2010	P-978	6	Ductile Iron	1992	0	0	FALSE
2012	P-980	8	Unlined Cast Iron	1901	0.4	0	FALSE
2013	P-981	6	Ductile Iron	1992	0	0	FALSE
2014	P-982	6	Unlined Cast Iron	1916	0	0	FALSE
2016	P-984	12	Unlined Cast Iron	1894	1.3	1	FALSE
2019	P-988	8	Unlined Cast Iron	1901	0	1	FALSE
2020	P-989	8	Unlined Cast Iron	1901	0.4	1	FALSE
2021	P-990	6	Unlined Cast Iron	1915	1.4	1	FALSE
2023	P-992	6	Unlined Cast Iron	1915	1.4	1	FALSE
2025	P-995	12	Asbestos Cement	1956	0	1	FALSE
2026	P-996	12	Asbestos Cement	1956	0.3	1	FALSE
2027	P-997	6	Unlined Cast Iron	1922	0	1	FALSE
2028	P-998	12	Asbestos Cement	1956	0.3	1	FALSE
2029	P-999	6	Unlined Cast Iron	1915	17	1	FALSE
2030	P-1000	6	Unlined Cast Iron	1924	0	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2031	P-1001	6	Unlined Cast Iron	1915	17	1	FALSE
2032	P-1002	6	Unlined Cast Iron	1923	3.7	1	FALSE
2033	P-1003	6	Unlined Cast Iron	1923	3.7	1	FALSE
2034	P-1004	12	Asbestos Cement	1956	0.3	1	FALSE
2035	P-1005	6	Unlined Cast Iron	1923	0	1	FALSE
2036	P-1006	6	Unlined Cast Iron	1922	0	1	FALSE
2037	P-1007	12	Asbestos Cement	1956	0.3	1	FALSE
2038	P-1008	6	Unlined Cast Iron	1923	3.7	1	FALSE
2039	P-1009	6	Unlined Cast Iron	1922	2.4	1	FALSE
2040	P-1010	6	Unlined Cast Iron	1915	0	1	FALSE
2041	P-1011	6	Unlined Cast Iron	1915	1.4	1	FALSE
2042	P-1012	6	Unlined Cast Iron	1922	2.4	1	FALSE
2043	P-1013	6	Unlined Cast Iron	1928	0	1	FALSE
2044	P-1014	6	Unlined Cast Iron	1915	1.4	1	FALSE
2045	P-1015	6	Unlined Cast Iron	1922	2.4	1	FALSE
2046	P-1016	6	Unlined Cast Iron	1922	0	1	FALSE
2047	P-1017	6	Unlined Cast Iron	1915	1.4	1	FALSE
2048	P-1018	6	Unlined Cast Iron	1922	2.4	1	FALSE
2049	P-1019	6	Unlined Cast Iron	1915	0	1	FALSE
2050	P-1020	6	Unlined Cast Iron	1915	1.4	1	FALSE
2051	P-1021	6	Asbestos Cement	1950	0	1	FALSE
2052	P-1022	6	Asbestos Cement	1950	1.7	1	FALSE
2053	P-1023	6	Unlined Cast Iron	1922	0	1	FALSE
2054	P-1024	6	Unlined Cast Iron	1915	0	1	FALSE
2055	P-1025	6	Asbestos Cement	1957	1.7	1	FALSE
2056	P-1026	6	Unlined Cast Iron	1922	0	1	FALSE
2058	P-1028	8	Ductile Iron	1987	0	1	FALSE
2059	P-1029	8	Ductile Iron	1987	0	1	FALSE
2060	P-1030	8	Ductile Iron	1987	0	1	FALSE
2061	P-1031	8	Ductile Iron	1987	0	1	FALSE
2062	P-1032	6	Asbestos Cement	1949	2.1	1	FALSE
2063	P-1033	8	Ductile Iron	1987	0	1	FALSE
2064	P-1034	6	Asbestos Cement	1949	3.5	1	FALSE
2065	P-1035	6	Unlined Cast Iron	1928	0	1	FALSE
2066	P-1036	6	Asbestos Cement	1965	2.1	1	FALSE
2067	P-1037	6	Unlined Cast Iron	1923	1.4	1	FALSE
2068	P-1038	6	Unlined Cast Iron	1923	0.8	1	FALSE
2069	P-1039	6	Asbestos Cement	1953	0	1	FALSE
2071	P-1041	6	Asbestos Cement	1953	0	1	FALSE
2072	P-1044	6	Asbestos Cement	1954	2	1	FALSE
2073	P-1045	6	Asbestos Cement	1954	2	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2074	P-1046	20	Unlined Cast Iron	1924	0	1	FALSE
2076	P-1048	6	Unlined Cast Iron	1915	4.1	1	FALSE
2077	P-1049	6	Unlined Cast Iron	1915	4.1	1	FALSE
2078	P-1050	12	Unlined Cast Iron	1894	1.3	1	FALSE
2079	P-1051	12	Unlined Cast Iron	1894	1.3	1	FALSE
2082	P-1054	6	Unlined Cast Iron	1916	0	1	FALSE
2083	P-1055	6	Unlined Cast Iron	1916	3.7	1	FALSE
2084	P-1056	6	Unlined Cast Iron	1915	4.8	1	FALSE
2085	P-1057	6	Unlined Cast Iron	1916	3.7	1	FALSE
2086	P-1058	6	Unlined Cast Iron	1915	0	1	FALSE
2087	P-1059	12	Unlined Cast Iron	1894	1.3	1	FALSE
2088	P-1060	6	Unlined Cast Iron	1922	0	1	FALSE
2089	P-1061	8	Unlined Cast Iron	1911	6.5	1	FALSE
2090	P-1062	8	Unlined Cast Iron	1911	6.5	1	FALSE
2091	P-1063	6	Unlined Cast Iron	1915	4.8	1	FALSE
2092	P-1064	6	Unlined Cast Iron	1904	1.3	1	FALSE
2093	P-1065	6	Ductile Iron	1996	0	1	FALSE
2095	P-1067	6	Ductile Iron	1996	0	1	FALSE
2096	P-1068	8	Factory Lined Cast Iron	1964	0	1	FALSE
2097	P-1069	8	Factory Lined Cast Iron	1964	0	1	FALSE
2098	P-1070	6	Unlined Cast Iron	1904	1.3	1	FALSE
2099	P-1072	12	Unlined Cast Iron	1894	1.3	1	FALSE
2100	P-1073	6	Unlined Cast Iron	1923	3.6	1	FALSE
2102	P-1075	6	Unlined Cast Iron	1916	0	1	FALSE
2103	P-1077	6	Unlined Cast Iron	1896	1.9	1	FALSE
2104	P-1078	8	Ductile Iron	1986	0	1	FALSE
2105	P-1079	6	Factory Lined Cast Iron	1964	0	1	FALSE
2106	P-1080	6	Unlined Cast Iron	1911	1.3	1	FALSE
2107	P-1081	6	Unlined Cast Iron	1957	4.3	1	FALSE
2108	P-1082	6	Unlined Cast Iron	1911	1.3	1	FALSE
2110	P-1084	6	Unlined Cast Iron	1915	5.1	1	FALSE
2111	P-1085	6	Unlined Cast Iron	1915	5.1	1	FALSE
2112	P-1086	12	Unlined Cast Iron	1894	1.3	1	FALSE
2113	P-1087	6	Unlined Cast Iron	1923	0.8	1	FALSE
2116	P-1092	8	Ductile Iron	1990	0	1	FALSE
2118	P-1094	6	Unlined Cast Iron	1957	0	1	FALSE
2119	P-1096	6	Unlined Cast Iron	1916	2.6	1	FALSE
2120	P-1097	12	Unlined Cast Iron	1909	1.3	1	FALSE
2122	P-1100	6	Unlined Cast Iron	1922	0	1	FALSE
2123	P-1101	6	Asbestos Cement	1949	0	1	FALSE
2124	P-1102	12	Asbestos Cement	1956	1.4	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2126	P-1105	12	Asbestos Cement	1955	1.4	0	FALSE
2127	P-1106	6	Factory Lined Cast Iron	1964	0	0	FALSE
2128	P-1107	6	Unlined Cast Iron	1915	0.6	0	FALSE
2129	P-1108	8	Ductile Iron	1986	0	0	FALSE
2130	P-1109	12	Unlined Cast Iron	1933	0	0	FALSE
2131	P-1110	6	Factory Lined Cast Iron	1965	1.9	0	FALSE
2132	P-1111	6	Unlined Cast Iron	1915	0.6	0	FALSE
2133	P-1112	6	Unlined Cast Iron	1915	0.6	0	FALSE
2134	P-1113	8	Ductile Iron	1990	2.4	0	FALSE
2135	P-1114	8	Ductile Iron	1990	0	1	FALSE
2136	P-1115	8	Factory Lined Cast Iron	1964	0.5	1	FALSE
2137	P-1116	8	Factory Lined Cast Iron	1964	0.5	1	FALSE
2139	P-1118	12	Unlined Cast Iron	1909	1.3	1	FALSE
2140	P-1119	6	Unlined Cast Iron	1897	0	1	FALSE
2142	P-1121	6	Unlined Cast Iron	1915	0	1	FALSE
2143	P-1122	12	Unlined Cast Iron	1909	1.3	1	FALSE
2145	P-1124	8	Ductile Iron	1983	0	0	FALSE
2147	P-1126	8	Unlined Cast Iron	1911	0.5	1	FALSE
2148	P-1127	6	Unlined Cast Iron	1915	4.8	1	FALSE
2149	P-1128	6	Unlined Cast Iron	1915	4.8	1	FALSE
2151	P-1130	6	Unlined Cast Iron	1957	5	1	FALSE
2153	P-1132	8	Unlined Cast Iron	1911	0.5	1	FALSE
2154	P-1133	8	Unlined Cast Iron	1959	0.5	1	FALSE
2157	P-1136	6	Unlined Cast Iron	1897	0	1	FALSE
2160	P-1139	6	Asbestos Cement	1950	6.3	1	FALSE
2162	P-1141	6	Factory Lined Cast Iron	1960	5.8	1	FALSE
2163	P-1142	6	Factory Lined Cast Iron	1960	0	1	FALSE
2166	P-1148	6	Factory Lined Cast Iron	1960	0	1	FALSE
2167	P-1149	6	Asbestos Cement	1947	4.6	1	FALSE
2168	P-1150	6	Unlined Cast Iron	1931	0	1	FALSE
2171	P-1155	6	Ductile Iron	1982	0	1	FALSE
2172	P-1156	12	Unlined Cast Iron	1909	1.3	1	FALSE
2173	P-1157	12	Unlined Cast Iron	1909	1.3	1	FALSE
2176	P-1160	12	Unlined Cast Iron	1909	1.3	1	FALSE
2177	P-1161	12	Unlined Cast Iron	1909	1.3	1	FALSE
2178	P-1162	12	Unlined Cast Iron	1909	1.3	1	FALSE
2179	P-1163	6	Asbestos Cement	1950	4.6	1	FALSE
2180	P-1164	6	Unlined Cast Iron	1950	0	1	FALSE
2181	P-1165	6	Factory Lined Cast Iron	1964	0	1	FALSE
2182	P-1166	6	Factory Lined Cast Iron	1964	0	1	FALSE
2183	P-1167	6	Unlined Cast Iron	1916	9.2	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2184	P-1168	6	Unlined Cast Iron	1916	9.2	1	FALSE
2185	P-1169	6	Unlined Cast Iron	1916	9.2	1	FALSE
2186	P-1170	6	Unlined Cast Iron	1908	8.3	1	FALSE
2188	P-1172	6	Unlined Cast Iron	1922	0.9	1	FALSE
2189	P-1173	8	Ductile Iron	1989	0	1	FALSE
2190	P-1174	6	Asbestos Cement	1950	3	1	FALSE
2191	P-1175	6	Unlined Cast Iron	1916	2.8	1	FALSE
2192	P-1176	6	Factory Lined Cast Iron	1972	1.4	1	FALSE
2193	P-1177	8	Ductile Iron	1993	0	1	FALSE
2195	P-1179	8	Factory Lined Cast Iron	1964	0	1	FALSE
2197	P-1181	6	Factory Lined Cast Iron	1964	1.9	1	FALSE
2199	P-1183	6	Unlined Cast Iron	1922	2.7	1	FALSE
2200	P-1184	6	Unlined Cast Iron	1901	2.4	1	FALSE
2201	P-1185	6	Unlined Cast Iron	1916	1.5	1	FALSE
2203	P-1187	6	Factory Lined Cast Iron	1960	0	1	FALSE
2204	P-1188	6	Factory Lined Cast Iron	1964	0	1	FALSE
2205	P-1189	6	Unlined Cast Iron	1901	2.4	1	FALSE
2207	P-1198	8	Ductile Iron	1980	0	0	FALSE
2208	P-1199	12	Unlined Cast Iron	1909	1.1	0	FALSE
2209	P-1200	8	Unlined Cast Iron	1917	0	0	FALSE
2210	P-1202	8	Unlined Cast Iron	1917	0	0	FALSE
2211	P-1203	8	Ductile Iron	1998	0	0	FALSE
2212	P-1204	8	Ductile Iron	1998	0	0	FALSE
2213	P-1205	8	Ductile Iron	1980	0	0	FALSE
2214	P-1207	6	Unlined Cast Iron	1896	0	0	FALSE
2215	P-1208	6	Unlined Cast Iron	1919	0	0	FALSE
2216	P-1209	6	Unlined Cast Iron	1914	0	0	FALSE
2218	P-1212	8	Asbestos Cement	1956	2.2	0	FALSE
2219	P-1213	6	Unlined Cast Iron	1913	0	0	FALSE
2220	P-1214	6	Asbestos Cement	1956	0	0	FALSE
2221	P-1215	6	Asbestos Cement	1956	0	0	FALSE
2222	P-1216	6	Asbestos Cement	1956	0	0	FALSE
2223	P-1217	6	Unlined Cast Iron	1898	0	0	FALSE
2224	P-1218	6	Unlined Cast Iron	1917	0	0	FALSE
2225	P-1219	6	Unlined Cast Iron	1898	0	0	FALSE
2226	P-1220	6	Asbestos Cement	1956	0	0	FALSE
2228	P-1222	8	Asbestos Cement	1956	2.2	0	FALSE
2229	P-1223	12	Unlined Cast Iron	1909	1.1	0	FALSE
2230	P-1224	6	Asbestos Cement	1956	0	0	FALSE
2231	P-1226	12	Unlined Cast Iron	1909	1.1	0	FALSE
2232	P-1227	12	Unlined Cast Iron	1909	1.1	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2233	P-1228	8	Asbestos Cement	1956	2.2	0	FALSE
2235	P-1230	6	Factory Lined Cast Iron	1966	1.4	0	FALSE
2236	P-1231	6	Factory Lined Cast Iron	1966	1.4	0	FALSE
2237	P-1232	6	Factory Lined Cast Iron	1966	1.4	0	FALSE
2238	P-1233	6	Factory Lined Cast Iron	1966	0	0	FALSE
2239	P-1234	8	Ductile Iron	1985	0	0	FALSE
2240	P-1235	8	Ductile Iron	1985	0	0	FALSE
2241	P-1236	8	Ductile Iron	1985	0	0	FALSE
2242	P-1237	8	Ductile Iron	1985	1.3	0	FALSE
2243	P-1238	8	Unlined Cast Iron	1957	1.1	0	FALSE
2244	P-1239	8	Unlined Cast Iron	1957	1.8	0	FALSE
2245	P-1240	12	Ductile Iron	1985	0	0	FALSE
2246	P-1241	8	Ductile Iron	1985	0	0	FALSE
2247	P-1242	12	Ductile Iron	1985	0	0	FALSE
2248	P-1244	8	Unlined Cast Iron	1957	1.8	0	FALSE
2249	P-1245	6	Unlined Cast Iron	1942	2.5	0	FALSE
2250	P-1246	8	Unlined Cast Iron	1942	0	0	FALSE
2252	P-1248	6	Unlined Cast Iron	1896	0	1	FALSE
2254	P-1251	6	Unlined Cast Iron	1894	0	0	FALSE
2256	P-1253	12	Unlined Cast Iron	1909	0	0	FALSE
2258	P-1256	12	Unlined Cast Iron	1909	0.7	0	FALSE
2259	P-1257	12	Unlined Cast Iron	1913	0.7	0	FALSE
2262	P-1260	12	Unlined Cast Iron	1913	0.7	0	FALSE
2263	P-1261	6	Factory Lined Cast Iron	1964	0	0	FALSE
2264	P-1262	8	Unlined Cast Iron	1957	0.8	0	FALSE
2265	P-1263	6	Factory Lined Cast Iron	1964	0	0	FALSE
2266	P-1264	12	Unlined Cast Iron	1913	0.7	0	FALSE
2267	P-1265	12	Unlined Cast Iron	1913	0.7	0	FALSE
2268	P-1266	8	Unlined Cast Iron	1957	0.8	0	FALSE
2269	P-1267	6	Unlined Cast Iron	1898	0	0	FALSE
2270	P-1268	12	Unlined Cast Iron	1913	0.7	0	FALSE
2271	P-1269	12	Unlined Cast Iron	1913	0.7	0	FALSE
2272	P-1271	12	Unlined Cast Iron	1913	0.7	0	FALSE
2273	P-1272	6	Unlined Cast Iron	1896	0	0	FALSE
2274	P-1273	12	Unlined Cast Iron	1913	0.7	0	FALSE
2276	P-1275	6	Unlined Cast Iron	1921	0	0	FALSE
2278	P-1277	12	Unlined Cast Iron	1913	0.7	1	FALSE
2279	P-1278	6	Unlined Cast Iron	1958	0	0	FALSE
2280	P-1279	8	Ductile Iron	1985	0	0	FALSE
2282	Central St	8	Asbestos Cement	1956	0	0	FALSE
2284	P-1284	8	Asbestos Cement	1956	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2285	P-1285	6	Unlined Cast Iron	1914	2.6	0	FALSE
2286	P-1291	24	Ductile Iron	1996	0	0	FALSE
2287	P-1293	12	Unlined Cast Iron	1910	0	0	FALSE
2288	P-1294	24	Ductile Iron	1995	0.9	1	FALSE
2289	P-1296	24	Ductile Iron	1996	0	0	FALSE
2290	P-1297	24	Ductile Iron	1996	0	0	FALSE
2291	P-1300	8	Unlined Cast Iron	1998	0	0	FALSE
2292	P-1301	12	Unlined Cast Iron	1909	1.3	1	FALSE
2294	P-1304	12	Unlined Cast Iron	1909	1.1	0	FALSE
2295	P-1305	12	Unlined Cast Iron	1909	1.1	0	FALSE
2296	P-1308	8	Factory Lined Cast Iron	1971	0	0	FALSE
2297	P-1309	8	Ductile Iron	1992	0	0	FALSE
2298	P-1310	8	Ductile Iron	1992	0	0	FALSE
2299	P-1311	8	Ductile Iron	1992	0	0	FALSE
2302	P-1315	6	Unlined Cast Iron	1915	0	1	FALSE
2304	P-1321	6	Asbestos Cement	1947	0	0	FALSE
2306	P-1323	8	Unlined Cast Iron	1955	0	0	FALSE
2307	P-1324	8	Asbestos Cement	1955	0	0	FALSE
2308	P-1325	8	Unlined Cast Iron	1950	1.26	0	FALSE
2309	P-1326	8	Unlined Cast Iron	1950	1.26	0	FALSE
2310	P-1327	12	Unlined Cast Iron	1916	0.7	0	FALSE
2311	P-1328	10	Unlined Cast Iron	1916	0	0	FALSE
2312	P-1329	12	Unlined Cast Iron	1917	1.7	0	FALSE
2313	P-1330	12	Unlined Cast Iron	1917	1.7	0	FALSE
2314	P-1331	6	Asbestos Cement	1953	1.7	0	FALSE
2315	P-1332	6	Unlined Cast Iron	1959	0	0	FALSE
2316	P-1333	8	Unlined Cast Iron	1949	0	0	FALSE
2318	P-1335	6	Unlined Cast Iron	1908	0	0	FALSE
2320	P-1337	10	Unlined Cast Iron	1922	0	0	FALSE
2322	P-1339	6	Factory Lined Cast Iron	1971	4.8	0	FALSE
2324	P-1341	8	Ductile Iron	1986	0	1	FALSE
2325	P-1342	6	Unlined Cast Iron	1887	32.8	1	FALSE
2327	P-1344	6	Unlined Cast Iron	1902	0	1	FALSE
2328	P-1345	6	Unlined Cast Iron	1949	0	1	FALSE
2329	P-1346	6	Asbestos Cement	1949	4.3	1	FALSE
2331	P-1348	6	Unlined Cast Iron	1948	0	1	FALSE
2332	P-1349	6	Asbestos Cement	1948	8.5	1	FALSE
2333	P-1350	6	Asbestos Cement	1955	0	0	FALSE
2334	P-1351	6	Unlined Cast Iron	1955	0	0	FALSE
2335	P-1361	12	Ductile Iron	1986	0	0	TRUE
2336	P-1362	12	Ductile Iron	1986	0	0	TRUE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2337	P-1363	6	Unlined Cast Iron	1949	0	0	FALSE
2338	P-1365	8	Unlined Cast Iron	1917	0.2	0	FALSE
2339	P-1366	8	Unlined Cast Iron	1917	0.2	0	FALSE
2340	P-1367	6	Asbestos Cement	1953	0	0	FALSE
2341	P-1368	6	Asbestos Cement	1953	0	0	FALSE
2342	P-1370	8	Unlined Cast Iron	1917	2.1	0	FALSE
2343	P-1372	12	Ductile Iron	1985	1.4	0	TRUE
2344	P-1043	8	Unlined Cast Iron	1917	0.2	0	FALSE
2345	P-1066	6	Unlined Cast Iron	1949	0	0	FALSE
2346	P-1071	6	Unlined Cast Iron	1949	0	0	FALSE
2347	P-1088	6	Asbestos Cement	1953	0	0	FALSE
2348	P-1095	6	Asbestos Cement	1953	0	0	FALSE
2351	P-1145	12	Ductile Iron	1985	1.4	0	FALSE
2352	P-1147	12	Ductile Iron	1985	1.4	0	FALSE
2356	P-1191	8	Factory Lined Cast Iron	1964	0.33	0	FALSE
2362	P-1210	8	Factory Lined Cast Iron	1964	0.33	0	FALSE
2363	P-1290	8	Asbestos Cement	1952	1.6	0	FALSE
2366	P-1299	12	Factory Lined Cast Iron	1970	0.4	0	TRUE
2367	P-1303	12	Factory Lined Cast Iron	1970	0.4	0	FALSE
2368	P-1306	8	Ductile Iron	1996	0	0	TRUE
2369	P-1316	8	Ductile Iron	1996	0	0	TRUE
2370	P-1317	8	Ductile Iron	1996	0	0	TRUE
2371	P-1318	8	Ductile Iron	1996	0	0	TRUE
2372	P-1319	12	Unlined Cast Iron	1913	0.7	0	FALSE
2373	HP-77	6	Factory Lined Cast Iron	1965	0	0	FALSE
2374	HP-63	12	Ductile Iron	1997	0	0	FALSE
2375	HP-61	8	Factory Lined Cast Iron	1964	0	0	FALSE
2376	HP-57	12	Ductile Iron	1986	0	0	FALSE
2377	HP-46	6	Asbestos Cement	1955	0	0	FALSE
2378	HP-43	6	Factory Lined Cast Iron	1971	0	1	FALSE
2379	HP-42	6	Asbestos Cement	1955	0	0	FALSE
2380	HP-40	12	Asbestos Cement	1953	0	0	FALSE
2381	HP-33	6	Asbestos Cement	1953	0	0	FALSE
2382	HP-39	12	Asbestos Cement	1961	0	0	FALSE
2384	P-1316a	8	Ductile Iron	1979	0	1	FALSE
2385	HP-237	12	Ductile Iron	1995	0	0	FALSE
2386	HP-235	8	Factory Lined Cast Iron	1962	3.9	0	FALSE
2387	HP-234	8	Factory Lined Cast Iron	1962	3.9	0	FALSE
2388	HP-70	12	Factory Lined Cast Iron	1963	0	0	FALSE
2389	HP-69	12	Factory Lined Cast Iron	1963	0	0	FALSE
2390	HP-67	12	Factory Lined Cast Iron	1961	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2391	HP-66	12	Factory Lined Cast Iron	1961	0	0	FALSE
2392	HP-65	8	Asbestos Cement	1954	0.7	0	FALSE
2393	HP-56	12	Factory Lined Cast Iron	1961	0	0	FALSE
2394	HP-41	8	Factory Lined Cast Iron	1967	0.8	0	FALSE
2395	HP-38	12	Asbestos Cement	1961	0	0	FALSE
2396	HP-37	12	Factory Lined Cast Iron	1961	0	0	FALSE
2397	HP-36	6	Asbestos Cement	1955	0	0	FALSE
2398	HP-35	8	Asbestos Cement	1954	0	0	FALSE
2399	HP-34	8	Asbestos Cement	1954	0.7	0	FALSE
2400	HP-32	6	Asbestos Cement	1953	0	0	FALSE
2401	HP-31	8	Factory Lined Cast Iron	1966	0	1	FALSE
2402	HP-30	8	Factory Lined Cast Iron	1969	0	0	FALSE
2403	HP-29	8	Ductile Iron	1981	0	1	FALSE
2404	HP-28	8	Factory Lined Cast Iron	1969	0	1	FALSE
2405	HP-26	8	Factory Lined Cast Iron	1963	0.9	0	FALSE
2406	HP-25	8	Factory Lined Cast Iron	1966	0.9	0	FALSE
2407	HP-24	12	Factory Lined Cast Iron	1961	0	1	FALSE
2408	HP-23	12	Factory Lined Cast Iron	1971	0	1	FALSE
2409	HP-22	8	Factory Lined Cast Iron	1972	0	0	FALSE
2410	HP-21	12	Factory Lined Cast Iron	1969	0	0	FALSE
2414	HP-17	12	Ductile Iron	1995	0	0	FALSE
2415	HP-16	12	Ductile Iron	1995	0	0	FALSE
2417	HP-13	12	Factory Lined Cast Iron	1961	0	0	FALSE
2418	HP-12	12	Factory Lined Cast Iron	1965	0	1	FALSE
2419	HP-11	12	Factory Lined Cast Iron	1965	0	1	FALSE
2420	HP-10	12	Factory Lined Cast Iron	1965	0	0	FALSE
2422	HP-8	8	Factory Lined Cast Iron	1963	0.4	0	FALSE
2423	HP-7	8	Factory Lined Cast Iron	1963	0.86	0	FALSE
2424	HP-5	8	Ductile Iron	1977	1.6	1	FALSE
2425	HP-4	8	Ductile Iron	1977	0	0	FALSE
2426	HP-3	8	Ductile Iron	1977	1.6	0	FALSE
2427	HP-2	12	Factory Lined Cast Iron	1965	0	1	FALSE
2428	HP-1	12	Factory Lined Cast Iron	1967	0	1	FALSE
2429	HP-200	16	Ductile Iron	1967	0	0	FALSE
2430	P-199	24	Asbestos Cement	1953	0	0	FALSE
2432	Main Street	8	Unlined Cast Iron	1912	0.6	1	FALSE
2433	HP-53	8	Factory Lined Cast Iron	1964	0	0	FALSE
2434	HP-52	6	Factory Lined Cast Iron	1962	0	1	FALSE
2435	HP-51	8	Factory Lined Cast Iron	1962	0	0	FALSE
2436	HP-50	8	Unlined Cast Iron	1912	0.6	0	FALSE
2437	HP-49	8	Unlined Cast Iron	1912	0.6	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2438	HP-48	8	Ductile Iron	1985	0	0	FALSE
2439	HP-45	12	Asbestos Cement	1953	0	0	FALSE
2440	HP-44	6	Factory Lined Cast Iron	1972	0	0	FALSE
2441	Pioneer Road	8	Factory Lined Cast Iron	1963	0.7	0	TRUE
2442	HP-185	6	Factory Lined Cast Iron	1966	0	1	TRUE
2443	HP-171	8	Asbestos Cement	1951	1.1	0	TRUE
2444	HP-170	8	Asbestos Cement	1952	0	0	TRUE
2445	Winthrop Rd	8	Asbestos Cement	1956	0	0	TRUE
2446	HP-145	8	Factory Lined Cast Iron	1966	0	0	TRUE
2447	HP-194	6	Factory Lined Cast Iron	1968	0	0	TRUE
2448	HP-179	6	Asbestos Cement	1954	0	0	TRUE
2449	HP-197	8	Factory Lined Cast Iron	1968	0	1	TRUE
2450	HP-196	6	Factory Lined Cast Iron	1968	0	1	TRUE
2451	HP-195	6	Factory Lined Cast Iron	1968	0	0	TRUE
2452	HP-187	8	Factory Lined Cast Iron	1963	0	1	TRUE
2453	HP-186	6	Factory Lined Cast Iron	1964	0.6	1	TRUE
2454	HP-164	8	Ductile Iron	1989	0	0	FALSE
2455	HP-163	12	Ductile Iron	1989	0.5	0	FALSE
2456	Cushing Street	12	Ductile Iron	1991	0.5	0	FALSE
2457	HP-155	8	Factory Lined Cast Iron	1966	0	0	FALSE
2458	HP-154	8	Factory Lined Cast Iron	1964	0	0	FALSE
2459	HP-153	8	Factory Lined Cast Iron	1964	0	0	FALSE
2460	HP-152	8	Ductile Iron	1992	0	0	FALSE
2461	HP-150	8	Factory Lined Cast Iron	1969	0	0	FALSE
2462	HP-149	8	Factory Lined Cast Iron	1965	0	0	FALSE
2463	HP-147	8	Factory Lined Cast Iron	1963	0	1	TRUE
2464	HP-146	12	Factory Lined Cast Iron	1967	0.5	0	FALSE
2465	HP-306	8	Ductile Iron	2007	0	0	FALSE
2467	HP-305	8	Ductile Iron	2007	0	1	FALSE
2468	HP-303	8	Ductile Iron	2007	0	0	FALSE
2469	HP-300	8	Ductile Iron	2007	0	0	FALSE
2471	HP-301	8	Ductile Iron	2007	0	0	FALSE
2473	P-4	8	Factory Lined Cast Iron	1963	0	0	FALSE
2474	P-3	8	Factory Lined Cast Iron	1963	0	0	FALSE
2475	HP-60	12	Ductile Iron	1996	0	0	FALSE
2476	HP-64	12	Ductile Iron	1986	0	0	FALSE
2477	HP-62	12	Ductile Iron	1986	0	0	FALSE
2478	HP-59	8	Ductile Iron	1996	0	1	FALSE
2480	Upland Dr	8	Factory Lined Cast Iron	1968	0	1	FALSE
2481	Wanders Dr	8	Factory Lined Cast Iron	1967	0	1	FALSE
2482	HP-139	8	Factory Lined Cast Iron	1965	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2483	HP-138	6	Factory Lined Cast Iron	1969	0	0	FALSE
2484	HP-1358	8	Ductile Iron	1981	0	1	FALSE
2486	HP-204	6	Asbestos Cement	1950	0	0	FALSE
2487	HP-203	6	Unlined Cast Iron	1942	0	0	FALSE
2488	HP-202	6	Unlined Cast Iron	1942	0	0	FALSE
2489	HP-201	8	Factory Lined Cast Iron	1965	0	0	TRUE
2490	HP-193	6	Asbestos Cement	1950	1.2	0	TRUE
2491	HP-192	6	Asbestos Cement	1950	0	0	TRUE
2492	Pioneer Rd	6	Asbestos Cement	1955	1.2	0	TRUE
2493	HP-190	6	Factory Lined Cast Iron	1964	0.6	0	TRUE
2494	HP-189	8	Factory Lined Cast Iron	1965	0	0	TRUE
2495	HP-184	8	Factory Lined Cast Iron	1965	1.8	0	TRUE
2496	HP-183	6	Factory Lined Cast Iron	1966	3.9	0	TRUE
2497	HP-182	8	Factory Lined Cast Iron	1964	0	0	TRUE
2498	HP-181	6	Asbestos Cement	1954	0	0	TRUE
2499	HP-180	6	Asbestos Cement	1954	0	0	TRUE
2500	HP-178	6	Asbestos Cement	1954	0	0	TRUE
2501	HP-177	8	Asbestos Cement	1951	1.1	0	TRUE
2502	HP-176	8	Asbestos Cement	1951	1.1	0	TRUE
2503	HP-175	6	Asbestos Cement	1948	0	0	TRUE
2504	HP-174	6	Asbestos Cement	1954	0	0	TRUE
2505	HP-173	8	Asbestos Cement	1951	0	0	TRUE
2506	Pilgrim Rd	6	Asbestos Cement	1952	0	0	TRUE
2507	HP-169	6	Asbestos Cement	1954	0	0	TRUE
2508	Puritan Rd	6	Asbestos Cement	1952	0	0	TRUE
2509	HP-167	6	Asbestos Cement	1952	0	0	TRUE
2510	HP-166	8	Asbestos Cement	1954	0	0	TRUE
2511	HP-165	8	Asbestos Cement	1954	0	0	TRUE
2512	HP-161	6	Asbestos Cement	1954	0	0	TRUE
2514	HP-159	6	Asbestos Cement	1951	0	0	FALSE
2515	HP-158	8	Asbestos Cement	1956	0	1	TRUE
2516	HP-157	8	Asbestos Cement	1954	0	0	TRUE
2517	HP-137	8	Factory Lined Cast Iron	1965	0	0	FALSE
2518	Prospect St	8	Factory Lined Cast Iron	1963	0	0	FALSE
2519	HP-135	8	Factory Lined Cast Iron	1965	0	0	FALSE
2520	Meadow Rd	8	Factory Lined Cast Iron	1963	0	0	FALSE
2521	HP-133	8	Factory Lined Cast Iron	1963	0	0	FALSE
2522	HP-129_2	8	Unlined Cast Iron	1912	0	0	FALSE
2523	HP-127_1	8	Factory Lined Cast Iron	1971	0	0	FALSE
2524	HP-126	8	Ductile Iron	1996	0	0	FALSE
2525	HP-125	8	Factory Lined Cast Iron	1970	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2528	HP-122	8	Factory Lined Cast Iron	1966	0	0	FALSE
2529	HP-121	8	Factory Lined Cast Iron	1970	0	0	FALSE
2531	HP-119	8	Ductile Iron	1992	0	0	FALSE
2532	HP-118_2	8	Unlined Cast Iron	1912	0	0	FALSE
2533	HP-117_3	8	Factory Lined Cast Iron	1971	0	0	FALSE
2534	HP-116	8	Factory Lined Cast Iron	1966	0	0	FALSE
2537	HP-113	8	Factory Lined Cast Iron	1970	0	0	FALSE
2540	HP-110	8	Factory Lined Cast Iron	1971	0	0	FALSE
2541	HP-88	8	Unlined Cast Iron	1957	0	1	FALSE
2542	HP-107	6	Factory Lined Cast Iron	1962	0	0	FALSE
2543	HP-105	6	Unlined Cast Iron	1957	0	0	FALSE
2544	HP-104	8	Unlined Cast Iron	1912	0.6	0	FALSE
2545	HP-103	12	Asbestos Cement	1956	1.5	0	FALSE
2546	HP-1287	6	Unlined Cast Iron	1942	0	0	FALSE
2547	HP-1360	6	Unlined Cast Iron	1942	0	0	FALSE
2549	HP-1359	6	Unlined Cast Iron	1942	0	0	FALSE
2550	HP-1357	8	Ductile Iron	1981	0	0	FALSE
2551	HP-1356	12	Ductile Iron	1995	0	0	FALSE
2552	HP-1355	12	Ductile Iron	1995	0	0	FALSE
2553	HP-1354	12	Ductile Iron	1995	0	0	FALSE
2554	HP-1352	6	Unlined Cast Iron	1912	0	0	FALSE
2555	P-1319	6	Unlined Cast Iron	1959	0	0	FALSE
2556	P-1318a	6	Asbestos Cement	1956	0	1	FALSE
2557	HP-128	12	Ductile Iron	1995	0	0	FALSE
2558	HP-128_1	6	Unlined Cast Iron	1912	0	0	FALSE
2559	HP-109_1	12	Ductile Iron	1995	0	0	FALSE
2560	P-700	8	Factory Lined Cast Iron	1963	0	0	FALSE
2561	P-246	8	Factory Lined Cast Iron	1963	0	0	FALSE
2562	HP-245	8	Ductile Iron	1981	0	1	FALSE
2563	HP-233	6	Asbestos Cement	1950	0	0	FALSE
2564	HP-232	6	Unlined Cast Iron	1949	0	0	FALSE
2565	HP-231	6	Unlined Cast Iron	1915	0.9	0	FALSE
2566	HP-229	8	Ductile Iron	1990	0	0	FALSE
2567	HP-228	6	Unlined Cast Iron	1949	0	0	FALSE
2568	HP-227	6	Unlined Cast Iron	1948	0	0	FALSE
2569	HP-226	6	Factory Lined Cast Iron	1966	0	0	FALSE
2571	HP-224	6	Asbestos Cement	1950	0	0	FALSE
2572	HP-223	6	Asbestos Cement	1950	0	0	FALSE
2573	HP-222	6	Asbestos Cement	1950	0	0	FALSE
2574	HP-221	6	Asbestos Cement	1950	0	0	FALSE
2575	HP-219	6	Factory Lined Cast Iron	1966	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2576	HP-218	8	Factory Lined Cast Iron	1971	0	1	FALSE
2577	HP-217_1	6	Unlined Cast Iron	1912	0	0	FALSE
2578	HP-215	6	Asbestos Cement	1951	0	0	FALSE
2579	HP-214	6	Unlined Cast Iron	1912	0.9	0	FALSE
2581	HP-211	6	Asbestos Cement	1948	1.4	0	FALSE
2582	HP-102	12	Asbestos Cement	1956	1.5	0	FALSE
2583	HP-101	8	Factory Lined Cast Iron	1963	0	0	FALSE
2584	HP-100	8	Unlined Cast Iron	1957	0	0	FALSE
2585	HP-99	12	Asbestos Cement	1955	1.5	0	FALSE
2586	HP-98	8	Factory Lined Cast Iron	1962	0	0	FALSE
2587	HP-97	8	Asbestos Cement	1955	0	0	FALSE
2588	HP-96	8	Factory Lined Cast Iron	1962	0	0	FALSE
2590	HP-94	8	Asbestos Cement	1955	0	0	FALSE
2591	HP-93	8	Unlined Cast Iron	1912	0.6	0	FALSE
2592	HP-91	6	Asbestos Cement	1955	0	0	FALSE
2593	HP-90	8	Asbestos Cement	1955	0	0	FALSE
2594	HP-89	12	Asbestos Cement	1955	1.5	0	FALSE
2596	Sentinel Rd	8	Ductile Iron	1975	0	0	FALSE
2597	HP-84	8	Unlined Cast Iron	1957	0	0	FALSE
2598	HP-83	8	Ductile Iron	1975	0	0	FALSE
2599	HP-82	8	Ductile Iron	1975	0	0	FALSE
2600	HP-76	8	Asbestos Cement	1954	0	0	FALSE
2601	HP-75	8	Factory Lined Cast Iron	1967	0	0	FALSE
2602	HP-74	12	Factory Lined Cast Iron	1967	0	0	FALSE
2603	HP-106	8	Unlined Cast Iron	1957	0	0	FALSE
2604	Richards Rd	8	Unlined Cast Iron	1957	0	0	FALSE
2605	HP-87	8	Unlined Cast Iron	1957	0	0	FALSE
2607	HP-92	8	Factory Lined Cast Iron	1963	0	0	FALSE
2608	HP-80	8	Factory Lined Cast Iron	1963	0	0	FALSE
2609	HP-79	8	Factory Lined Cast Iron	1963	0	0	FALSE
2610	HP-78	8	Unlined Cast Iron	1912	0.6	0	FALSE
2611	HP-142	8	Factory Lined Cast Iron	1967	0	1	FALSE
2612	HP-141	8	Factory Lined Cast Iron	1965	0	1	FALSE
2613	HP-140	8	Ductile Iron	1982	0	1	FALSE
2614	P-1352	12	Ductile Iron	1995	0	0	FALSE
2615	P-1353	12	Ductile Iron	1995	0	0	FALSE
2617	P-1355	8	Ductile Iron	2007	0	0	FALSE
2620	P-1358	12	Asbestos Cement	1956	0.3	1	FALSE
2621	P-1359	12	Asbestos Cement	1956	0	1	FALSE
2622	P-1364	8	Factory Lined Cast Iron	1966	0	1	FALSE
2623	P-1369	8	Factory Lined Cast Iron	1965	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2624	P-1371	8	Ductile Iron	1985	0	1	FALSE
2625	P-1373	8	Ductile Iron	1985	0	0	FALSE
2628	P-1376	8	Asbestos Cement	1950	0.4	0	FALSE
2629	P-1377	8	Unlined Cast Iron	1927	0	0	FALSE
2630	P-1378	8	Unlined Cast Iron	1927	0	0	TRUE
2631	P-1379	8	Ductile Iron	1973	0	0	FALSE
2632	P-1380	8	Ductile Iron	1975	0	1	TRUE
2633	P-1381	8	Ductile Iron	1980	0	0	FALSE
2635	P-1383	12	Unlined Cast Iron	1917	0.3	1	FALSE
2636	P-1384	12	Unlined Cast Iron	1917	0.3	0	FALSE
2637	P-1385	12	Unlined Cast Iron	1891	0.3	0	FALSE
2638	P-1386	12	Unlined Cast Iron	1891	0.3	0	FALSE
2640	P-1388	6	Unlined Cast Iron	1895	0.2	0	FALSE
2641	P-1389	8	Factory Lined Cast Iron	1965	1.5	0	FALSE
2642	P-1390	8	Factory Lined Cast Iron	1965	0	0	FALSE
2644	P-1391	12	Unlined Cast Iron	1894	1.3	0	FALSE
2646	P-1394	12	Unlined Cast Iron	1894	1.3	1	FALSE
2647	P-1395	12	Unlined Cast Iron	1894	1.3	1	FALSE
2648	P-1396	12	Unlined Cast Iron	1894	1.3	1	FALSE
2649	P-1397	12	Unlined Cast Iron	1894	1.3	1	FALSE
2650	P-1398	24	Ductile Iron	1996	0	0	FALSE
2652	P-1400	8	Asbestos Cement	1955	2.3	0	FALSE
2654	P-1402	6	Asbestos Cement	1948	1.4	0	FALSE
2657	P-1405	12	Unlined Cast Iron	1909	1.3	1	FALSE
2658	P-1406	12	Unlined Cast Iron	1894	1.3	0	FALSE
2663	P-1411	8	Unlined Cast Iron	1957	0	0	FALSE
2664	P-1412	6	Unlined Cast Iron	1907	0	0	FALSE
2665	P-1413	6	Unlined Cast Iron	1907	0	0	FALSE
2666	P-1414	8	Unlined Cast Iron	1916	0.2	0	FALSE
2667	P-1415	8	Unlined Cast Iron	1916	0.2	0	FALSE
2669	P-1419 (Proposed)	6	Factory Lined Cast Iron	1962	0.9	0	TRUE
2670	P-1418 (Proposed)	12	Ductile Iron	2007	0	0	FALSE
2672	P-1418	24	Ductile Iron	1995	0	0	TRUE
2674	P-1420	4	Unlined Cast Iron	1916	0	0	FALSE
2675	P-1419	8	Asbestos Cement	1951	0	0	TRUE
2705	P-1441	12	Unlined Cast Iron	1894	1.3	1	FALSE
2706	P-1442	12	Unlined Cast Iron	1894	1.3	1	FALSE
2707	P-1443	6	Unlined Cast Iron	1924	0	1	FALSE
2710	P-1444	20	Unlined Cast Iron	1924	0	1	FALSE
2714	P-1446	20	Unlined Cast Iron	1924	0	1	FALSE
2719	P-1448	8	Ductile Iron	1985	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2720	P-1449	8	Ductile Iron	1985	0	0	FALSE
2722	P-1450	8	Ductile Iron	2007	0	1	FALSE
2724	P-1451	8	Ductile Iron	2007	0	1	FALSE
2727	P-1452	12	Ductile Iron	1996	0	0	FALSE
2728	P-1453	12	Ductile Iron	1996	0	0	FALSE
2733	P-1455	8	Ductile Iron	2007	0	1	FALSE
2734	P-1456	8	Ductile Iron	2007	0	0	FALSE
2739	P-1458	8	Ductile Iron	2007	0	0	FALSE
2740	P-1459	8	Ductile Iron	2007	0	1	FALSE
2742	P-1460	8	Ductile Iron	2007	0	0	FALSE
2744	P-1461	12	Ductile Iron	2007	0	1	FALSE
2747	P-1463	8	Ductile Iron	2007	0	0	FALSE
2749	P-1464	12	Ductile Iron	2007	0	0	FALSE
2752	P-1465	8	Ductile Iron	1983	0	0	TRUE
2755	P-1466	8	Ductile Iron	1974	0	0	FALSE
2756	P-1467	8	Ductile Iron	1974	0	0	FALSE
2758	P-1468	8	Ductile Iron	1974	0	0	FALSE
2763	P-1469	8	Unlined Cast Iron	1899	0.7	0	FALSE
2764	P-1470	8	Unlined Cast Iron	1899	0.7	0	FALSE
2766	P-1471	8	Ductile Iron	2007	0	0	FALSE
2769	P-1472	12	Factory Lined Cast Iron	1963	0.2	0	FALSE
2772	P-1474	2.3	Factory Lined Cast Iron	1965	1.9	0	FALSE
2774	P-1475	8	Asbestos Cement	1952	4.2	0	TRUE
2775	P-1476	8	Asbestos Cement	1952	4.2	0	TRUE
2777	P-1477	12	Ductile Iron	1985	0	1	TRUE
2778	P-1478	12	Ductile Iron	1985	0	0	FALSE
2784	P-1480	12	Ductile Iron	1985	0	0	FALSE
2785	P-1481	12	Ductile Iron	1985	0	0	FALSE
2787	P-1482	8	Ductile Iron	1985	0	0	FALSE
2790	P-1483	12	Ductile Iron	1986	0	0	TRUE
2791	P-1484	12	Ductile Iron	1997	0	1	FALSE
2795	P-1486	12	Ductile Iron	1997	0	0	FALSE
2796	P-1487	12	Ductile Iron	1997	0	0	FALSE
2798	P-1488	6	Ductile Iron	1997	0	0	FALSE
2800	P-1489	12	Ductile Iron	1997	0	0	FALSE
2802	P-1490	8	Factory Lined Cast Iron	1964	1.6	0	FALSE
2804	P-1492	12	Ductile Iron	2007	0	0	FALSE
2807	P-1493	12	Ductile Iron	2007	0	0	FALSE
2809	P-1494	8	Ductile Iron	2007	0	0	FALSE
2812	P-1495	8	Factory Lined Cast Iron	1964	1.6	0	FALSE
2813	P-1496	8	Factory Lined Cast Iron	1964	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2815	P-1497	6	Ductile Iron	2007	0	0	FALSE
2817	P-1498	12	Factory Lined Cast Iron	1961	0	0	FALSE
2818	P-1499	12	Factory Lined Cast Iron	1961	0	0	FALSE
2820	P-1500	8	Unlined Cast Iron	1912	0.6	0	FALSE
2821	P-1501	8	Unlined Cast Iron	1912	0.6	0	FALSE
2823	P-1502	8	Ductile Iron	2007	0	0	FALSE
2826	P-1504	8	Ductile Iron	1981	0	1	FALSE
2831	P-1506	8	Factory Lined Cast Iron	1962	0	0	FALSE
2833	P-1507	8	Ductile Iron	1999	0	0	FALSE
2840	P-1510	8	Ductile Iron	2007	0	0	FALSE
2842	P-1511	8	Ductile Iron	2007	0	0	FALSE
2844	P-1512	8	Ductile Iron	2007	0	0	FALSE
2846	P-1513	8	Unlined Cast Iron	1949	1.9	0	FALSE
2847	P-1514	6	Unlined Cast Iron	1949	0	0	FALSE
2853	P-1516	12	Ductile Iron	2007	0	0	FALSE
2854	P-1517	12	Ductile Iron	2007	0	0	FALSE
2855	P-1518	12	Ductile Iron	2007	0	0	FALSE
2857	P-1519	12	Factory Lined Cast Iron	1962	0	0	FALSE
2858	P-1520	12	Ductile Iron	1995	0	0	FALSE
2861	P-1522	12	Ductile Iron	2007	0	0	FALSE
2866	P-1523	8	Unlined Cast Iron	1949	1.9	0	FALSE
2871	P-1526	6	Ductile Iron	1999	0	0	FALSE
2873	P-1527	8	Unlined Cast Iron	1950	1.26	0	FALSE
2874	P-1528	8	Unlined Cast Iron	1950	1.26	0	FALSE
2876	P-1529	6	Factory Lined Cast Iron	1962	0	0	FALSE
2878	P-1530	6	Factory Lined Cast Iron	1965	0	0	FALSE
2880	P-1531	6	Unlined Cast Iron	1902	0	0	TRUE
2883	P-1533	6	Unlined Cast Iron	1939	0	0	TRUE
2885	P-1534	6	Asbestos Cement	1957	0	0	FALSE
2886	P-1535	8	Factory Lined Cast Iron	1966	0	0	FALSE
2887	P-1536	6	Factory Lined Cast Iron	1968	4.2	0	TRUE
2900	P-1543	6	Ductile Iron	1991	0	0	FALSE
2903	P-1544	6	Asbestos Cement	1954	0.6	0	FALSE
2905	P-1545	6	Asbestos Cement	1954	0.6	0	FALSE
2907	P-1546	6	Asbestos Cement	1954	0.6	0	FALSE
2908	P-1547	6	Asbestos Cement	1954	0.6	0	FALSE
2910	P-1548	6	Unlined Cast Iron	1957	0	0	FALSE
2912	P-1549	6	Unlined Cast Iron	1957	0	0	FALSE
2914	P-1550	6	Unlined Cast Iron	1957	0	0	FALSE
2916	P-1551	8	Factory Lined Cast Iron	1970	0	0	FALSE
2917	P-1552	8	Factory Lined Cast Iron	1970	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
2919	P-1553	8	Factory Lined Cast Iron	1970	0	0	FALSE
2921	P-1554	8	Factory Lined Cast Iron	1972	0	0	FALSE
2923	P-1555	8	Asbestos Cement	1951	0	0	TRUE
2924	P-1556	8	Asbestos Cement	1951	0	0	TRUE
2926	P-1557	6	Ductile Iron	1998	0	0	TRUE
2928	P-1558	6	Asbestos Cement	1955	0.6	0	FALSE
2929	P-1559	6	Asbestos Cement	1955	0.6	0	FALSE
2932	P-1560	6	Asbestos Cement	1954	0	0	FALSE
2934	P-1561	6	Asbestos Cement	1954	0	0	FALSE
2936	P-1562	6	Asbestos Cement	1954	0	0	FALSE
2937	P-1563	6	Asbestos Cement	1954	0	0	FALSE
2939	P-1564	20	Prestressed Concrete	1954	0	1	FALSE
2940	P-1565	20	Prestressed Concrete	1954	0	0	FALSE
2942	P-1566	8	Asbestos Cement	1955	0	0	FALSE
2950	P-1571	6	Unlined Cast Iron	1941	0.3	0	FALSE
2951	P-1572	6	Asbestos Cement	1960	4.3	0	FALSE
2955	P-1575	6	Factory Lined Cast Iron	1964	0	0	FALSE
2975	P-1585	6	Unlined Cast Iron	1941	0.3	0	FALSE
2976	P-1586	6	Unlined Cast Iron	1941	0.3	0	FALSE
2978	P-1588	6	Unlined Cast Iron	1941	0.3	0	FALSE
2982	P-1591	6	Unlined Cast Iron	1942	0	0	FALSE
2984	P-1592	6	Unlined Cast Iron	1916	6.3	0	FALSE
2985	P-1593	6	Unlined Cast Iron	1916	0	0	FALSE
2986	P-1594	8	Ductile Iron	1999	0	0	FALSE
2988	P-1595	8	Factory Lined Cast Iron	1963	0	0	FALSE
2989	P-1596	8	Factory Lined Cast Iron	1963	0	0	FALSE
2991	P-1597	8	Ductile Iron	1985	0	0	FALSE
2992	P-1598	8	Ductile Iron	1985	0	0	FALSE
2994	P-1599	6	Unlined Cast Iron	1922	0	0	FALSE
2996	P-1600	24	Ductile Iron	1994	0	0	TRUE
2997	P-1601	24	Ductile Iron	1994	0	0	TRUE
2999	P-1602	8	Ductile Iron	1995	0	0	TRUE
3003	P-1604	8	Ductile Iron	1986	2.6	0	FALSE
3007	P-1606	12	Unlined Cast Iron	1917	1.4	0	FALSE
3008	P-1607	12	Unlined Cast Iron	1917	1.4	0	FALSE
3010	P-1608	6	Unlined Cast Iron	1917	0	0	FALSE
3014	P-1610	20	Prestressed Concrete	1963	0	0	FALSE
3015	P-1611	20	Prestressed Concrete	1963	0	0	FALSE
3016	P-1612	6	Unlined Cast Iron	1923	0	0	FALSE
3018	P-1613	12	Factory Lined Cast Iron	1967	0	0	TRUE
3019	P-1614	12	Factory Lined Cast Iron	1967	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3021	P-1615	8	Ductile Iron	1995	0	0	TRUE
3023	P-1616	6	Unlined Cast Iron	1899	0	1	FALSE
3025	P-1617	6	Ductile Iron	1995	0	0	FALSE
3027	P-1618	12	Unlined Cast Iron	1909	1.3	1	FALSE
3028	P-1619	12	Unlined Cast Iron	1909	1.3	1	FALSE
3032	P-1622	6	Unlined Cast Iron	1911	1.3	1	FALSE
3033	P-1623	6	Unlined Cast Iron	1911	1.3	1	FALSE
3036	P-1625	6	Unlined Cast Iron	1937	0	1	FALSE
3037	P-1626	6	Unlined Cast Iron	1937	0	1	FALSE
3040	P-1628	12	Unlined Cast Iron	1894	1.3	1	FALSE
3043	P-1630	6	Unlined Cast Iron	1915	4.8	1	FALSE
3047	P-1633	6	Unlined Cast Iron	1911	1.3	1	FALSE
3048	P-1634	6	Unlined Cast Iron	1911	1.3	1	FALSE
3053	P-1636	12	Unlined Cast Iron	1919	0	1	FALSE
3055	P-1637	12	Unlined Cast Iron	1919	0	1	FALSE
3057	P-1638	12	Unlined Cast Iron	1894	1.3	0	FALSE
3058	P-1639	12	Unlined Cast Iron	1894	1.3	0	FALSE
3062	P-1641	8	Ductile Iron	1998	0	0	FALSE
3065	P-1643	8	Ductile Iron	1998	0	0	FALSE
3067	P-1644	8	Ductile Iron	1998	0	0	FALSE
3070	P-1646	8	Ductile Iron	1998	0	0	FALSE
3072	P-1647	8	Ductile Iron	1998	0	0	FALSE
3076	P-1650	8	Ductile Iron	1998	0	1	FALSE
3077	P-1651	8	Ductile Iron	1998	0	1	FALSE
3078	P-1652	8	Ductile Iron	1998	0	1	FALSE
3080	P-1653	8	Ductile Iron	1998	0	0	FALSE
3081	P-1654	8	Ductile Iron	1998	0	1	FALSE
3082	P-1655	8	Ductile Iron	1998	0	0	FALSE
3084	P-1656	6	Unlined Cast Iron	1908	8.4	1	FALSE
3085	P-1657	6	Unlined Cast Iron	1908	8.4	1	FALSE
3087	P-1658	6	Unlined Cast Iron	1908	0	1	FALSE
3089	P-1659	12	Unlined Cast Iron	1894	1.3	1	FALSE
3090	P-1660	12	Unlined Cast Iron	1894	0.6	1	FALSE
3092	P-1661	6	Unlined Cast Iron	1915	4.8	1	FALSE
3093	P-1662	6	Unlined Cast Iron	1915	4.8	1	FALSE
3096	P-1664	2.3	Unlined Cast Iron	1922	23.7	1	FALSE
3098	P-1665	6	Unlined Cast Iron	1930	0	1	FALSE
3099	P-1666	6	Unlined Cast Iron	1916	9.2	1	FALSE
3101	P-1667	6	Unlined Cast Iron	1954	0	0	FALSE
3103	P-1668	6	Asbestos Cement	1949	6.3	1	FALSE
3104	P-1669	6	Asbestos Cement	1949	6.3	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3109	P-1672	6	Unlined Cast Iron	1915	0	1	FALSE
3111	P-1673	8	Unlined Cast Iron	1907	0	0	FALSE
3112	P-1674	8	Unlined Cast Iron	1957	0.8	0	FALSE
3114	P-1675	6	Unlined Cast Iron	1898	0	0	FALSE
3115	P-1676	6	Unlined Cast Iron	1956	0	0	FALSE
3117	P-1677	6	Asbestos Cement	1952	5.2	0	FALSE
3118	P-1678	8	Ductile Iron	2005	0	0	FALSE
3120	P-1679	6	Asbestos Cement	1957	2	0	FALSE
3122	P-1680	6	Unlined Cast Iron	1903	5	1	FALSE
3123	P-1681	6	Factory Lined Cast Iron	1961	0	1	FALSE
3126	P-1683	6	Unlined Cast Iron	1911	1.6	0	FALSE
3128	P-1684	6	Unlined Cast Iron	1958	0	0	FALSE
3130	P-1685	6	Ductile Iron	1988	0	0	FALSE
3135	P-1688	4	Ductile Iron	1988	0	1	FALSE
3137	P-1689	8	Unlined Cast Iron	1957	0.8	0	FALSE
3138	P-1690	8	Unlined Cast Iron	1957	0.8	0	FALSE
3140	P-1691	6	Unlined Cast Iron	1911	0	0	FALSE
3142	P-1692	6	Unlined Cast Iron	1929	0	0	FALSE
3144	P-1693	8	Ductile Iron	1998	0	0	FALSE
3145	P-1694	2	Galvanized Steel	1919	0	1	FALSE
3146	P-1695	12	Unlined Cast Iron	1919	0	1	FALSE
3151	P-1697	12	Ductile Iron	2009	0	0	FALSE
3153	P-1698	12	Ductile Iron	2009	0	0	FALSE
3155	P-1699	12	Ductile Iron	2009	0	0	FALSE
3157	P-1700	12	Ductile Iron	2009	0	0	FALSE
3161	P-1702	12	Ductile Iron	1989	0	0	TRUE
3163	P-1703	12	Ductile Iron	2009	0	0	FALSE
3164	P-1704	12	Ductile Iron	2009	0	0	FALSE
3169	P-1707	12	Ductile Iron	2009	0	0	FALSE
3171	P-1708	12	Ductile Iron	2009	0	0	FALSE
3210	P-1730	6	Asbestos Cement	1949	0	0	FALSE
3211	P-1731	6	Asbestos Cement	1949	0	0	FALSE
3213	P-1732	8	Factory Lined Cast Iron	1965	0	0	FALSE
3214	P-1733	8	Unlined Cast Iron	1917	0	0	FALSE
3223	P-1739	12	Unlined Cast Iron	1894	1.3	1	FALSE
3224	P-1740	12	Unlined Cast Iron	1891	0	0	FALSE
3225	P-1741	8	Factory Lined Cast Iron	1964	0	0	FALSE
3226	P-1742	8	Unlined Cast Iron	1917	0	0	FALSE
3229	P-1744	16	Unlined Cast Iron	1917	0	0	FALSE
3230	P-1745	8	Factory Lined Cast Iron	1964	0	0	FALSE
3236	P-1749	8	Unlined Cast Iron	1917	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3237	P-1750	8	Unlined Cast Iron	1917	0.2	0	FALSE
3238	P-1751	8	Unlined Cast Iron	1917	0	0	FALSE
3241	P-1753	8	Unlined Cast Iron	1901	0.4	1	FALSE
3244	P-1755	12	Unlined Cast Iron	1894	1.3	1	FALSE
3245	P-1756	8	Unlined Cast Iron	1901	0	1	FALSE
3247	P-1757	6	Ductile Iron	1999	0	0	FALSE
3249	P-1758	8	Ductile Iron	1999	0	0	FALSE
3250	P-1759	8	Ductile Iron	1999	0	0	FALSE
3252	P-1760	6	Ductile Iron	1999	0	0	FALSE
3254	P-1761	8	Factory Lined Cast Iron	1971	0.8	0	TRUE
3255	P-1762	8	Factory Lined Cast Iron	1971	0.8	0	TRUE
3260	P-1765	8	Ductile Iron	1998	0	0	TRUE
3262	P-1766	8	Ductile Iron	1998	0	0	TRUE
3264	P-1767	8	Ductile Iron	1998	0	0	TRUE
3265	P-1768	8	Ductile Iron	1998	0	0	TRUE
3267	P-1769	8	Ductile Iron	1998	0	0	TRUE
3275	P-1774	12	Factory Lined Cast Iron	1963	0.2	0	FALSE
3278	P-1776	6	Ductile Iron	2007	0	0	FALSE
3280	P-1777	8	Unlined Cast Iron	1917	2.1	0	FALSE
3281	P-1778	8	Unlined Cast Iron	1917	2.1	0	FALSE
3283	P-1779	8	Ductile Iron	1998	0	0	FALSE
3286	P-1781	8	Asbestos Cement	1955	2.3	0	FALSE
3288	P-1782	8	Ductile Iron	1998	0	0	FALSE
3290	P-1783	8	Asbestos Cement	1955	0	0	FALSE
3291	P-1784	8	Asbestos Cement	1955	2.3	0	FALSE
3293	P-1785	8	Ductile Iron	1998	0	0	FALSE
3297	P-1787	8	Ductile Iron	1980	0	0	FALSE
3299	P-1788	6	Ductile Iron	1980	0	0	FALSE
3301	P-1789	8	Asbestos Cement	1957	3.3	0	FALSE
3302	P-1790	8	Asbestos Cement	1957	3.3	0	FALSE
3304	P-1791	8	Ductile Iron	1999	0	0	FALSE
3306	P-1792	16	Unlined Cast Iron	1917	0.4	0	FALSE
3307	P-1793	16	Unlined Cast Iron	1917	0.4	1	FALSE
3309	P-1794	8	Ductile Iron	2007	0	0	FALSE
3314	P-1795	6	Unlined Cast Iron	1923	0	0	FALSE
3317	P-1797	6	Asbestos Cement	1948	1.4	0	FALSE
3318	P-1798	6	Asbestos Cement	1948	1.4	0	FALSE
3319	P-1799	8	Ductile Iron	2007	0	0	FALSE
3322	P-1800	6	Unlined Cast Iron	1896	0	0	FALSE
3324	P-1801	6	Asbestos Cement	1954	0	0	FALSE
3326	P-1802	2.3	Unlined Cast Iron	1953	5.9	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3329	P-1803	1.5	Galvanized Steel	1928	13.2	0	FALSE
3338	P-1808	12	Unlined Cast Iron	1913	0.7	0	FALSE
3339	P-1809	12	Unlined Cast Iron	1913	0.7	0	FALSE
3343	P-1811	6	Asbestos Cement	1955	2.8	0	FALSE
3344	P-1812	2.3	Unlined Cast Iron	1955	0	0	FALSE
3347	P-1814	6	Asbestos Cement	1955	2.8	0	FALSE
3350	P-1816	12	Unlined Cast Iron	1913	0	0	FALSE
3351	P-1817	2.3	Unlined Cast Iron	1955	0	0	FALSE
3353	P-1818	6	Asbestos Cement	1955	2.8	0	FALSE
3354	P-1819	6	Asbestos Cement	1955	2.8	0	FALSE
3356	P-1820	12	Unlined Cast Iron	1913	0.7	0	FALSE
3357	P-1821	12	Unlined Cast Iron	1913	0.7	0	FALSE
3358	P-1822	2.3	Unlined Cast Iron	1955	3.6	0	FALSE
3361	P-1823	6	Unlined Cast Iron	1957	2	0	FALSE
3362	P-1824	6	Unlined Cast Iron	1957	2	0	FALSE
3369	P-1828	2	Unlined Cast Iron	1884	0	0	FALSE
3370	P-1829	2	Unlined Cast Iron	1884	0	0	FALSE
3373	P-1830	2	Galvanized Steel	1894	4.4	0	FALSE
3374	P-1831	8	Ductile Iron	1992	0	0	FALSE
3376	P-1832	8	Asbestos Cement	1957	0.6	1	FALSE
3377	P-1833	8	Asbestos Cement	1957	0.6	1	FALSE
3380	P-1835	6	Unlined Cast Iron	1912	0	0	FALSE
3382	P-1836	12	Unlined Cast Iron	1909	0	1	FALSE
3383	P-1837	12	Unlined Cast Iron	1909	0	1	FALSE
3385	P-1838	6	Unlined Cast Iron	1926	0	0	FALSE
3387	P-1839	6	Unlined Cast Iron	1912	0	0	FALSE
3392	P-1840	2	PVC	1979	0	0	FALSE
3394	P-1841	12	Asbestos Cement	1953	0	0	FALSE
3395	P-1842	12	Asbestos Cement	1953	0	0	FALSE
3397	P-1843	2.3	Factory Lined Cast Iron	1967	0	0	FALSE
3399	P-1844	2.3	Factory Lined Cast Iron	1966	0	0	FALSE
3401	P-1845	2.3	Factory Lined Cast Iron	1969	1.99	0	FALSE
3403	P-1846	2.3	Factory Lined Cast Iron	1968	3.3	0	FALSE
3405	P-1847	8	Asbestos Cement	1954	0.9	0	TRUE
3406	P-1848	8	Asbestos Cement	1954	0	0	TRUE
3408	P-1849	2	Unlined Cast Iron	1955	0	0	TRUE
3410	P-1850	2.3	Unlined Cast Iron	1948	0	0	FALSE
3412	P-1851	6	Unlined Cast Iron	1942	0	0	FALSE
3413	P-1852	6	Unlined Cast Iron	1942	0	0	FALSE
3414	P-1853	2.3	Unlined Cast Iron	1948	0	0	FALSE
3416	P-1854	2.3	Unlined Cast Iron	1959	2.9	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3418	P-1855	2	Unlined Cast Iron	1948	0	0	FALSE
3420	P-1856	8	Factory Lined Cast Iron	1980	0	0	FALSE
3423	P-1858	4	Factory Lined Cast Iron	1980	0	0	FALSE
3425	P-1859	8	Factory Lined Cast Iron	1980	0	0	FALSE
3426	P-1860	8	Factory Lined Cast Iron	1980	0	0	FALSE
3428	P-1861	4	Factory Lined Cast Iron	1980	0	0	FALSE
3431	P-1862	2.3	Unlined Cast Iron	1959	0	0	FALSE
3433	P-1863	2.3	Unlined Cast Iron	1956	0	0	FALSE
3435	P-1864	6	Asbestos Cement	1950	0	0	FALSE
3436	P-1865	6	Asbestos Cement	1950	0	0	FALSE
3438	P-1866	2.3	Unlined Cast Iron	1950	0	0	FALSE
3441	P-1867	2.3	Factory Lined Cast Iron	1963	0	0	FALSE
3443	P-1868	2	Unlined Cast Iron	1952	0	0	TRUE
3445	P-1869	8	Factory Lined Cast Iron	1968	0	1	FALSE
3446	P-1870	8	Factory Lined Cast Iron	1968	0	1	FALSE
3448	P-1871	2.3	Factory Lined Cast Iron	1970	2.5	0	FALSE
3450	P-1872	2.3	Unlined Cast Iron	1948	3.5	0	FALSE
3452	P-1873	6	Unlined Cast Iron	1939	0	0	TRUE
3453	P-1874	6	Unlined Cast Iron	1939	0	0	FALSE
3455	P-1875	2.3	Unlined Cast Iron	1941	0	0	FALSE
3457	P-1876	2	Galvanized Steel	1975	4.8	0	FALSE
3459	P-1877	2	Galvanized Steel	1975	4.8	0	FALSE
3461	P-1878	8	Factory Lined Cast Iron	1969	0	1	TRUE
3462	P-1879	8	Factory Lined Cast Iron	1969	0	1	TRUE
3464	P-1880	2.3	Factory Lined Cast Iron	1969	0	0	TRUE
3466	P-1881	8	Asbestos Cement	1956	0	1	TRUE
3467	P-1882	8	Asbestos Cement	1956	0	1	FALSE
3469	P-1883	2.3	Factory Lined Cast Iron	1978	0	0	FALSE
3471	P-1884	2	Galvanized Steel	1925	1.5	0	TRUE
3474	P-1886	20	Prestressed Concrete	1952	0	1	FALSE
3476	P-1887	2.3	Galvanized Steel	1955	0	0	FALSE
3478	P-1888	2.3	Unlined Cast Iron	1947	3.6	0	FALSE
3480	P-1889	2.3	Unlined Cast Iron	1947	0	0	FALSE
3482	P-1890	2.3	Unlined Cast Iron	1938	0	0	FALSE
3484	P-1891	12	Factory Lined Cast Iron	1963	0.2	0	FALSE
3486	P-1893	2.3	Unlined Cast Iron	1938	0	0	FALSE
3488	P-1894	2.3	Unlined Cast Iron	1946	0	0	FALSE
3490	P-1895	6	Asbestos Cement	1947	0	0	FALSE
3491	P-1896	6	Asbestos Cement	1947	0	0	FALSE
3493	P-1897	2.3	Unlined Cast Iron	1947	0	0	FALSE
3495	P-1898	12	Factory Lined Cast Iron	1963	0.2	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3498	P-1900	8	Ductile Iron	2010	0	0	FALSE
3501	P-1901	2	Factory Lined Cast Iron	1965	0	0	FALSE
3503	P-1902	6	Unlined Cast Iron	1928	0	0	FALSE
3504	P-1903	6	Unlined Cast Iron	1928	0	0	FALSE
3506	P-1904	2	Unlined Cast Iron	1927	0	0	FALSE
3508	P-1905	8	Asbestos Cement	1956	0	0	FALSE
3509	P-1906	8	Asbestos Cement	1956	0	0	FALSE
3511	P-1907	2.3	Unlined Cast Iron	1948	3	0	FALSE
3514	P-1909	6	Unlined Cast Iron	1922	0	0	FALSE
3516	P-1910	8	Unlined Cast Iron	1922	0	0	FALSE
3517	P-1911	4	Unlined Cast Iron	1922	0	0	FALSE
3518	P-1912	4	Unlined Cast Iron	1909	2.1	0	FALSE
3520	P-1913	12	Factory Lined Cast Iron	1965	0	0	FALSE
3521	P-1914	12	Factory Lined Cast Iron	1965	0	0	FALSE
3523	P-1915	2	Galvanized Steel	1929	1.8	0	FALSE
3525	P-1916	2.3	Unlined Cast Iron	1959	0	0	FALSE
3527	P-1917	20	Unlined Cast Iron	1910	0.6	0	TRUE
3530	P-1919	4	Unlined Cast Iron	1920	0	0	TRUE
3532	P-1920	6	Unlined Cast Iron	1927	0	0	TRUE
3534	P-1921	12	Factory Lined Cast Iron	1963	0	0	TRUE
3535	P-1922	12	Factory Lined Cast Iron	1963	0	0	TRUE
3537	P-1923	2	Galvanized Steel	1914	0	0	TRUE
3539	P-1924	20	Unlined Cast Iron	1910	0.6	0	TRUE
3540	P-1925	20	Unlined Cast Iron	1910	0.6	0	TRUE
3542	P-1926	20	Unlined Cast Iron	1910	0.6	0	FALSE
3543	P-1927	20	Unlined Cast Iron	1910	0.6	0	FALSE
3546	P-1929	20	Unlined Cast Iron	1910	0.6	0	TRUE
3547	P-1930	20	Unlined Cast Iron	1910	0.6	0	TRUE
3549	P-1931	2	Galvanized Steel	1928	0	0	TRUE
3554	P-1933	2.3	Unlined Cast Iron	1941	2	0	TRUE
3556	P-1934	2.3	Unlined Cast Iron	1937	2.6	0	FALSE
3560	P-1937	8	Asbestos Cement	1956	0.4	0	FALSE
3633	P-1977	8	Ductile Iron	1986	0	0	TRUE
3640	P-1981	6	Unlined Cast Iron	1952	3.8	0	TRUE
3643	P-1983	6	Unlined Cast Iron	1952	3.8	0	TRUE
3644	P-1984	6	Unlined Cast Iron	1952	3.8	0	TRUE
3645	P-1985	2.3	Unlined Cast Iron	1952	7.2	0	TRUE
3647	P-1986	8	Unlined Cast Iron	1917	2.1	0	FALSE
3648	P-1987	8	Unlined Cast Iron	1917	2.1	0	FALSE
3650	P-1988	2.3	Unlined Cast Iron	1909	2.8	0	FALSE
3652	P-1989	2.3	Unlined Cast Iron	1938	2.8	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3654	P-1990	2.3	Unlined Cast Iron	1948	29.2	0	FALSE
3656	P-1991	2.3	Unlined Cast Iron	1955	2.2	0	FALSE
3657	P-1992	4	Unlined Cast Iron	1900	0	0	FALSE
3659	P-1993	4	Unlined Cast Iron	1907	0	0	FALSE
3660	P-1994	4	Unlined Cast Iron	1907	0	0	FALSE
3661	P-1995	4	Unlined Cast Iron	1908	0	0	FALSE
3663	P-1996	4	Factory Lined Cast Iron	1965	2.1	0	FALSE
3665	P-1997	8	Asbestos Cement	1956	0	0	FALSE
3668	P-1999	2.3	Unlined Cast Iron	1940	25.5	0	FALSE
3670	P-2000	8	Asbestos Cement	1956	0	0	FALSE
3671	P-2001	8	Unlined Cast Iron	1933	5	0	FALSE
3673	P-2002	2.3	Unlined Cast Iron	1949	0	0	FALSE
3675	P-2003	2.3	Unlined Cast Iron	1934	5.1	0	FALSE
3677	P-2004	8	Asbestos Cement	1956	0	0	FALSE
3680	P-2006	2	Galvanized Steel	1925	1.8	0	FALSE
3682	P-2007	2	Galvanized Steel	1927	0	0	FALSE
3684	P-2008	2.3	Unlined Cast Iron	1956	0	0	FALSE
3687	P-2010	12	Factory Lined Cast Iron	1962	0.2	0	FALSE
3689	P-2011	2	Galvanized Steel	1904	6	0	FALSE
3691	P-2012	8	Ductile Iron	2010	0	0	FALSE
3693	P-2013	12	Factory Lined Cast Iron	1963	0.2	0	FALSE
3694	P-2014	12	Factory Lined Cast Iron	1963	0.2	0	FALSE
3695	P-2015	4	Unlined Cast Iron	1892	1.3	0	FALSE
3697	P-2016	2.3	Unlined Cast Iron	1941	1.9	0	FALSE
3699	P-2017	6	Factory Lined Cast Iron	1961	1.7	0	FALSE
3700	P-2018	6	Factory Lined Cast Iron	1961	1.7	0	FALSE
3702	P-2019	8	Ductile Iron	1990	0	0	FALSE
3703	P-2020	8	Ductile Iron	1990	0	0	FALSE
3704	P-2021	4	Unlined Cast Iron	1907	0	0	FALSE
3705	P-2022	2	Galvanized Steel	1927	3.7	0	FALSE
3707	P-2023	2	Galvanized Steel	1928	3.7	0	FALSE
3709	P-2024	6	Unlined Cast Iron	1932	0	0	FALSE
3710	P-2025	6	Unlined Cast Iron	1932	0	0	FALSE
3712	P-2026	2.3	Unlined Cast Iron	1939	21.5	0	FALSE
3714	P-2027	2.3	Unlined Cast Iron	1937	0	0	FALSE
3716	P-2028	20	Unlined Cast Iron	1910	0	0	FALSE
3717	P-2029	20	Unlined Cast Iron	1910	0	0	FALSE
3719	P-2030	4	Unlined Cast Iron	1896	1.9	0	FALSE
3721	P-2031	2.3	Unlined Cast Iron	1939	2.8	0	FALSE
3723	P-2032	6	Unlined Cast Iron	1939	0	0	FALSE
3724	P-2033	6	Unlined Cast Iron	1939	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3726	P-2034	2.3	Unlined Cast Iron	1947	0	0	FALSE
3728	P-2035	2.3	Factory Lined Cast Iron	1969	2.3	0	FALSE
3730	P-2036	2.3	Factory Lined Cast Iron	1969	2.3	0	FALSE
3732	P-2037	6	Unlined Cast Iron	1941	0.3	0	FALSE
3733	P-2038	6	Unlined Cast Iron	1941	0.3	0	FALSE
3735	P-2039	2.3	Factory Lined Cast Iron	1962	10.1	0	FALSE
3737	P-2040	4	Factory Lined Cast Iron	1965	3	0	FALSE
3739	P-2041	6	Unlined Cast Iron	1958	2.7	0	FALSE
3740	P-2042	6	Unlined Cast Iron	1958	0	0	FALSE
3742	P-2043	2	PVC	1979	0	0	FALSE
3744	P-2044	12	Unlined Cast Iron	1917	1.4	0	FALSE
3745	P-2045	12	Unlined Cast Iron	1917	1.4	0	FALSE
3747	P-2046	2.3	Unlined Cast Iron	1953	2.4	0	FALSE
3749	P-2047	20	Unlined Cast Iron	1910	1.1	0	FALSE
3750	P-2048	20	Unlined Cast Iron	1910	1.1	0	FALSE
3752	P-2049	2.3	Unlined Cast Iron	1951	2.3	0	FALSE
3754	P-2050	12	Unlined Cast Iron	1917	1.4	0	FALSE
3755	P-2051	12	Unlined Cast Iron	1917	1.4	0	FALSE
3758	P-2053	3	Unlined Cast Iron	1924	0	0	FALSE
3760	P-2054	2.3	Unlined Cast Iron	1947	17.1	0	FALSE
3762	P-2055	2.3	Unlined Cast Iron	1949	0	0	TRUE
3764	P-2056	8	Unlined Cast Iron	1941	0	0	FALSE
3767	P-2058	6	Asbestos Cement	1956	0	0	FALSE
3769	P-2059	2.3	Unlined Cast Iron	1956	3.4	0	FALSE
3771	P-2060	8	Unlined Cast Iron	1941	0	0	FALSE
3772	P-2061	8	Unlined Cast Iron	1941	0	0	FALSE
3774	P-2062	2.3	Unlined Cast Iron	1920	36.5	0	FALSE
3776	P-2063	8	Asbestos Cement	1952	0	0	FALSE
3777	P-2064	8	Asbestos Cement	1952	1.6	0	FALSE
3779	P-2065	4	Unlined Cast Iron	1924	0	0	FALSE
3781	P-2066	2	Galvanized Steel	1936	5.3	0	FALSE
3783	P-2067	2.3	Unlined Cast Iron	1937	5.1	0	FALSE
3785	P-2068	2.3	Unlined Cast Iron	1940	6.7	0	FALSE
3789	P-2070	6	Unlined Cast Iron	1929	0	0	FALSE
3790	P-2071	6	Unlined Cast Iron	1929	0	0	FALSE
3791	P-2072	2.3	Factory Lined Cast Iron	1968	31.4	0	FALSE
3793	P-2073	8	Unlined Cast Iron	1947	0.3	0	FALSE
3794	P-2074	8	Unlined Cast Iron	1947	0	0	FALSE
3795	P-2075	4	Unlined Cast Iron	1925	6.84	0	FALSE
3797	P-2076	2.3	Unlined Cast Iron	1937	28.2	0	FALSE
3799	P-2077	6	Asbestos Cement	1953	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3800	P-2078	6	Asbestos Cement	1953	0	0	FALSE
3802	P-2079	2.3	Unlined Cast Iron	1953	0	0	FALSE
3804	P-2080	8	Factory Lined Cast Iron	1960	0	0	FALSE
3805	P-2081	8	Factory Lined Cast Iron	1960	0	0	FALSE
3808	P-2083	2	Galvanized Steel	1927	0	0	FALSE
3809	P-2084	2.3	Unlined Cast Iron	1952	5	0	FALSE
3811	P-2085	6	Asbestos Cement	1952	0	0	FALSE
3812	P-2086	6	Asbestos Cement	1952	0	0	FALSE
3814	P-2087	2.3	Factory Lined Cast Iron	1968	4	0	FALSE
3816	P-2088	2.3	Unlined Cast Iron	1940	0	0	FALSE
3818	P-2089	4	Unlined Cast Iron	1905	0	0	FALSE
3820	P-2090	8	Unlined Cast Iron	1898	0	0	FALSE
3821	P-2091	8	Unlined Cast Iron	1898	0	0	FALSE
3823	P-2092	4	Unlined Cast Iron	1923	0	0	FALSE
3827	P-2094	6	Unlined Cast Iron	1898	0	0	FALSE
3828	P-2095	2.3	Galvanized Steel	1908	0	0	FALSE
3830	P-2096	10	Unlined Cast Iron	1911	0.4	0	FALSE
3831	P-2097	10	Unlined Cast Iron	1911	0.4	0	FALSE
3833	P-2098	2.3	Factory Lined Cast Iron	1966	2.5	0	FALSE
3835	P-2099	10	Unlined Cast Iron	1917	0.4	0	FALSE
3836	P-2100	10	Unlined Cast Iron	1917	0.4	0	FALSE
3840	P-2102	2.3	Factory Lined Cast Iron	1964	3	0	FALSE
3841	P-2103	2	Unlined Cast Iron	1923	0	0	FALSE
3843	P-2104	6	Factory Lined Cast Iron	1968	0	0	FALSE
3844	P-2105	6	Factory Lined Cast Iron	1968	0	0	FALSE
3846	P-2106	2.3	Unlined Cast Iron	1949	2.3	0	FALSE
3848	P-2107	6	Unlined Cast Iron	1908	0.2	0	FALSE
3849	P-2108	6	Unlined Cast Iron	1908	0.2	0	FALSE
3857	P-2112	6	Unlined Cast Iron	1949	0	0	FALSE
3859	P-2113	4	Unlined Cast Iron	1922	17.6	0	FALSE
3862	P-2115	8	Factory Lined Cast Iron	1965	0	0	FALSE
3864	P-2116	2	Galvanized Steel	1910	1.9	0	FALSE
3866	P-2117	6	Unlined Cast Iron	1929	2	0	FALSE
3867	P-2118	6	Unlined Cast Iron	1929	2	0	FALSE
3869	P-2119	6	Unlined Cast Iron	1929	2	0	FALSE
3870	P-2120	4	Unlined Cast Iron	1929	3.1	0	FALSE
3872	P-2121	2.3	Unlined Cast Iron	1947	11.3	0	FALSE
3874	P-2122	6	Asbestos Cement	1955	3.6	0	FALSE
3875	P-2123	6	Asbestos Cement	1955	3.6	0	FALSE
3877	P-2124	3	PVC	1999	0	0	FALSE
3879	P-2125	2	Unlined Cast Iron	1925	6	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3881	P-2126	4	Unlined Cast Iron	1915	1.9	0	FALSE
3882	P-2127	4	Unlined Cast Iron	1907	0	0	FALSE
3883	P-2128	4	Unlined Cast Iron	1907	0	0	FALSE
3884	P-2129	4	Unlined Cast Iron	1907	0	0	FALSE
3885	P-2130	4	Unlined Cast Iron	1907	4.1	0	FALSE
3887	P-2131	6	Unlined Cast Iron	1908	0.9	0	FALSE
3888	P-2132	6	Unlined Cast Iron	1908	0.9	0	FALSE
3889	P-2133	4	Unlined Cast Iron	1908	0	0	FALSE
3891	P-2134	6	Unlined Cast Iron	1906	1.1	0	FALSE
3892	P-2135	6	Unlined Cast Iron	1906	1.1	0	FALSE
3894	P-2136	6	Unlined Cast Iron	1906	0	0	FALSE
3895	P-2137	6	Unlined Cast Iron	1906	0	0	FALSE
3896	P-2138	4	Unlined Cast Iron	1906	0	0	FALSE
3898	P-2139	4	Unlined Cast Iron	1892	0	0	FALSE
3901	P-2141	4	Unlined Cast Iron	1892	0	0	FALSE
3902	P-2142	4	Unlined Cast Iron	1892	0	0	FALSE
3904	P-2143	6	Unlined Cast Iron	1892	0	0	FALSE
3905	P-2144	6	Unlined Cast Iron	1892	0	0	FALSE
3906	P-2145	4	Unlined Cast Iron	1882	0	0	FALSE
3908	P-2146	4	Unlined Cast Iron	1908	0	0	FALSE
3910	P-2147	6	Asbestos Cement	1954	7.1	0	FALSE
3913	P-2149	2.3	Factory Lined Cast Iron	1967	5.6	0	FALSE
3915	P-2150	8	Factory Lined Cast Iron	1971	0	0	FALSE
3918	P-2152	2.3	Factory Lined Cast Iron	1967	1.7	0	FALSE
3920	P-2153	6	Unlined Cast Iron	1921	0	0	FALSE
3921	P-2154	6	Unlined Cast Iron	1921	0	0	FALSE
3922	P-2155	4	Factory Lined Cast Iron	1960	0	0	FALSE
3924	P-2156	12	Unlined Cast Iron	1894	1.3	0	FALSE
3927	P-2158	2	Galvanized Steel	1914	2.8	0	FALSE
3929	P-2159	12	Unlined Cast Iron	1894	1.3	0	FALSE
3930	P-2160	12	Unlined Cast Iron	1894	1.3	0	FALSE
3932	P-2161	4	Factory Lined Cast Iron	1960	1	0	FALSE
3934	P-2162	20	Unlined Cast Iron	1924	0	0	FALSE
3935	P-2163	20	Unlined Cast Iron	1924	0	0	FALSE
3937	P-2164	2.3	Unlined Cast Iron	1953	0	0	FALSE
3939	P-2165	6	Ductile Iron	1993	0	0	FALSE
3940	P-2166	6	Ductile Iron	1993	0	0	FALSE
3942	P-2167	2.3	Factory Lined Cast Iron	1966	13.6	0	FALSE
3944	P-2168	6	Unlined Cast Iron	1958	1	0	FALSE
3945	P-2169	6	Unlined Cast Iron	1958	1	0	FALSE
3947	P-2170	4	Unlined Cast Iron	1922	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
3949	P-2171	10	Unlined Cast Iron	1923	1.2	0	FALSE
3950	P-2172	10	Unlined Cast Iron	1923	1.2	0	FALSE
3952	P-2173	2.3	Unlined Cast Iron	1954	0	0	FALSE
3955	P-2175	12	Ductile Iron	2010	0	1	FALSE
3957	P-2176	4	Factory Lined Cast Iron	1960	0	0	FALSE
3960	P-2178	12	Ductile Iron	2009	0	1	FALSE
3962	P-2179	8	Ductile Iron	2000	0	0	FALSE
3965	P-2181	12	Ductile Iron	2011	0	1	FALSE
3967	P-2182	4	Unlined Cast Iron	1889	0	0	FALSE
3970	P-2184	12	Ductile Iron	2011	0	1	FALSE
3971	P-2185	4	Unlined Cast Iron	1889	0	0	FALSE
3973	P-2186	6	Factory Lined Cast Iron	1966	2.1	1	FALSE
3976	P-2188	2	PVC	2005	0	0	FALSE
3978	P-2189	6	Factory Lined Cast Iron	1966	2.1	1	FALSE
3979	P-2190	6	Factory Lined Cast Iron	1966	0	1	FALSE
3981	P-2191	6	Unlined Cast Iron	1882	2.5	1	FALSE
3982	P-2192	6	Unlined Cast Iron	1882	2.5	1	FALSE
3983	P-2193	4	Unlined Cast Iron	1891	0.8	0	FALSE
3985	P-2194	2	Unlined Cast Iron	1910	36.6	0	FALSE
3987	P-2195	2	Galvanized Steel	1919	0	0	FALSE
3989	P-2196	2	Unlined Cast Iron	1954	0	0	FALSE
3991	P-2197	2.3	Unlined Cast Iron	1949	6.6	0	FALSE
3993	P-2198	6	Unlined Cast Iron	1916	1.2	0	FALSE
3996	P-2200	8	Unlined Cast Iron	1901	0.4	0	FALSE
3997	P-2201	8	Unlined Cast Iron	1901	0.4	0	FALSE
3998	P-2202	2.3	Factory Lined Cast Iron	1962	3.5	0	FALSE
4000	P-2203	8	Unlined Cast Iron	1901	0.4	0	FALSE
4001	P-2204	8	Unlined Cast Iron	1901	0.4	0	FALSE
4003	P-2205	2.3	Factory Lined Cast Iron	1969	0	0	FALSE
4008	P-2208	6	Unlined Cast Iron	1915	0.5	1	FALSE
4010	P-2209	4	Unlined Cast Iron	1915	0	1	FALSE
4012	P-2210	6	Unlined Cast Iron	1915	0.5	1	FALSE
4013	P-2211	6	Unlined Cast Iron	1915	0.5	1	FALSE
4014	P-2212	4	Unlined Cast Iron	1915	0	0	FALSE
4016	P-2213	6	Unlined Cast Iron	1928	0	1	FALSE
4017	P-2214	6	Unlined Cast Iron	1928	2.9	1	FALSE
4019	P-2215	2.3	Factory Lined Cast Iron	1965	2.8	0	FALSE
4021	P-2216	12	Unlined Cast Iron	1894	1.3	1	FALSE
4022	P-2217	12	Unlined Cast Iron	1894	1.3	1	FALSE
4023	P-2218	2	Factory Lined Cast Iron	1965	2.8	0	FALSE
4025	P-2219	8	Ductile Iron	1988	0	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4026	P-2220	8	Ductile Iron	1988	0	1	FALSE
4028	P-2221	6	Asbestos Cement	1950	0	1	FALSE
4029	P-2222	6	Asbestos Cement	1950	0	1	FALSE
4030	P-2223	2	Galvanized Steel	1933	12.7	0	FALSE
4034	P-2225	6	Unlined Cast Iron	1895	0.5	1	FALSE
4036	P-2227	4	Unlined Cast Iron	1935	0	0	FALSE
4039	P-2229	6	Unlined Cast Iron	1915	4.8	1	FALSE
4041	P-2230	12	Unlined Cast Iron	1894	1.3	1	FALSE
4042	P-2231	12	Unlined Cast Iron	1894	1.3	1	FALSE
4043	P-2232	2	Unlined Cast Iron	1928	4.3	0	FALSE
4045	P-2233	6	Unlined Cast Iron	1915	4.8	1	FALSE
4046	P-2234	6	Unlined Cast Iron	1915	4.8	1	FALSE
4048	P-2235	2	Unlined Cast Iron	1923	6.3	0	FALSE
4050	P-2236	6	Unlined Cast Iron	1923	3.6	1	FALSE
4051	P-2237	6	Unlined Cast Iron	1923	3.6	1	FALSE
4053	P-2238	2.3	Factory Lined Cast Iron	1967	4.5	0	FALSE
4055	P-2239	6	Unlined Cast Iron	1915	4.8	1	FALSE
4058	P-2241	2	Unlined Cast Iron	1935	10.4	0	FALSE
4060	P-2242	6	Unlined Cast Iron	1915	4.8	1	FALSE
4061	P-2243	6	Unlined Cast Iron	1915	4.8	1	FALSE
4062	P-2244	2.3	Unlined Cast Iron	1946	25.8	0	FALSE
4064	P-2245	6	Asbestos Cement	1954	0	1	FALSE
4065	P-2246	6	Asbestos Cement	1954	0	1	FALSE
4067	P-2247	2.3	Unlined Cast Iron	1957	17.9	0	FALSE
4069	P-2248	6	Unlined Cast Iron	1895	0.5	1	FALSE
4073	P-2251	2.3	Unlined Cast Iron	1954	2.4	1	FALSE
4074	P-2252	2.3	Unlined Cast Iron	1954	2.4	1	FALSE
4076	P-2253	6	Unlined Cast Iron	1911	1.3	1	FALSE
4077	P-2254	6	Unlined Cast Iron	1911	1.3	1	FALSE
4078	P-2255	4	Unlined Cast Iron	1915	0	0	FALSE
4080	P-2256	6	Unlined Cast Iron	1895	0	1	FALSE
4081	P-2257	6	Unlined Cast Iron	1895	0	1	FALSE
4082	P-2258	2	Unlined Cast Iron	1928	17.7	0	FALSE
4084	P-2259	6	Unlined Cast Iron	1930	3.9	1	FALSE
4087	P-2261	12	Unlined Cast Iron	1933	6.6	1	FALSE
4088	P-2262	12	Unlined Cast Iron	1933	6.6	1	FALSE
4090	P-2263	8	Factory Lined Cast Iron	1964	0.5	1	FALSE
4094	P-2266	6	Unlined Cast Iron	1937	0	1	FALSE
4095	P-2267	6	Unlined Cast Iron	1896	0.7	1	FALSE
4098	P-2269	12	Unlined Cast Iron	1909	1.3	1	FALSE
4099	P-2270	12	Unlined Cast Iron	1909	1.3	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4100	P-2271	4	Unlined Cast Iron	1925	0	0	FALSE
4107	P-2275	4	Unlined Cast Iron	1925	1	0	FALSE
4108	P-2276	4	Unlined Cast Iron	1925	1	0	FALSE
4110	P-2277	6	Unlined Cast Iron	1894	0	0	FALSE
4111	P-2278	6	Unlined Cast Iron	1894	0	0	FALSE
4112	P-2279	4	Unlined Cast Iron	1925	1	0	FALSE
4113	P-2280	4	Unlined Cast Iron	1912	13.5	0	FALSE
4115	P-2281	2.3	Unlined Cast Iron	1957	4.9	0	FALSE
4116	P-2282	8	Ductile Iron	1990	2.4	0	FALSE
4119	P-2283	4	Unlined Cast Iron	1893	3.7	0	FALSE
4120	P-2284	4	Unlined Cast Iron	1893	3.7	0	FALSE
4121	P-2285	4	Unlined Cast Iron	1893	3.7	0	FALSE
4122	P-2286	4	Unlined Cast Iron	1893	5.8	0	FALSE
4123	P-2287	6	Factory Lined Cast Iron	1960	0	1	FALSE
4125	P-2288	12	Unlined Cast Iron	1909	1.3	1	FALSE
4126	P-2289	12	Unlined Cast Iron	1909	1.3	1	FALSE
4127	P-2290	2	Galvanized Steel	1928	3.3	0	FALSE
4129	P-2291	4	Unlined Cast Iron	1910	0	0	FALSE
4131	P-2292	2.3	Unlined Cast Iron	1927	0	0	FALSE
4133	P-2293	6	Unlined Cast Iron	1898	0.7	1	FALSE
4134	P-2294	6	Unlined Cast Iron	1898	0.7	1	FALSE
4135	P-2295	2	Galvanized Steel	1927	0	0	FALSE
4136	P-2296	4	Unlined Cast Iron	1915	0	0	FALSE
4138	P-2297	12	Unlined Cast Iron	1909	1.3	1	FALSE
4140	P-2299	2.3	Unlined Cast Iron	1952	13.8	0	FALSE
4142	P-2300	2	Galvanized Steel	1928	8.4	0	FALSE
4144	P-2301	2.3	Unlined Cast Iron	1946	0	0	FALSE
4146	P-2302	6	Unlined Cast Iron	1898	0.7	1	FALSE
4147	P-2303	6	Unlined Cast Iron	1898	0.7	1	FALSE
4148	P-2304	2	Galvanized Steel	1940	0	0	FALSE
4150	P-2305	6	Asbestos Cement	1950	4.6	1	FALSE
4151	P-2306	6	Unlined Cast Iron	1931	0	1	FALSE
4152	P-2307	2.3	Unlined Cast Iron	1950	9.6	0	FALSE
4154	P-2308	12	Unlined Cast Iron	1909	1.3	1	FALSE
4155	P-2309	12	Unlined Cast Iron	1909	1.3	1	FALSE
4156	P-2310	4	Unlined Cast Iron	1915	4.2	0	FALSE
4157	P-2311	4	Unlined Cast Iron	1909	3.5	0	FALSE
4159	P-2312	6	Unlined Cast Iron	1898	0.7	1	FALSE
4160	P-2313	6	Unlined Cast Iron	1898	0.7	1	FALSE
4161	P-2314	2	Galvanized Steel	1927	4.5	0	FALSE
4162	P-2315	4	Unlined Cast Iron	1916	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4164	P-2316	6	Factory Lined Cast Iron	1964	0	1	FALSE
4166	P-2318	2	Galvanized Steel	1950	11.8	0	FALSE
4168	P-2319	12	Unlined Cast Iron	1909	1.3	1	FALSE
4169	P-2320	12	Unlined Cast Iron	1909	1.3	1	FALSE
4170	P-2321	4	Unlined Cast Iron	1909	0	0	FALSE
4172	P-2322	2	Unlined Cast Iron	1924	0	0	FALSE
4174	P-2323	2.3	Unlined Cast Iron	1924	0	0	FALSE
4176	P-2324	6	Factory Lined Cast Iron	1964	0	1	FALSE
4177	P-2325	6	Factory Lined Cast Iron	1964	0	1	FALSE
4178	P-2326	1.5	Unlined Cast Iron	1924	14.8	0	FALSE
4180	P-2327	2.3	Factory Lined Cast Iron	1964	25	0	FALSE
4182	P-2328	12	Unlined Cast Iron	1909	1.3	1	FALSE
4185	P-2330	6	Factory Lined Cast Iron	1965	0	1	FALSE
4187	P-2332	4	Unlined Cast Iron	1915	4	0	FALSE
4188	P-2333	4	Factory Lined Cast Iron	1978	1.3	0	FALSE
4190	P-2334	6	Unlined Cast Iron	1922	0.9	1	FALSE
4191	P-2335	6	Unlined Cast Iron	1922	0.9	1	FALSE
4192	P-2336	4	Unlined Cast Iron	1915	4.3	0	FALSE
4194	P-2337	12	Unlined Cast Iron	1909	1.3	1	FALSE
4196	P-2339	4	Unlined Cast Iron	1922	1.4	0	FALSE
4198	P-2340	4	Unlined Cast Iron	1915	0	0	FALSE
4201	P-2341	6	Unlined Cast Iron	1922	0.9	1	FALSE
4202	P-2342	6	Unlined Cast Iron	1922	0.9	1	FALSE
4203	P-2343	2.3	Unlined Cast Iron	1947	0	0	FALSE
4205	P-2344	12	Unlined Cast Iron	1909	1.3	1	FALSE
4206	P-2345	12	Unlined Cast Iron	1909	1.3	1	FALSE
4207	P-2346	2	Galvanized Steel	1924	6.8	0	FALSE
4209	P-2347	6	Factory Lined Cast Iron	1965	0	1	FALSE
4210	P-2348	6	Factory Lined Cast Iron	1965	0	1	FALSE
4213	P-2350	2	Galvanized Steel	1912	0	0	FALSE
4215	P-2351	2	Galvanized Steel	1910	0	0	FALSE
4218	P-2352	2	Galvanized Steel	1905	9.9	0	FALSE
4220	P-2353	2	Galvanized Steel	1913	3.4	0	FALSE
4222	P-2354	8	Ductile Iron	1985	0	1	FALSE
4223	P-2355	8	Factory Lined Cast Iron	1985	0	1	FALSE
4226	P-2357	4	Unlined Cast Iron	1900	0	0	FALSE
4228	P-2358	2	Unlined Cast Iron	1900	8.4	0	FALSE
4230	P-2359	6	Unlined Cast Iron	1900	0	0	FALSE
4231	P-2360	6	Unlined Cast Iron	1900	0	0	FALSE
4233	P-2361	2.3	Unlined Cast Iron	1905	0	0	FALSE
4235	P-2362	12	Unlined Cast Iron	1909	1.3	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4236	P-2363	12	Unlined Cast Iron	1909	1.3	1	FALSE
4237	P-2364	2	Galvanized Steel	1905	9.7	0	FALSE
4238	P-2365	4	Unlined Cast Iron	1892	4.8	0	FALSE
4240	P-2366	2.3	Factory Lined Cast Iron	1972	7.7	0	FALSE
4242	P-2367	4	Unlined Cast Iron	1892	0	0	FALSE
4244	P-2368	2	Unlined Cast Iron	1927	14.1	0	FALSE
4246	P-2369	2	Galvanized Steel	1935	3.1	0	FALSE
4248	P-2370	2	Galvanized Steel	1935	3.1	0	FALSE
4252	P-2372	2	Galvanized Steel	1935	3.1	0	FALSE
4253	P-2373	2.3	Factory Lined Cast Iron	1969	2.7	0	FALSE
4255	P-2374	2.3	Factory Lined Cast Iron	1971	25.6	0	FALSE
4257	P-2375	2.3	Unlined Cast Iron	1950	2.5	0	FALSE
4259	P-2376	2	Galvanized Steel	1926	0	0	FALSE
4261	P-2377	2.3	Unlined Cast Iron	1940	2.6	0	TRUE
4262	P-2378	2	Galvanized Steel	1932	3.7	0	TRUE
4264	P-2379	6	Unlined Cast Iron	1934	0.43	0	FALSE
4265	P-2380	6	Unlined Cast Iron	1934	0	0	FALSE
4267	P-2381	2.3	Unlined Cast Iron	1937	16.6	0	FALSE
4270	P-2382	6	Unlined Cast Iron	1897	0	1	FALSE
4271	P-2383	6	Unlined Cast Iron	1897	1.9	1	FALSE
4273	P-2384	2	Factory Lined Cast Iron	1968	15.3	0	FALSE
4275	P-2385	6	Unlined Cast Iron	1934	1.2	0	FALSE
4276	P-2386	6	Unlined Cast Iron	1934	1.2	0	FALSE
4278	P-2387	1	PVC	1979	12.6	0	FALSE
4281	P-2388	2	Unlined Cast Iron	1949	26.1	0	FALSE
4283	P-2389	6	Unlined Cast Iron	1915	0.6	0	FALSE
4284	P-2390	6	Unlined Cast Iron	1915	0.6	0	FALSE
4286	P-2391	2	Galvanized Steel	1935	9.2	0	FALSE
4288	P-2392	2	Galvanized Steel	1924	3.3	0	TRUE
4290	P-2393	2.3	Factory Lined Cast Iron	1966	3	0	FALSE
4292	P-2394	1	Galvanized Steel	1920	13.8	0	FALSE
4294	P-2395	6	Asbestos Cement	1949	4.8	0	FALSE
4296	P-2396	6	Asbestos Cement	1954	7.1	0	FALSE
4297	P-2397	6	Asbestos Cement	1954	0	0	FALSE
4299	P-2398	2	PVC	1998	0	0	FALSE
4301	P-2399	2	Galvanized Steel	1923	1.9	0	FALSE
4303	P-2400	6	Unlined Cast Iron	1957	0	0	FALSE
4304	P-2401	6	Unlined Cast Iron	1957	0	0	FALSE
4306	P-2402	1	Galvanized Steel	1924	8	0	FALSE
4308	P-2403	2.3	Unlined Cast Iron	1955	13.1	0	FALSE
4310	P-2404	6	Unlined Cast Iron	1915	4.8	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4313	P-2406	1	Galvanized Steel	1921	19	0	FALSE
4315	P-2407	6	Unlined Cast Iron	1915	4.8	1	FALSE
4316	P-2408	6	Unlined Cast Iron	1915	4.8	1	FALSE
4318	P-2409	2.3	Unlined Cast Iron	1954	10.4	0	FALSE
4320	P-2410	2.3	Unlined Cast Iron	1953	9	0	FALSE
4322	P-2411	6	Factory Lined Cast Iron	1960	1.3	0	FALSE
4323	P-2412	6	Factory Lined Cast Iron	1960	1.3	0	FALSE
4325	P-2413	1	Galvanized Steel	1948	37.2	0	FALSE
4327	P-2414	6	Unlined Cast Iron	1916	1.2	0	FALSE
4328	P-2415	6	Unlined Cast Iron	1916	1.2	0	FALSE
4330	P-2416	8	Ductile Iron	1980	0	0	FALSE
4331	P-2417	8	Ductile Iron	1980	0	0	FALSE
4333	P-2418	12	Factory Lined Cast Iron	1962	0.2	0	FALSE
4334	P-2419	12	Factory Lined Cast Iron	1962	0.2	0	FALSE
4336	P-2420	4	Unlined Cast Iron	1899	3	0	FALSE
4338	P-2421	6	Unlined Cast Iron	1913	0	0	FALSE
4339	P-2422	6	Unlined Cast Iron	1913	0	0	FALSE
4341	P-2423	6	Unlined Cast Iron	1904	2.5	1	FALSE
4342	P-2424	6	Unlined Cast Iron	1904	1.3	1	FALSE
4344	P-2425	6	Unlined Cast Iron	1917	2.3	0	FALSE
4345	P-2426	6	Unlined Cast Iron	1917	0	0	FALSE
4347	P-2427	8	Factory Lined Cast Iron	1971	0	0	FALSE
4348	P-2428	8	Factory Lined Cast Iron	1971	0	0	FALSE
4350	P-2429	6	Ductile Iron	1981	0	0	FALSE
4351	P-2430	6	Ductile Iron	1981	0	0	FALSE
4353	P-2431	6	Unlined Cast Iron	1957	2	0	FALSE
4354	P-2432	6	Unlined Cast Iron	1957	2	0	FALSE
4356	P-2433	2	Galvanized Steel	1924	9.7	0	FALSE
4358	P-2434	8	Asbestos Cement	1956	0	0	FALSE
4359	P-2435	8	Asbestos Cement	1956	0	0	FALSE
4361	P-2436	1.3	Galvanized Steel	1921	14.8	0	FALSE
4363	P-2437	6	Factory Lined Cast Iron	1964	1.2	0	FALSE
4364	P-2438	6	Factory Lined Cast Iron	1964	0	0	FALSE
4366	P-2439	6	Unlined Cast Iron	1922	2.9	0	FALSE
4370	P-2442	6	Unlined Cast Iron	1922	2.9	0	FALSE
4372	P-2443	12	Unlined Cast Iron	1894	1.3	0	FALSE
4373	P-2444	12	Unlined Cast Iron	1894	1.3	0	FALSE
4374	P-2445	8	Ductile Iron	2008	0	0	FALSE
4376	P-2446	6	Ductile Iron	2008	0	0	FALSE
4380	P-2448	6	Ductile Iron	2008	0	0	FALSE
4381	P-2449	6	Ductile Iron	2008	0	0	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4383	P-2450	6	Ductile Iron	2008	0	0	FALSE
4385	P-2451	8	Ductile Iron	1983	0	0	FALSE
4388	P-2453	4	Ductile Iron	1983	0	0	FALSE
4390	P-2454	8	Ductile Iron	1983	0	0	FALSE
4393	P-2456	4	Factory Lined Cast Iron	1983	0	0	FALSE
4395	P-2457	8	Ductile Iron	1983	0	0	FALSE
4398	P-2459	4	Factory Lined Cast Iron	1983	0	0	FALSE
4400	P-2460	8	Ductile Iron	1983	0	0	FALSE
4401	P-2461	8	Ductile Iron	1983	0	0	FALSE
4403	P-2462	4	Factory Lined Cast Iron	1983	0	0	FALSE
4405	P-2463	8	Ductile Iron	1996	0	0	FALSE
4406	P-2464	8	Ductile Iron	1996	0	0	FALSE
4408	P-2465	4	Ductile Iron	1996	0	0	FALSE
4410	P-2466	4	Ductile Iron	1996	0	0	FALSE
4412	P-2467	6	Unlined Cast Iron	1927	0	0	TRUE
4413	P-2468	6	Unlined Cast Iron	1927	0	0	TRUE
4415	P-2469	1.5	Galvanized Steel	1927	0	0	TRUE
4417	P-2470	6	Unlined Cast Iron	1908	0.2	0	FALSE
4418	P-2471	6	Unlined Cast Iron	1908	0.2	0	FALSE
4420	P-2472	6	Ductile Iron	1998	0	0	FALSE
4422	P-2473	6	Ductile Iron	1998	0	0	FALSE
4424	P-2474	6	Ductile Iron	1998	0	0	FALSE
4426	P-2475	20	Prestressed Concrete	1952	0	1	FALSE
4427	P-2476	20	Prestressed Concrete	1952	0	1	FALSE
4429	P-2477	8	Asbestos Cement	1950	0.4	0	FALSE
4430	P-2478	8	Asbestos Cement	1950	0.4	0	FALSE
4437	P-2479	8	Factory Lined Cast Iron	1970	0	0	FALSE
4439	P-2480	8	Ductile Iron	2008	0	0	FALSE
4443	P-2483	8	Ductile Iron	1998	0	1	FALSE
4446	P-2485	12	Unlined Cast Iron	1917	0.3	0	FALSE
4447	P-2486	12	Unlined Cast Iron	1917	0.3	0	FALSE
4449	P-2487	12	Unlined Cast Iron	1894	1.3	1	FALSE
4450	P-2488	12	Unlined Cast Iron	1894	1.3	1	FALSE
4452	P-2489	20	Unlined Cast Iron	1924	0	1	FALSE
4453	P-2490	20	Unlined Cast Iron	1924	0	1	FALSE
4454	P-2491	12	Unlined Cast Iron	1924	0	0	FALSE
4456	P-2492	10	Unlined Cast Iron	1922	7	0	FALSE
4457	P-2493	10	Unlined Cast Iron	1922	0	0	FALSE
4459	P-2494	6	Unlined Cast Iron	1921	0	0	FALSE
4461	P-2495	8	Unlined Cast Iron	1901	0.4	1	FALSE
4462	P-2496	8	Unlined Cast Iron	1901	0.4	1	FALSE

Asset Management Pipe Input Data
Capital Efficiency Study
Aquarion Water Company - Hingham/Hull Water System

ID	Label	Diameter (in)	Material	Installation Year	Breaks per 1000'	Corrosive Soils	Water Quality
4464	P-2497	8	Factory Lined Cast Iron	1965	0.33	0	FALSE
4465	P-2498	6	Unlined Cast Iron	1935	3.8	0	FALSE
4467	P-2499	8	Unlined Cast Iron	1955	1.3	1	FALSE
4468	P-2500	8	Unlined Cast Iron	1955	1.3	1	FALSE
4470	P-2501	8	Asbestos Cement	1960	3.7	0	FALSE
4471	P-2502	8	Asbestos Cement	1960	0	0	FALSE
4480	P-2505	6	Unlined Cast Iron	1922	0	0	FALSE
4481	P-2506	6	Unlined Cast Iron	1922	0	0	FALSE
4485	P-2508	2	PVC	1979	48.5	0	FALSE
4490	P-2509	6	Factory Lined Cast Iron	1972	2.5	1	FALSE
4491	P-2510	6	Factory Lined Cast Iron	1972	2.5	1	FALSE
4495	P-2511	12	Ductile Iron	2007	0	1	FALSE
4496	P-2512	8	Ductile Iron	2007	0	1	FALSE
4500	P-2514	12	Ductile Iron	0	0	0	FALSE
4501	P-2515	12	Ductile Iron	0	0	0	FALSE
4503	P-2516	12	Ductile Iron	0	0	0	FALSE
4505	P-2517	8	PVC	0	0	0	FALSE
4509	P-2518	1.5	Galvanized Steel	1926	5.1	0	FALSE
4513	P-2520	1.5	Galvanized Steel	1926	5.1	0	FALSE
4514	P-2521	1.5	Galvanized Steel	1926	5.1	0	FALSE
4531	P-2529	12	Unlined Cast Iron	1909	1.1	0	FALSE
4536	P-2532	12	Unlined Cast Iron	1909	0	1	FALSE
4537	P-2533	12	Unlined Cast Iron	1909	0	1	FALSE
0	P-2534	6	Unlined Cast Iron	1912	2.5	1	FALSE
0	P-2535	12	Ductile Iron	2011	0	1	FALSE



Legend

- Service Area Boundary
- Pipe
- Junction

Link Map
Hingham/Hull, Massachusetts
Aquarion Water Company

TATA & HOWARD
Water and Wastewater Consultants

MARCH 2011

Approximate Scale: 1" = 1,500'



**Hydraulically Deficient Areas
Hingham/Hull, Massachusetts
Aquarion Water Company**



TATA & HOWARD
Water and Wastewater Consultants

MARCH 2011

Approximate Scale: 1" = 1,500'



Legend	
	School
	Healthcare Facility
	Other Critical Customer
	Critical Areas
	Service Area Boundary
Water Main Diameter	
	4-Inch or Smaller
	6-Inch
	8-Inch
	10-Inch
	12-Inch
	14-Inch
	16-Inch
	18-Inch
	20-Inch
	24-Inch

Turkey Hill Standpipe
Capacity: 2.0 mg
Overflow Elevation: 240 feet

Downing Street Well

Free Street Well No. 4

Free Street Well No. 2

Free Street Well No. 3

Free Street Well No. 5

Fulling Mill Well

Hingham Water Treatment Facility
Capacity: 7.7 mgd

Prospect Street Well

Scotland Street Well

Accord Tank
Capacity: 0.75 mg
Overflow Elevation: 282 feet

Critical Component Areas
Hingham/Hull, Massachusetts
Aquarion Water Company

TATA & HOWARD
Water and Wastewater Consultants

MARCH 2011
Approximate Scale: 1" = 1,500'




Asset Management Summary
Hingham/Hull, Massachusetts
Aquarion Water Company



MARCH 2011

Approximate Scale: 1" = 1,500'



Legend

- School
- Healthcare Facility
- Other Critical Customer
- Hydraulic Improvements
- Critical Areas
- Service Area Boundary
- Asset Management Rating
 - Good - Excellent
 - Fair - Good
 - Poor - Fair

Hull Booster Pump Station

Atlantic Ocean

Hingham Harbor

HULL

Turkey Hill Standpipe
Capacity: 2.0 mg
Overflow Elevation: 240 feet

Downing Street Well

Free Street Well No. 2

HINGHAM

COHASSET

Free Street Well No. 4

Free Street Well No. 3

Free Street Well No. 5

WEYMOUTH

Fulling Mill Well

Hingham Water Treatment Facility
Capacity: 7.7 mgd

Prospect Street Well

SCITUATE

Scotland Street Well

NORWELL


Accord Tank
Capacity: 0.75 mg
Overflow Elevation: 282 feet

Three Circles Integration Map
Hingham/Hull, Massachusetts
Aquarion Water Company



MARCH 2011

Approximate Scale: 1" = 1,500'



**Phase I and II Improvements
Hingham/Hull, Massachusetts
Aquarion Water Company**



TATA & HOWARD
Water and Wastewater Consultants

MARCH 2011

Approximate Scale: 1" = 1,500'



Phase III Improvements
Hingham/Hull, Massachusetts
Aquarion Water Company



TATA & HOWARD
Water and Wastewater Consultants

MARCH 2011

Approximate Scale: 1" = 1,500'